


Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

General Details

Involving 1 2016 HONDA CIVIC 1.5 (SMH7178D)

Date of Loss 4 May 2019

Time of Loss 9:50

Loss Description SMH7178D (INSD) > SLQ8306J (TP) > SLB5662D

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount \$37,406.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion *

Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Vehicle & Driver Details

Vehicle Registration# SMH7178D

Purchase Date

Registration State SINGAPORE

Registration Date *

Mileage

Age of Vehicle 2

CATEGORY POLICY INFORMATION ASSESSMENT INFORMATION

Manufacturing Year 2016

CATEGORY FNOL INFORMATION POST SURVEY INFORMATION

Make HONDA

Driver Name TOH MENG LOONG SHAWN

Model CIVIC 1.5

Date of Birth 8 May 1988

Age 31

| CATEGORY | POLICY INFORMATION | ASSESSMENT INFORMATION | CATEGORY | FNOL INFORMATION | POST SURVEY INFORMATION |
|-----------------|--------------------|------------------------|-------------------------|--|-------------------------|
| Type | | | Occupation | Unknown | |
| Type of Paint | | | Education Qualification | Other | |
| Chassis No | MRHFC1660GT000453 | MRHFC1660GT0 | Driving Experience | 10 | |
| Engine No | L15B71629343 | L15B71629343 | Driver License # | | |
| Engine Capacity | | 1498 | License Type | | |
| Sum Insured | 0 | 0 | License Issue Date | | dd/mm/yy |
| Market Value | 0 | 93000 | License Expiration Date | | dd/mm/yy |
| | | | Address | BLK 156 RIVERVALE CRESCENT, #02-152, 540156, Singapore | |
| | | | Address type | Residential | |

POST SURVEY
INFORMATION

FNOL INFORMATION

CATEGORY

Gender

Male

Marital
status

Married

Identification
#

S8815686B


Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *

07/05/2019



Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

500

Young/Inexperienced/Un-named Driver Excess

0

Engine Modification

Yes No

Other Excess

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/50R17

Rear Tyre Size

215/50R17

Front left side

YOKOHAMA9mm

Rear left side

YOKOHAMA9mm

Front right side

YOKOHAMA9mm

Rear right side

YOKOHAMA9mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

| EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC QOUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) |
|--------------------------|-------|-----------|-------------------------------|-----------|-------------|-----------------------|-----------------------|---------------------|--------------|-------------|-----------|------------------|-----------------|----------------|
| <input type="checkbox"/> | 0 | 1 | BULKHEAD ASSY.FR. | | Repair | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | BRACEBULKHEAD LOWER | | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | FACEFR.BUMPER | | Deformed | 0 | 434.92 | No | | | | 434.92 | 434.92 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | GRILLE.FR.BUMPER LOWER | | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | PLATEFR.BUMPER LOWER INDUCTIO | | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | BASEFR LIC PLATE | | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | NUMBER PLATE WITH CASING | | Bent | 0 | 45 | No | | | | 45 | 45 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | GARNISHR.FR.BUMPER SIDE | | Deformed | 0 | 10.65 | No | | | | 10.65 | 10.65 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | GARNISHL.FR.BUMPER SIDE | | Deformed | 0 | 10.65 | No | | | | 10.65 | 10.65 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | BEAM COMPFR.BUMPER | | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |

| EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR/ BTRK% | DISC QUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) |
|--------------------------|-------|-----------|----------|-------------------------------|-------------|-----------------------|-----------------------|---------------------|-------------|------------|-----------|------------------|-----------------|----------------|
| <input type="checkbox"/> | 0 | 1 | | PLATEFR BUMPER-MIDDLE INDUCTN | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | | BEAM COMPFR BUMPER CENTER UPP | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | | BEAMR.FR BUMPER UPPER | Cracked | 0 | 20.02 | No | | | | 20.02 | 20.02 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | BEAML.FR BUMPER UPPER | Cracked | 0 | 20.02 | No | | | | 20.02 | 20.02 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | SPACERR.FR BUMPER SIDE | Bent | 0 | 7.8 | No | | | | 7.8 | 7.8 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | SPACERL.FR BUMPER SIDE | Bent | 0 | 7.8 | No | | | | 7.8 | 7.8 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | CLIP, BUMPER-22PCS | Necessary | 0 | 37.95 | No | | | | 37.95 | 37.95 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | BASE.FR GRILLE CHROME | Cracked | 0 | 55.35 | No | | | | 55.35 | 55.35 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | MOLDINGFR GRILLE | Cracked | 0 | 75.3 | No | | | | 75.3 | 75.3 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | EXTENSION ASSYR.FR GRILLE | Cracked | 0 | 64.2 | No | | | | 64.2 | 64.2 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | EXTENSION ASSYL.FR GRILLE | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | | RUBBERHOOD SEAL | Necessary | 0 | 20.7 | No | | | | 20.7 | 20.7 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | EMBLEM | Broken | 0 | 11.25 | No | | | | 11.25 | 11.25 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | NUJTPUSH 3MM-2PCS | Necessary | 0 | 3.15 | No | | | | 3.15 | 3.15 | Reviewing |
| <input type="checkbox"/> | 0 | 1 | | COVERFR.BULKHEAD | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | | LIGHT ASSYR.FR.FOG | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| <input type="checkbox"/> | 0 | 1 | | LIGHT ASSYL.FR.FOG | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |

| EDIT | SR NO | QUANTITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR/BTRR% | DISC QUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) |
|------|-------|----------|----------|----------------------------|-------------|-----------------------|-----------------------|---------------------|------------|------------|-----------|------------------|-----------------|----------------|
| | 0 | 1 | | HEADLIGHT ASSY.R. | Cracked | 0 | 892.27 | No | | | | 892.27 | 892.27 | Reviewing |
| | 0 | 1 | | HEADLIGHT ASSYL | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| | 0 | 1 | | RADIATOR COMP | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| | 0 | 3 | | COOLANT ANTI-FREEZE TYPE 2 | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| | 0 | 1 | | CONDENSER ASSY | Bent | 0 | 528.3 | No | | | | 528.3 | 528.3 | Reviewing |
| | 0 | 1 | | SENSOR ASSY/AMBIENT | Serviceable | 0 | 0 | No | | | | 0 | 0 | Deny |
| | 0 | 1 | | CLIP/AMBIENT SENSOR | Cracked | 0 | 4.05 | No | | | | 4.05 | 4.05 | Reviewing |
| | 0 | 1 | | SUNDRIES | Necessary | 0 | 20 | No | | | | 20 | 20 | Reviewing |

Labour

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT |
|------|-------|-------------------------|---|------------------------|------------------------|-----------------------|-----------------------|-----------------|---------|
| | 0 | | INSPECT FR LIGHTING MECHANISMS & FOCUS | 0 | 80 | 0 | 0 | Reviewing | |
| | 0 | | REMOVE & INSTALL A/C CONDENSER WITH FITTINGS | 0 | 230 | 0 | 0 | Reviewing | |
| | 0 | | REMOVE & INSTALL RADIATOR WITH FITTINGS | 0 | 0 | 0 | 0 | Deny | |
| | 0 | | REMOVE & RENEW BULKHEAD. STRAIGHTEN | 0 | 1120 | 0 | 0 | Reviewing | |
| | 0 | | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P) | 0 | 900 | 0 | 0 | Reviewing | |

Assessment Details

Add Approve Deny Submit All

| EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|------|-------|-------------------------|-----------|------------------|-----------------|---------|--------|
| | 0 | DAYS OF REPAIR : 5 DAYS | Reviewing | | 0 | | |

Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Estimated Claim Amount Adjusted Claim Amount **\$4,099.38**

| CATEGORY | ESTIMATE | ADJUSTED |
|-------------|----------|------------|
| Spare Parts | \$0.00 | \$2,269.38 |
| Labour | \$0.00 | \$2,330.00 |
| Excess | | -\$500.00 |

Submit for Review