

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6670 R

1 pc	Front n/s head lamp ✓	\$	1,028.00
1 pc	Support panel <i>x repair</i>	\$	645.00
1 pc	Air duct ✓	\$	210.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper sponge ✕	\$	116.00
1 pc	Front bumper reinforcement ✕	\$	328.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00 ✕	\$	32.00
1 pc	Front bumper n/s protector ✓	\$	51.00
1 pc	Front bumper n/s fog lamp cover ✓	\$	66.00
1 pc	Bonnet ✓	\$	979.00
1 pc	Bonnet grille ✓	\$	386.00
		\$	4,416.00
	Less 10%	\$	441.60
		\$	3,974.40

S/NETT

1 set	Front bumper clips ✓	\$	48.00
1 pc	Front no. plate ✓	\$	50.00 35
	Sundry		
	To top up aircon gas	\$	50.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	80.00 ✕
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$	180.00 ✕
	To putty and spray painting on bonnet, front bumper, front n/s fender	\$	400 900.00
	To apply rustproofing on the repaired and replaced panels.	\$	50 600.00
		\$	120.00 50
		\$	6,002.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalin UCKY
6/5/19 1700h
3 Pcs
L/S
After Repair photo