

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

* To disassemble damaged part(s) during resurvey
* Third party insurance claim on "as is" basis
* No illegal modification is allowed
* Supply of new part(s) must be resurveyed and
is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Alvin
date
7/5/19
Singapore
tel: 62563561

2/5 84000

5 day
Date, 6-5-19

Vehicle No: SLN 1735R

Chewolt Cruze

1	1PC Rear bumper	\$ 1047.00 dis -
2	1PC Rear bumper reinforcement	\$ 560.00 crs ✓
3	1PC Rear bumper Moulding centre	\$ 78.00 cm -
4	1PC Rear bumper Moulding side RH	\$ 62.00 cm -
5	1PC Tail lamp RH	\$ 683.00 cm -
6	1PC Boot lid w/strip	\$ 258.00 cm ✓
7	1PC End panel	\$ 987.00 w/seal ✓
8	2PC Reverse Sensor @ \$178.00	\$ 356.00 stuck 1PC
9	1PC End panel Garnish	\$ 258.00 11x
		\$ 4289.00 P-3853
	Less 10%	\$ 428.90 12
		\$ 3860.10 3467.70

S/Nett Item:-

1	1PC Rear no plate with ^{holder} bracket	\$ 35.00 scr ✓
2	1PC Reverse Camera	\$ 350.00 scr X

Labour charges:-

1)	To remove, replace reverse Sensor & Camera and check wiring	\$ 180.00 - 30
2)	To spray painting	\$ 980.00 - 900
3)	To remove, replace bumper & end panels	
	redign all accident parts to same	\$ 680.00 - 600

Total: \$ 6085.10 50327