



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



INDIA INT'L INSURANCE PTE LTD		NAME : Mr KT White		WIP : 27599	
64 CECIL STREET		ADDRESS : 21 Lambeth Walk		EXCESS :	
#04-06 IOB BUILDING		Singapore 798944		DATE: 03.05.2019	
SINGAPORE 049711		TEL : 96478802		<i>Kimberly 98501961</i>	
ATTN : MOTOR CLAIMS		FAX :			
VEH NO :	SKP3305L	DATE IN :		CONTACT PERSON :	JOBI THOMAS 63310682
CHASSIS NO :	WMWSS12010WN74512	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	R61	DATE REG.:	29.08.2014	POLICY NO. :	

NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
	QTY				
1	BONNET R60	1	M41.00.9.805.935	<i>bt</i>	\$ 1,698.00
2	TRIM RING, HEADLAMP LH	1	M51.13.9.813.823	<i>nei</i>	\$ 229.78
3	TRIM RING, HEADLAMP RH	1	M51.13.9.813.824	<i>mis</i>	\$ 229.78
4	EMBLEM FRONT	1	M51.14.9.811.725	<i>ng</i>	\$ 78.72
5	BONNET TWIST PROTECTOR	2	M51.23.7.002.012	<i>X</i>	\$ 16.90
6	TWIST PROTECTOR RIVET	2	M51.16.8.197.908	<i>X</i>	\$ 1.82
7	EXPANDING RIVET	20	M51.47.1.911.992	<i>nei</i>	\$ 27.40
8	FRONT BUMPER	1	M51.11.9.807.196	<i>Rp</i>	\$ 801.26
9	FRONT BUMPER LOWER CHORM FRAME	1	M51.11.9.804.005	<i>?</i>	\$ 160.03
10	FRONT BUMPER SPOILER	1	M51.11.9.801.917	<i>wt</i>	\$ 229.65
11	BLIND RIVET	4	M51.11.8.222.901	<i>nei</i>	\$ 5.72
12	RIVET	4	M51.77.0.382.696	<i>nei</i>	\$ 24.96
13	CLAMP	4	M07.14.7.054.461	<i>nei</i>	\$ 8.08
14	FRONT WHEEL ARCH	1	M51.77.9.800.762	<i>wt</i>	\$ 168.93
15	RIVET	6	M07.14.9.807.127	<i>ng</i>	\$ 7.02
16	SPLASH SHIELD	1	M51.71.9.807.830	<i>tn</i>	\$ 147.68
17	RIVET	9	M07.13.0.702.966	<i>nei</i>	\$ 12.87
18	FRONT FENDER	1	M41.00.9.805.644	<i>Rp</i>	\$ 500.18
19	SPLASH SHIELD LOWER LIP	1	M51.11.9.802.644	<i>? m/s</i>	\$ 21.91
20	RH HEADLIGHT(WHITE INDI.)	1	M63.12.9.801.032	<i>croq</i>	\$ 974.48
21	NUT	4	M63.12.2.752.224	<i>nei</i>	\$ 27.04
22	SPRING	4	M63.12.2.752.225	<i>me</i>	\$ 10.68
23	ANTI-FREEZE	2	B83.51.2.355.290	<i>?</i>	\$ 52.26
24	FRONT TOP SUPPORT PANEL	1	M51.64.9.802.008	<i>?</i>	\$ 721.11
TOTAL PARTS					\$ 6,156.26
					\$ -
TOTAL PARTS COST					\$ 6,156.26

Labour Description		
1	TO REPLACE BONNET, FRONT BUMPER, RH FRONT FENDER, FRONT SUPPORT PANEL &	<i>1680</i>
	TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>240</i> <i>*with support</i> <i>2940</i>

2	TO RESPRAY BONNET, FRONT BUMPER & RH FRONT FENDER. <i>800</i>	<i>1600</i>	\$ 2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>X</i>	\$ 250.00
4	TO REMOVE & REFIT RADIATOR, CONDENSER AND RADIATOR FAN ASSY.	NETT <i>?</i>	\$ 1,260.00
5	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	NETT <i>?</i>	\$ 500.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT <i>✓</i>	\$ 560.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>150.</i>	\$ 250.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>250</i>	\$ 350.00
9	SUNDRIES.	NETT <i>50</i>	\$ 100.00
TOTAL LABOUR		\$ -	\$ 10,070.00
TOTAL PARTS		\$ -	\$ 6,156.26
TOTAL		\$ -	\$ 16,226.26
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ -	
GST 7%		\$ -	\$ -
GRAND TOTAL		\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Tanjilun 97495449 / 67418434
'WP'
7/5/19 @ 320pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5-6 days

Resurvey before paint.
sure lkkauto.com