

INS. CASE OWNER:

CC 6 / N/A 1900 8009, U883/

IDAC:

Survivor:

marms

ASSIGNMENT

Date:

7/5/19

Registered in Meriton:

9/5/19

Assign / CCU / FTE



Insured Vehicle No.:

SLJ 9761H

Name of Insured:

KEE SIMMY HWE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

30/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Only HEE BLOW

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

482291098354

Policy No.:

A00085129-01

Make / Model:

MAZDA

Place of Accident:

SUE TMS HKE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKC 3185J



INSRS:

WSP:

Tel:

Liability:

RMKS: Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

9/9/19
khongkha

File pass to type mandate

01/1/2020
khongkha

File pass to mk to close.

C RV, vch no. wrong.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 45 \$S 14,500 (10 days) Reduction: 60 %

Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 11/12/19 Confirm with Jason

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28

If NO or B 28, Ass. Lia: 0

Repair Cost: (WHS) \$S 15,515.00

6UEH (C.C. 2013RDUE4)

Loss of Rental (LOR): \$S (days)

Loss of Use (LOU): \$S 773 (10 days) x \$77.30

Loss of Income (LOI): \$S (3 x days)

OR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$S 2.00

Medical: \$S -

Disbursement: \$S (e.g. Tow/ Independent)

Legal Cost \$S -

Total: \$S 16,290 Global Sum \$S: 16,000

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: \$S 16,000

Name 1: FASTECH AUTO PTE LTD

Payee 2 (Strike if N.A.): \$S

Name 2:

Payee 3 (Strike if N.A.): \$S

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 70

3) Survey fee: \$220

COPY SENT
8/1/2020

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

Aug/

FCN

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SKC 3185J
at Workshop m/s Lf.
of SLJ 9761H
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 80k
IDAC Accident Report: _____ Consistent? : Yes or No
GPR Seen: l Consistent? : Yes or No
Est. Repairs: 10 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 17752851 Vehicle: IN / OUT

Veh No: SKC 3185J Yr Regn: 8/15
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Subaru Forester cc 1998
Colour: Brown A/C: Insured / Std / NI / NA
Sp. Reading: 101710 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JF1SJ6K85F6056067
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/55R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7</u> mm
D.O.A. <u>30/4/19</u>	D.O.I. <u>7/5/19</u>

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/11/18 Dep 11 net 27149

have G.A

29/7/19 4/5 @ 14.520 confirmed with Aler

Ched \$ 22,085.60 / 60%)

10 days + 1 Sunday = 11 days

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

) \$ + RS \$ _____

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

)

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

(QB/11/13) wel
ASS. REC. BY: Marcus

REF: Ag/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SKC 3185J
at Workshop m/s SL
of SLJ 9761H
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SKC 3185J Yr Regn: 8, 15
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA /
Make: Subaru Forester c.c. 1998
Colour: Brown A/C: Insured / Std / NI / NA
Sp. Reading: 101710 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JF1SJGK85FG056067
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/55R18
R: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 80k
Consistent? : Yes or No
IDAC Accident Rpt: _____
Consistent? : Yes or No
Gla PR Seen: l
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear 7
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. 30/4/19 D.O.I. 7/5/19

Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & SL
The U/C / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: 17752851

Date / Time Action / Instruction
6/4/2019 Dep 11 net 27149
have h.a

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$ _____) S + RS _____
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

not Authorized
date
7/5/19
2/5 = 14,500/
10dy.

VEHICLE NO:SKC 3185J

QTY	PARTICULAR			
1 PCS	TAILGATE	R	\$1,225.00	X
1 PCS	TAILGATE REAR LOGO	neu	\$88.30	/
1 PCS	TAILGATE 'FORESTER' EMBLEM	neu	\$72.30	/
1 PCS	TAILGATE 'XT' EMBLEM	neu	\$72.00	/
1 PCS	TAILGATE 'SUBARU' EMBLEM	neu	\$75.00	/
1 PCS	TAILGATE 'STI' EMBLEM	neu	\$78.00	/
1 PCS	TAILGATE 'AWA' EMBLEM	neu	\$70.00	/
1 PCS	TAILGATE INNER LOCK	in	\$176.40	X
1 PCS	TAILGATE WEATHERSTRIP	twi	\$120.80	/
1 PCS	REAR BUMPER	m/be	\$800.40	/
1 SET	REAR BUMPER CLIPS	neu	\$50.00	/
1 PCS	REAR BUMPER REINFORCEMENT	neu	\$420.40	/
1 PCS	REAR BUMPER TOW COVER	De	\$28.80	/
2 PCS	REAR BUMPER REFLECTORS @\$35.00	in	\$70.00	X
2 PCS	REAR BUMPER SIDE REATINERS @\$45.00	in	\$90.00	X
1 PCS	REAR BUMPER LOWER SKIRTING	R	\$900.00	X
1 PCS	REAR END PANEL	body	\$615.00	/
1 PCS	REAR END PANEL TOP GARNISH	neu	\$288.00	/
2 PCS	TAILLAMP LEDS @\$1200.00 1050x2=2100	neu	\$2,400.00	/
1 PCS	REAR EXHAUST	R	\$788.20	X
1 PCS	REAR FLOOR PANEL	R	\$845.20	X
1 PCS	REAR FLOOR PANEL TOP BOARD	so/warped	\$600.50	/
1 PCS	REAR FLOOR PANEL TOOLS SPONGE	for	\$420.80	/
2 PCS	REAR FENEDR INNER TRIM BOARDS @\$425.10	in	\$850.20	X
1 PCS	BONNET	R	\$1,020.20	X
2 PCS	BONNET HINGES @\$65.00	in	\$130.00	X
1 SET	BONNET INSULATOR CLIPS	in	\$50.00	X
1 PCS	FRONT GRILLE TOP	neu	\$288.40	/
1 PCS	FRONT GRILLE BOTTOM	De	\$455.10	/
1 PCS	FRONT GRILLE "STI" EMBLEM	neu	\$45.00	/
1 PCS	FRONT GRILLE LOGO	neu	\$65.00	/
2 PCS	HEADLAMPS @\$2880.00 2380x2=4760	neu	\$5,760.00	/
2 PCS	HEADLAMP LOVER BRACKETS @\$105.00	neu	\$210.00	/
1 PCS	FRONT BUMPER	neu	\$800.50	/
1 SET	FRONT BUMPER CLIPS	neu	\$50.00	/
1 PCS	FRONT BUMPER TOW COVER	m-s	\$35.00	/
1 PCS	FRONT BUMPER REINFORCEMENT	neu	\$499.00	/
1 PCS	FRONT BUMPER REINFORCEMENT PROTECTOR	De	\$315.00	/
2 PCS	FRONT BUMPER SIDE RETAINERS @\$89.00	in	\$178.00	X
2 PCS	FRONT BUMPER FOG LAMPS @\$450.00 388.00x2=776	neu	\$900.00	/
2 PCS	FRONT BUMPER LAMPS @\$480.00 355.00x2=710	neu	\$960.00	/
1 PCS	FRONT BUMPER LOWER SKIRTING	neu	\$850.00	/
1 PCS	FRONT BUMPER LOWER CENTRE GRILLE	in	\$305.00	X
1 PCS	FRONT SUPPORT PANEL	neu	\$605.00	/
1 PCS	FRONT SUPPORT PANEL BRACKET	in	\$72.90	X
1 PCS	AIR CON CONDENSOR	neu	\$980.00	/

(202)

1 PCS	RADIATOR ASSY	
1 PCS	AIR FILTER AIR DUCT	231.00
1 PCS	BONNET LOCK	
1 PCS	FRONT BRACE PANEL	
2 PCS	FRONT FENDERS @\$300.60	
2 PCS	FRONT FENDER INNER SHIELDS @\$105.00	

11	\$995.00	X
11	\$365.00	—
11	\$109.00	—
11	\$166.00	—
11	\$601.20	X
11	\$210.00	X

\$28,165.60

S.NETT	
1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR BUMPER TOP PROTECTOR
1 PCS	REAR BUMPER STICKER (RED)
1 PCS	REAR EXHAUST
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	FRONT LICENCE PLATE W/HOLDER
1 PCS	FRONT GRILLE CARBON STICKER

shop	\$280.00	200
de	\$600.00	400
11	\$80.00	X
11	\$2,200.00	X
11	\$50.00	X
11	\$50.00	40
11	\$180.00	150

LABOUR CHARGES

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO SPRAY RUST PROOFING	\$120.00	80
TO DISMANTLE & REFIX TAILGATE MECHANISM	\$100.00	X
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTREY	\$120.00	80
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	X
TO DISMANTLE & REFIX REAR EXHAUST	\$180.00	60
TO REFILL AIR-CON GAS	\$150.00	100
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00	1500
TO PUTTY & SPRAY PAINTING	\$2,200.00	1600

TOTAL

\$36,585.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey 2 weeks after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The survey is on a "Without Prejudice" basis
- No further modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-17384
202
13907.2
18197.2

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	1211E

Vehicle Details

Vehicle No.:	SKC3185J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 May 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	FA20K918805
Chassis No.:	JF1SJGK85FG056067
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$17,522.00
Original Registration Date:	30 Sep 2015
First Registration Date:	30 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$17,522.00 8761

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2025
PARF Rebate Amount:	\$13,141.00

Intended COE Rebate Details

COE Expiry Date:	29 Sep 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,101.00
COE Rebate Amount:	\$39,710.00
Total Rebate Amount:	\$52,851.00

The information contained herein is correct as at 07 May 2019

OK

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

5 Cars That Won't Last 100,000 Miles

2019 Toyota RAV4

What make and model worth renew COE after 10 years

Subaru Forester

Price Range

Depreciation

2015

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Henly Enterprises Co > Subaru Forester 2.0XT Sunroof

Subaru Forester 2.0XT Sunroof

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Henly

興利

HENLY ENTERPRISES COMPANY PRIVATE LIMITED

18 Ubi Road 4, #01-05/07/08 Ubi Car Mall Singapore 408616 Tel: 6336 3133

PREMIUM DEALER

Price	\$76,800	Reg Date	24-Jun-2015 (6yrs 1mth 16days COE left)
Depreciation	\$11,140 /yr <small>View models with similar depre</small>	Manufactured	2015
Mileage	82,700 km (21.4k /yr)	Transmission	Auto
Road Tax	\$1,210 /yr	OMV	\$16,890
Dereg Value	\$58,674 as of today (change)	ARF	\$16,890
COE	\$75,000	Power	177.0 kW (237 bhp)
Engine Cap	1,998 cc	No. of Owners	1
Curb Weight	1,682 kg		
Type of Vehicle	SUV		

Features

2.0L Turbocharged Engine, 237 BHP, Linear Tronic CVT Automatic Gearbox, AWD, ABS, Airbags, Keyless Entry/Start/Stop, Auto Headlights And Rain Sensors. View specs of the Subaru Forester (2013-2019)

Accessories

Panoramic Roof, Leather Seats, Sports Rims, Built-In Audio With Steering Controls, Retractable Side Mirrors, Reverse Sensors/Camera, Fog Lights.

Description

1 Owner! Fully Agent Maintained, 100% Accident Free. 100% Stock Condition. Perfect Performance/Handling For AWD. Price Negotiable. Beautiful Paintwork With Clean And Neat Interior. Bank Or In House Loan Available. Purchased With Assurance From Henly Enterprises, Well Established Since 1972. Hurry! Call Us Now For Your Viewings And Test Drive Appointment Today.

Category

PARF Car

Status

Available

Resources

STA Compare

Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Location Map

Price Chart

Summary

Price (\$K)

82K

80K

78K

76K

74K

72K

Mar

May

Jul

Sep

Nov

Reg Date

Click on the point to view the vehicle

Shortlist

Report Error

Compare

More Actions

Add note

Seller Information

Company

Henly Enterprises Co

* dealer's pricelist

* 109 vehs sold | 30 vehs available

Address

61 Ubi Avenue 2 #05-12

Search cars nearby this location

https://www.sgcarmart.com/used_cars/info.php?ID=821422&DL=2473

07-May-19

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more

Subaru Forester

Price Range

Depreciation

2015

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Direct Owners > Subaru Forester 2.0XT Sunroof

Subaru Forester 2.0XT Sunroof

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Price

\$79,888

Depreciation

\$11,290 /yr

View models with similar depre

Mileage

50,000 km (13.5k /yr)

Road Tax

\$1,210 /yr

Dereg Value

\$52,141 as of today (change)

COE

\$62,140

Engine Cap

1,998 cc

Curb Weight

1,682 kg

Type of Vehicle

SUV

Reg Date

28-Aug-2015

(6yrs 3mths 20days COE left)

Manufactured

2015

Transmission

Auto

OMV

\$17,222

ARF

\$17,222

Power

177.0 kW (237 bhp)

No. of Owners

1

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	07 May 2019 16:19	Clim Dtl Modified	Claimant's Name: -> -.	[A] Lau Shu Pei
2	07 May 2019 16:19	Clim Veh Model Changed	(202021) ADIVA AD200A 200cc (M).	[A] Lau Shu Pei
3	07 May 2019 16:19	Clim Created	Reg No: SKC3185J. Acct Date: 2019/04/30. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Fastech Auto Pte Ltd (HQ)	[A] Lau Shu Pei
4	07 May 2019 16:19	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	07 May 2019 16:19	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/16	[A] Lau Shu Pei
6	07 May 2019 16:19	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	07 May 2019 16:19	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	07 May 2019 16:20	Label Added	(19):Fastlane.	[A] Lau Shu Pei
9	07 May 2019 16:20	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
10	09 May 2019 10:42	Clim Dtl Modified	Claimant's Name: UNKNOWN -> KANG TECK YEONG (JIANG DERONG). Claimant's ID: -> S7421211E.	[A] Lau Shu Pei
11	09 May 2019 10:42	Clim Veh Model Changed	(202021) -> (206192) SUBARU FORESTER 2.0 XT CVT AWD SR (A).	[A] Lau Shu Pei
12	23 Sep 2019 15:11	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	23 Sep 2019 15:11	Clim Dtl Modified	JPJ Reg. Date: -> 2015/09/30.	[A] JOANNE LEE KHANG MIN
14	23 Sep 2019 15:11	Clim Details Notified		[A] JOANNE LEE KHANG MIN
15	25 Sep 2019 11:27	Adj Mandate Request	Cur.Req:16617.00:6 Vehicle chain collision, Our Insured vehicle is 3rd - BOLA 28. * 10 days recommendation for repair + 1 Sundays = 11 days	[A] Khanchna Pothura

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2288530	23 Sep 2019 15:11:29	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKC3185J	SLJ9761H	11.77

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 6 November 2019 1:21 PM
To: Tan, Bennie-WZ
Cc: Admin A
Subject: RE: AIG Ref: 4822910983SG-005 || Accident Involving SLJ9761H / SKC3185J on 30/04/2019

Dear Mr. Bennie,

The above matter and your e-mail below refers.

As requested, our clarification is in blue below, please refer to Merimen for the photos:

- 1. FRONT BUMPER LAMPS** –Photos are taken from distance, please indicate the damages [please refer to 148]
- 2. AIR CON CONDENSOR-185-192** – Based on OI's video, both OI & TP already stopped. Please further advise on the possibility of damages [Video footage shows that the collision impact had pushed the third party vehicle and as such, we opine that there is a huge possibility to the damages]

The breakdown is below:

Parts – To repair, replace and re-fix takes about 6 days

Labour – takes about 4 days

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>

Sent: Tuesday, 5 November 2019 12:18 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: AIG Ref: 4822910983SG-005 || Accident Involving SLJ9761H / SKC3185J on 30/04/2019

Hi Khanchna

Please find our comment below in red. (see below email)

Also, you may have mis-understand our query on breakdown to the recommended repair days. In short, please let us have a breakdown to days of the respective repairs needed which adds up to the recommendation of total repair days: 10days.

Thank you.

marcus.

Khanchna (LKK Auto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Tuesday, 5 November 2019 12:18 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: AIG Ref: 4822910983SG-005 || Accident Involving SLJ9761H / SKC3185J on 30/04/2019

Hi Khanchna

Please find our comment below in red. (see below email)

Also, you may have mis-understand our query on breakdown to the recommended repair days. In short, please let us have a breakdown to days of the respective repairs needed which adds up to the recommendation of total repair days: 10days.

Thank you.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

PA:
TO REPAIR, REPLACE AND REFILL TAKE ABOUT 6 DAY
TO REPAIR TAKE ABOUT 4 DAY.

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: Tuesday, October 22, 2019 6:24 PM
To: Tan, Bennie-WZ
Cc: Admin A
Subject: [EXTERNAL] RE: AIG Ref: 4822910983SG-005 || Accident Involving SLJ9761H / SKC3185J on 30/04/2019

This message is from an external sender; be cautious with links and attachments.

Dear Mr. Bennie,

The above matter and your e-mail below refers.

As requested, our clarification is below, please refer to Merimen for the photos:

1. TAILLAMP LEDS - 101-104
2. FRONT BUMPER LAMPS -145-147 -Photos are taken from distance, please indicate the damages - REFER 148.
3. AIR CON CONDENSOR-185-192 - Based on OI's video, both OI & TP already stopped. Please further advise on the possibility of damages, BASE ON THE VIDEO SHOW THAT ON THE IMPACT OF PUSH TP VEH AND
4. AIR FILTER AIR DUCT-160-162 FURTHER, THERE IS A HIGH POSSIBILITY TO THE DAMAGES,

The breakdown is below:

** 10 days recommendation for repair + 1 Sundays = 11 days

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>

Sent: Friday, 4 October 2019 11:20 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Subject: AIG Ref: 4822910983SG-005 || Accident Involving SJ9761H / SKC3185J on 30/04/2019

Hi Khanchna

Referring to above mandate request.

Please let us have your surveyor comments on their recommendation to the following:

1. **TAILLAMP LEDS**
2. **FRONT BUMPER LAMPS**
3. **AIR CON CONDENSOR**
4. **AIR FILTER AIR DUCT**

Also, please let us have a breakdown to the recommended repair days (i.e. 10days)

10 days -

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not

use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Khanchna (LKK Auto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Friday, 4 October 2019 11:20 AM
To: Khanchna (LKK Auto)
Subject: AIG Ref: 4822910983SG-005 || Accident Involving SLJ9761H / SKC3185J on 30/04/2019

Hi Khanchna

Referring to above mandate request.

Please let us have your surveyor comments on their recommendation to the following:

1. **TAILLAMP LEDS** 101-104
2. **FRONT BUMPER LAMPS** - 145-147.
3. **AIR CON CONDENSOR** - 185-192
4. **AIR FILTER AIR DUCT** - 160-162.

Also, please let us have a breakdown to the recommended repair days (i.e. 10days)

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



X

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Fastech Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. _____ ("name of surveyor") with respect to the amount claimed for S\$ _____ (repair costs), S\$ _____ (loss of use/rental) S\$ _____ (search fees) for vehicle no. SKC 3185J that was damaged pursuant to the accident which occurred on 30.04.2019 (date) along SLE Twds BKE (location) involving vehicle no/s SLJ 9761H.

This is pursuant to the inspection conducted on _____ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Kang Teck Yeong ("third party claimant") of vehicle no. SKC 3185J to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKC 3185J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this _____ day of _____ (month) 20____ (year)

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 11 December 2019 11:34 AM
To: Jason
Cc: Admin A
Subject: OFFER - Accident between SKC 3185J & SLJ 9761H (AIG) on 30/04/2019

Tracking:	Recipient	Delivery
	Jason	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 11/12/2019 11:34 AM
	olivialau@lkkauto.com	Delivered: 11/12/2019 11:34 AM
	shupei@lkkauto.com	Delivered: 11/12/2019 11:34 AM

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement on a global sum for \$16,000.00(all in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason <Jason@fastechauto.com.sg>

Sent: Wednesday, 11 December 2019 5:14 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: OFFER - Accident between SKC 3185J & SLJ 9761H (AIG) on 30/04/2019

Without Prejudice

Dear Khanchna,

We are pleased to accept your offer of global sum \$16,000.00(all in) for my client's vehicle property claim.

Thank you.

Best Regards

Jason Tang

Fastech Auto Pte Ltd

1 Kaki Bukit Ave 6

#01-46/48/50 AutoBay

Singapore 417883

Tel: 67465405

Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Khanchna (LKK Auto)

From: Jason <Jason@fastechauto.com.sg>
Sent: Wednesday, 18 December 2019 3:56 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: OFFER - Accident between SKC 3185J & SLJ 9761H (AIG) on 30/04/2019
Attachments: SKC3185J.pdf

Without Prejudice

Dear Khanchna,

We enclosed a copy of the signed DV for your perusal.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: Tuesday, December 17, 2019 8:43 AM
To: Jason <Jason@fastechauto.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: OFFER - Accident between SKC 3185J & SLJ 9761H (AIG) on 30/04/2019

Without Prejudice

Dear Sir/Madam,

Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Print Received Message

This mail is associated with :

***SKC3185J (4822910983SG)**
[SLJ9761H]

TP

KANG TECK YEONG (JIANG DERONG)

Apr 30 2019 12:00AM

[LEE SIANG HWEE]

Fastech Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 30/11/2019 15:38 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16290.00) - SKC3185J - Claim Handler: Tan, Bennie-WZ

Approved:16290.00:Pls do your utmost to negotiate settlement from: \$16,000 to \$16,290 (All-in)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2019 Edit Reg		07 May 2019 00:00 Edit Adj Rpt	S\$14,500.00 Edit Estimates	S\$14,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE SIANG HWEE, ID: S7734212E								
Main Claimant:	KANG TECK YEONG (JIANG DERONG), ID: S7421211E								
Vehicle Reg. No.:	SKC3185J	Date of Loss:	30/04/2019 00:00 - :59 [43 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4822910983SG	Policy/Cover Note No.:	1700085139 (Comprehensive) Coverage: 30/12/2018 - 29/12/2019						
Vehicle Reg. No. (Insured):	SLJ9761H	Policy No. (Claimant):	5100868358						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 16/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (30/11/2019): Alert - Adj Mandate Approved (S\$16290.00) - SKC3185J - Claim Handler: Tan, Benni... AIG_SG_EXPRESS (05/11/2019): Alert - Adj Mandate Maintained - SKC3185J - Claim Handler: Tan, Bennie-WZ AIG_SG_EXPRESS (04/10/2019): Alert - Adj Mandate Maintained - SKC3185J - Claim Handler: Tan, Bennie-WZ AIG_SG (08/05/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC3185J (4822910983SG)
[SLJ9761H]
TP
KANG TECK YEONG (JIANG DERONG)
Apr 30 2019 12:00AM
[LEE SIANG HWEE]
Fastech Auto Pte Ltd















































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)















































View View in Browser















































Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	04/10/19 10:53	OI Video - Accident (front)		Load MP4	
2	04/10/19 10:56	OI Video - Accident (rear)		Load MP4	













Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder			Thumbnail	Print
1	07/05/19 18:22	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	07/05/19 18:22	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
4	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
5	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
6	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
7	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
8	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
9	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
10	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
11	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
12	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
13	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
14	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
15	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
16	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
17	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
18	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
19	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
20	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
21	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
22	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
23	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
24	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
25	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
26	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
27	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
28	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
29	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
30	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
31	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
32	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
33	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
34	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>
35	07/05/19 18:23	General View		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
36	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
59	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
60	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
61	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
62	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
63	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
64	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
65	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
66	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
67	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
68	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
69	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
70	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
71	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
72	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
73	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
74	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
75	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
76	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
77	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
78	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
79	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
80	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
81	07/05/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
82	07/05/19 18:23	General View	Load JPG	<input checked="" type="checkbox"/>
83	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
92	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
139	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
140	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
141	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
142	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
143	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
144	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
145	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
146	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	07/05/19 18:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ATG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
148	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	07/05/19 18:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	07/05/19 18:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
195	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
196	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
197	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
198	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
199	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
200	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
201	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
202	07/05/19 18:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/05/19 18:00	TP GIA REPORT	 Load PDF	
2	23/08/19 09:29	LETTER TO OI	 Load PDF	
3	03/09/19 17:18	OI AMENDED GIA REPORT	 Load PDF	
4	23/09/19 15:28	GIA SEARCH	 Load PDF	
5	23/09/19 15:28	LOD	 Load PDF	
6	06/11/19 17:09	TP ESTIMATE MARKED (FINAL)	 Load PDF	
7	18/11/19 12:16	TP LOD, LTA SEARCH, FINAL REPAIR BILL, AUTHORISATION LETTER	 Load PDF	
8	09/01/20 09:49	WORKSHOP INVOICE	 Load PDF	
9	09/01/20 09:49	AUTHORISATION TO ACT FORM	 Load PDF	
10	09/01/20 09:49	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/05/19 11:17	OI GIA report	 Load PDF	
2	04/10/19 11:23	SME637H GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLJ9761H (Insd veh)	Model:	SUBARU FORESTER 2.0 XT
	SKC3185J (TP veh)		CVT AWD SR (A)
Date of Accident:	30/04/2019		

Global Sum Settlement	: <input checked="" type="checkbox"/> [X] Yes	: <input type="checkbox"/> [] No	
Repair Estimate	: \$		39,146.59
Final Repair Cost	: \$		16,000.00
Loss of Use	: \$		10.00 days at \$77.30 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$		16,000.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	: \$	16,000.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

09 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
 Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19008009/UKA3Q2

Date: 09/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700085139
Claimant
Vehicle No : SKC3185J **Insured Vehicle No :** SLJ9761H
Date of Loss: 30/04/2019 **Nature of Claim:** TP **Claim No:** 4822910983SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC3185J**
 Make & Model: SUBARU FORESTER, 2.0 XT CVT AWD SR (A) Engine No: FA20K918805
 Reg. Date: 30/09/2015 (Man. Year: 2015) Chassis No: JF1SJGK85FG056067
 Colour: Brown Odometer: 101710 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,605.60	14,697.20	16,908.40	53.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	3,500.00	1,480.00	29.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,585.60	18,197.20	18,388.40	50.26
Approved Total (Overridden) (S\$)		14,500.00		
(S\$)	36,585.60	14,500.00	22,085.60	60.37
+ GST 7.00/7.00% (S\$)	2,560.99	1,015.00	1,545.99	60.37
Nett Amount (S\$)	39,146.59	15,515.00	23,631.59	60.37
+ Loss of Use (10.0 x S\$77.30/day) (S\$)		773.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		16,290.00		
Global Sum Settlement (S\$)		16,000.00		

INSPECTION

Date of Assignment: 07/05/2019
 Date Inspected: 07/05/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,225.00 F	*- FL
2	1		*TAILGATE REAR LOGO	Necessary	88.30 F	*88.30 FL
3	1		*TAILGATE FORESTER EMBLEM	Necessary	72.30 F	*72.30 FL
4	1		*TAILGATE XT EMBLEM	Necessary	72.00 F	*72.00 FL
5	1		*TAILGATE SUBARU EMBLEM	Necessary	75.00 F	*75.00 FL
6	1		*TAILGATE STI EMBLEM	Necessary	78.00 F	*78.00 FL
7	1		*TAILGATE AWA EMBLEM	Necessary	70.00 F	*70.00 FL
8	1		*TAILGATE INNER LOCK	Not Necessary	178.40 F	*- FL
9	1		*TAILGATE WEATHERSTRIP	Twisted	120.80 F	*120.80 FL
10	1		*REAR BUMPER	Dented / Deformed	800.40 F	*694.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	420.40 F	*420.40 FL
13	1		*REAR BUMPER TOW COVER	Deformed	28.80 F	*28.80 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	70.00 F	*- FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	90.00 F	*- FL
16	1		*REAR BUMPER LOWER SKIRTING	Repair	900.00 F	*- FL
17	1		*REAR END PANEL	Badly Dented	615.00 F	*615.00 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	288.00 F	*288.00 FL
19	2		*TAILLAMP LEDS	Cracked	2,400.00 F	*2,100.00 FL
20	1		*REAR EXHAUST	Repair	788.20 F	*- FL
21	1		*REAR FLOOR PANEL	Repair	845.20 F	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Dented / Warped	600.50 F	*600.50 FL
23	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	420.80 F	*420.80 FL
24	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	850.20 F	*- FL
25	1		*BONNET	Repair	1,020.20 F	*- FL
26	2		*BONNET HINGES	Not Necessary	130.00 F	*- FL
27	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
28	1		*FRONT GRILLE TOP	Cracked	288.40 F	*288.40 FL
29	1		*FRONT GRILLE BOTTOM	Deformed	455.10 F	*311.00 FL
30	1		*FRONT GRILLE STI EMBLEM	Necessary	45.00 F	*45.00 FL
31	1		*FRONT GRILLE LOGO	Necessary	65.00 F	*65.00 FL
32	2		*HEADLAMPS	Cracked	5,760.00 F	*4,760.00 FL
33	2		*HEADLAMP LOWER BRACKETS	Cracked	210.00 F	*210.00 FL
34	1		*FRONT BUMPER	Dented / Deformed	800.50 F	*694.30 FL
35	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
36	1		*FRONT BUMPER TOW COVER	Missing	35.00 F	*35.00 FL
37	1		*FRONT BUMPER REINFORCEMENT	Bent	499.00 F	*420.50 FL
38	1		*FRONT BUMPER REINFORCEMENT PROTECTOR	Distorted	315.00 F	*288.20 FL
39	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	178.00 F	*- FL
40	2		*FRONT BUMPER FOG LAMPS	Cracked	900.00 F	*776.00 FL
41	2		*FRONT BUMPER LAMPS	Cracked	960.00 F	*710.00 FL
42	1		*FRONT BUMPER LOWER SKIRTING	Necessary / Deformed	850.00 F	*850.00 FL
43	1		*FRONT BUMPER LOWER CENTRE GRILLE	Not Necessary	305.00 F	*- FL
44	1		*FRONT SUPPORT PANEL	Bent	605.00 F	*600.70 FL
45	1		*FRONT SUPPORT PANEL BRACKET	Not Necessary	72.90 F	*- FL
46	1		*AIR CON CONDENSOR	Bent	980.00 F	*980.00 FL
47	1		*RADIATOR ASSY	Not Necessary	995.00 F	*- FL
48	1		*AIR FILTER AIR DUCT	Twisted	365.00 F	*231.00 FL
49	1		*BONNET LOCK	Twisted	109.00 F	*109.00 FL
50	1		*FRONT BRACE PANEL	Bent	166.00 F	*166.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	2		*FRONT FENDERS	Repair	601.20 F	*- FL
52	2		*FRONT FENDER INNER SHIELDS	Not Necessary	210.00 F	*- FL
53	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
54	1		*REAR BUMPER TOP PROTECTOR	Deformed	600.00 FS	*400.00 FS
55	1		*REAR BUMPER STICKER (RED)	Not Necessary	80.00 FS	*- FS
56	1		*REAR EXHAUST	Repair	2,200.00 FS	*- FS
57	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
58	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
59	1		*FRONT GRILLE CARBON STICKER	Necessary	180.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	31,605.60	18,174.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	3,476.80

Total Parts (\$\$)	31,605.60	14,697.20
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	120.00	80.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	180.00	60.00
8	TO REFILL AIR-CON GAS	New	150.00	100.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,500.00
10	TO PUTTY & SPRAY PAINTING	New	2,200.00	1,600.00
Gross Labour Cost (S\$)			4,980.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >