

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Denesh Darren S/O Thangaran
 TP INSURER: AIG Asia Pacific Insurance Pte Ltd
 POLICY NO: 5106463875
 REFERENCE: TP CLAIM
 DOA: 06/05/2019

Cecilia

REPAIR ESTIMATE

Est. No. : E19050001
 Date : 06/05/2019
 Vehicle Num. : SJK8619L
 Make/Model : TOYOTA ,COROLLA ALTIS
 Chassis/Eng# : MR053ZEE106121877

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Rear Bootlid <i>Painted</i>	1.00	606.40	606.40 ✓
2	Rear Bootlid Lamp <i>Painted</i>	2.00	145.00	290.00 ✓
3	Rear Taillamp <i>Painted</i>	2.00	237.80	475.60 ✓
4	Rear Bumper <i>Painted</i>	1.00	482.10	482.10 ✓
5	Rear Bumper Reflector <i>new</i>	2.00	66.10	132.20 ✓
6	Rear Bumper Sponge <i>Painted</i>	1.00	120.10	120.10 ✓
7	Rear Bumper Side Retainer LH/RH <i>new</i>	2.00	66.10	132.20 ✓
8	Rear End Panel <i>Painted</i>	1.00	517.10	517.10 ✓
9	Rear End Panel Garnish <i>Painted</i>	1.00	214.10	214.10 ✓
10	Bootlid Inner Lock <i>Painted</i>	1.00	145.35	145.35 ✓
11	Bootlid Inner Lock Striker <i>new</i>	1.00	65.00	65.00 ✓
12	Rear Bumper Clips <i>new</i>	1.00	12.10	12.10 ✓
13	Rear Exhaust Muffler <i>new</i>	1.00	971.10	971.10 ✓
14	Bootlid Chrome Garnish <i>Painted</i>	1.00	342.23	342.23 ✓
				Amt S\$ 4,505.58
				Discount (25.00%) S\$ 999.99
				Subtotal S\$ 3,379.19

3337.28
2502.96

Section: SPECIAL NETT ITEMS				
15	Number Plate <i>new</i>	1.00	50.00	50.00 ✓
16	Rear Bootlid Logo Emblem	1.00	80.00	80.00 42
17	Rear Bootlid "Corolla" Emblem	1.00	80.00	80.00 45
18	Rear Bootlid "Altis" Emblem	1.00	80.00	80.00 48
19	Rear Bootlid "1.6" Emblem	1.00	80.00	80.00 40
20	Rear Bootlid "TRD" Emblem	1.00	80.00	80.00 50

225
less 25%: 168.75

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Denesh Darren S/O Thangaran
 TP INSURER: AIG Asia Pacific Insurance Pte Ltd
 POLICY NO: 5106463875
 REFERENCE: TP CLAIM
 DOA: 06/05/2019

REPAIR ESTIMATE

Est. No. : E19050001
 Date : 06/05/2019
 Vehicle Num. : SJK8619L
 Make/Model : TOYOTA COROLLA ALTIS
 Chassis/Eng# : MR053ZEE106121877

No	Description	Qty	U/P	Amt
21	Rear Reverse Sensor <i>200</i>	2.00	300.00	600.00 <i>200</i>
				Amt S\$ 1,050.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,050.00

Section: LABOUR

22	To Remove and Reinstall Rear Bumper	1.00	100.00	100.00 ✓
23	To Remove & Reinstall Rear End Panel	1.00	350.00	350.00 <i>300</i>
24	To Remove & Reinstall Tailgate	1.00	100.00	100.00 ✓
25	To Remove & Reinstall Tailgate Components	1.00	80.00	80.00 <i>60</i>
26	To Remove & Reinstall Rear Exhaust Muffler	1.00	100.00	100.00 +
27	To Sand Down, Primer & Spraypaint	1.00	850.00	850.00 <i>700</i>
				Amt S\$ 1,580.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,580.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian L
2/5 07/05/19.
06 days.

total: 4131.71.
4/5: 3.3K ✓



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 3,379.19
SPECIAL NETT ITEMS Subtotal S\$ 1,050.00
LABOUR Subtotal S\$ 1,580.00
Total S\$ 6,009.19