

ASS. REC. BY: [initials] CS/CTI/19008023/09ds | n2
Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Elaine cheong of CTF Date/Time: 6/5/19 @ 5:48pm

Estimated Cost: Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. SMA1312 Insured: GBF 7252M

at Workshop no/s Specialist Motor Tel: 67 47 2112

of Blk 3018A ubi Rd / # 01-24

Policy No: DMCVSN 3018 211902 Claim No: SNM 19D201993C02/2

Sum insured: Excess:

Make of Veh: D.O.A: 3/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endor. Consent

Date/Time: 10:00am @ 7/5/19 Person Contacted: Irene

Vehicle IN / OUT


Date/Time	Action/Instruction (✓) Estimate
	SMA 1312 - ✓
	GBF 7252M - ✓

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMA1312J
 at Workshop m/s: Sport
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMA1312J Yr Regn: 6.18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Honda used c.c 1496
 Colour: purple A/C: Insured / Std / NI / NA
 Sp. Reading: 13357 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11303191
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Front		Rear	
R/Bal. 7 mm		R/Bal. 7 mm	
L/Bal. 7 mm		L/Bal. 7 mm	
D.O.A. 3/5/19		D.O.I. 13/5/19	
Survey held at _____			
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rear			
The U/C / Chassis frame / Body Structure affected due to collision.			

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 1.5% 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS LTA 44549
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
14/5/19	continued f. of \$2328.64 with inc. (had to 2940.64, 56%)

RECEIVED 17 MAY 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?
 Report Format: MER-TP
 Lump Sum / I.B.I.: (\$ 2328.64)

Days Of Repair: 4
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 Photos _____
 Others _____
 TOTAL: 220

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 6 May 2019 5:48 PM
To: Specialists Motor Pte Ltd; 'assignments'
Subject: FW: ACCIDENT INVOLVING SMA1312J AND GBF7252M ON 03/05/2019 AT ONFORNT OF 23 WESTWOOD TERRACE (CLAIM REF: SNM19D201993C02/2)
Attachments: 0441_001.pdf; IMG_3950.JPG; IMG_3952.JPG; IMG_3964.JPG

WITHOUT PREJUDICE

Dear Irene,

We refer to your email of 06.05.19.

Our insured have yet to report the accident to us.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer email below and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Claims Dept of CTI
Sent: Monday, 6 May, 2019 11:02 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; cardoc@singnet.com.sg
Cc: Angie Foo <angie.foo@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: FW: ACCIDENT INVOLVING SMA1312J AND GBF7252M ON 03/05/2019 AT ONFORNT OF 23 WESTWOOD TERRACE

Dear Elaine,

Please conduct PRS – TP: SMA1312J (SNM19D201993) soonest possible.
File with OIC – Elaine - 63896530

From: Specialists Motor Pte Ltd [<mailto:cardoc@singnet.com.sg>]
Sent: Monday, 6 May 2019 11:04 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: ACCIDENT INVOLVING SMA1312J AND GBF7252M ON 03/05/2019 AT ONFORNT OF 23 WESTWOOD TERRACE

Without Prejudice

Dear Sir/ Madam

Please refer to the above matter.

Our client (SMA1312J) is claiming against your insured GBF7252M.

Attached estimate, claim form and photos for your perusal.

Kindly check for us the above claim liability and arrange surveyor to survey the above vehicle at

Specialists Motor Pte Ltd

Blk 3018A, Ubi Road 1

#01-24/25/26

Singapore 408711

Thanks & Regards

Irene

67472112

From: cardoc@singnet.com.sg [<mailto:cardoc@singnet.com.sg>]

Sent: Monday, 6 May, 2019 9:43 AM

To: CARDOC

Subject: Attached Image



This email has been checked for viruses by AVG antivirus software.

www.avg.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0273Z
Vehicle Details	
Vehicle No.:	SMA1312J
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Purple
Manufacturing Year:	2018
Engine No.:	L15B5553197
Chassis No.:	RU11303191
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,536.00
Original Registration Date:	20 Jun 2018
First Registration Date:	20 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$12,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2028
PARF Rebate Amount:	\$9,113.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,941.00
COE Rebate Amount:	\$35,436.00
Total Rebate Amount:	\$44,549.00

The information contained herein is correct as at 13 May 2019

OK

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMA1312J/1905061

06th May 2019

The Manager
Motor Claim Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

*not adjust
Laba
to be replaced
4 days
13/5/19*

Date of Accident : 03rd May 2019
Location : Infont of 23 Westwood Terrace
Third Party Claim Vehicle No : GBF 7252 M
Repair Cost For Vehicle No : SMA 1312 J Honda Vezel

P/P \$2328.64

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Rear bumper fascia	<i>gran</i> 1	463.70	\$ 463.70 ✓
2	Rear bumper clips	<i>ner</i> 1set	35.00	\$ 35.00 ✓
3	Rear bumper quarter panel <i>side ALS</i>	<i>dis/cor</i> 1	411.90	\$ 411.90 ✓
4	Rear bumper side retainer LH	<i>st</i> 1	17.50	\$ 17.50 ✓
5	Rear fender LH	<i>n</i> 1	931.80	\$ 931.80 X
6	Rear fender cowling LH	<i>fl.1</i> 1	147.50	\$ 147.50 ✓
7	Rear fender cowling clips	<i>ner</i> 1set	35.00	\$ 35.00 ✓
8	Rear fender wheel arch garnish	<i>mis/ton</i>	150.20	\$ 150.20 ✓
				\$ 2,192.60
			Less 20%	\$ 438.52
				<u>\$ 1,754.08</u>

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMA1312J/1905061

06th May 2019

Balance b/f \$ 1,754.08

Labour Charges :-

Amounts

Cut out, renew, knocking & welding rear bumper fascia, rear fender LH, rear bumper quarter panel LH, tail lamp LH, remove & install all damage parts, straighten & re-align body	\$ 1,800.00	600
Remove & refix rear cabin, interior upholstery & safety belt	\$ 230.00	20
Remove & refix fuel tank to facilitate repairs	\$ 100.00	X
Tuff-kote on damage parts	\$ 80.00	20
Spray painting on damage parts	\$ 1,200.00	600
Check all lighting after repairs	\$ 35.00	20
Computerise wheel alignment	\$ 120.00	X
Labour Charge	\$ 3,565.00	
Total Amount	\$ 5,319.08	

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

WORKS Certificate No. is now
the Proprietor of the following:

- To include body and spray painting
- To include bumper parts, being refixing
- To include all work on confirmation
- This certificate is a "Without Prejudice" basis
- No other work should be done
- Specialist work must be rescheduled and
subject to approval from Insurance Company.

Acknowledged by Receiver:
Signature:
Date:

2-1260-80
202
100864
2328.64

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119008023/UQD3N2

Date: 22/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3018211902	
Claimant Vehicle No :	SMA1312J	Insured Vehicle No :	GBF7252M	
Date of Loss:	03/05/2019	Nature of Claim:	TP	Claim No: SNM19D201993C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA1312J	Engine No:	L15B5553197
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11303191
Reg. Date:	20/06/2018 (Man. Year: 2018)	Odometer:	13357 km
Colour:	Purple		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,754.08	1,008.64	745.44	42.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,565.00	1,320.00	2,245.00	62.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,319.08	2,328.64	2,990.44	56.22
+ GST 7.00/7.00% (\$\$)	372.34	163.00	209.34	56.22
Nett Amount (\$\$)	5,691.42	2,491.64	3,199.78	56.22

INSPECTION

Date of Assignment:	15/05/2019		
Date Inspected:	13/05/2019	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2019)	
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMA1312J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Grazed	463.70 FL	*463.70 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
3	1		*REAR BUMPER SIDE N/S	Distorted / Cracked	411.90 FL	*411.90 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Bent	17.50 FL	*17.50 FL
5	1		*REAR FENDER LH	Repair	931.80 FL	*- FL
6	1		*REAR FENDER COWLING LH	Torn	147.50 FL	*147.50 FL
7	1		*SET REAR FENDER COWLING CLIPS	Necessary	35.00 FL	*35.00 FL
8	1		*REAR FENDER WHEEL ARCH GARNISH	Missing / Torn	150.20 FL	*150.20 FL
Sub Total (S\$)					2,192.60	1,260.80
- List Item Discount on L Items 20.00/20.00% (S\$)					438.52	252.16
Total Parts (S\$)					1,754.08	1,008.64

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT, RENEW, KNOCKING & WELDING REAR BUMPER FASCIA, REAR FENDER LH, REAR BUMPER QUARTER PANEL LH, TAIL LAMP LH, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY.	New	1,800.00	600.00
2	REMOVE & REFIX REAR CABIN, INTERIOR, UPHOLSTERY & SAFETY BELT.	New	230.00	80.00
3	REMOVE & REFIX FUEL TANK TO FACILITATE REPAIRS.	New	100.00	0.00
4	TUFF-KOTE ON DAMAGE PARTS.	New	80.00	20.00
5	SPRAY PAINTING ON DAMAGE PARTS.	New	1,200.00	600.00
6	CHECK ALL LIGHTING AFTER REPAIRS.	New	35.00	20.00
7	COMPUTERISE WHEEL ALIGNMENT.	New	120.00	0.00
Gross Labour Cost (\$\$)			3,565.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >