



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19008034/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CYNTHIA LOH

Date : 27-05-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 6801X	Veh. Inspected	SJD 6019T
Policy No.	P1522514	Coverage (\$)	0.00
Claim No.	S9M01MCF	Excess (\$)	0.00
Assign From		Assign Date	08/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053ZEE106100640	Colour	SILVER
Odometer	419699	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	KAPSEN	6 mm
L/H Front Tyre	195/65 R15	KAPSEN	6 mm
R/H Rear Tyre	195/65 R15	KAPSEN	6 mm
L/H Rear Tyre	195/65 R15	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/05/2019	Inspection Date	08/05/2019
Survey held at	25 DEFU LANE 9		
Repairer	ALLSWELL MOTOR TRADERS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------