

marcus.hue@lkkaweb.com

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email:ben@allswellmotor.com.sg

Not Authorized
marcus. hbl
8/5/18
The H. Allswell
1/5 = 1400/2
Hbl

(3rd party claim against AXA insured XB601X

DOT : 03:05.2019

Estimate repair

Vehicle No. : SD6019T
Make & Model : Corolla Auto
Chassis No. : 1.6 Auto

Submitted by : Bm
COE expiry : 27-03-2023
Engine No. :

Date of survey :

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper	01	#900.00	566.10	712 ✓
02	LH near door	01	#690.00		* repair 2X
03	LH near fender	01	#741.60	252	* repair 2X
Special note					
166	01 Clasp / retainer slide for rear bumper bumper & door upholstery board #40/pkt	01	#40.10	40	not ✓
Labour Description					
01	Panel knocking on LH door rear, fender arc & door arc	01	#800.00		600
02	Spray painting on all affected parts (door, fender, door arc) including putty & ground	01	#800.00		700
			#391.60		
	P - 566.10				
	502				
	P - 283.05				
	S.N - 40.00				
	1300.00				
	7.196 #1623.05				
LKK Auto Consultants hence notify the Repairer of the following:					
- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Part prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company					
Acknowledged by Repairer					
Signature:					
Date:					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.