

(ROC / GST Reg. No. 201500371E)
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Tel : 6341 6789 Fax: 6341 6778
E-mail: visionautowork@gmail.com

TO : CHINA MOTOR CLAIMS DEPTS
VEHICLE NO : SJY7451K
MODEL : MIT-LANCER
DATE OF ACCIDENT : 04.05.19
TIME OF ACCIDENT : 16:30HRS

CLAIM DETAIL : PARTS		QTY	UNIT LIST PRICE	TOTAL LIST PRICE
S/N	DESCRIPTION			
1	BOOT LID <i>Dented</i>	1	\$ 680.00	\$ 680.00
2	BOOT LID LOGO	1	\$ 39.00	\$ 39.00
3	BOOT LID EMBLEM "LANCER" <i>2</i>	1	\$ 43.00	\$ 43.00
4	BOOT LID EMBLEM "EX" <i>1</i>	1	\$ 32.00	\$ 32.00
5	BOOT LID HINGE <i>new</i>	2	\$ 125.00	\$ 250.00
6	BOOT LID TOP LOCK <i>Dented</i>	1	\$ 159.00	\$ 159.00
7	BOOT LID LOWER LOCK <i>new</i>	1	\$ 21.00	\$ 21.00
8	BOOT LID WEATHER STRIP <i>1</i>	1	\$ 160.00	\$ 160.00
9	BOOT LID THIRD BRAKE LIGHT <i>new</i>	1	\$ 379.00	\$ 379.00
10	REAR BUMPER <i>Dented</i>	1	\$ 710.00	\$ 710.00
11	REAR BUMPER REFLECTOR <i>LH cracked</i>	2	\$ 67.00	\$ 134.00
12	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 387.00	\$ 387.00
13	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 58.00	\$ 116.00
14	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 59.00	\$ 118.00
15	REAR NUMBER PLATE LAMP BRACKET <i>new</i>	2	\$ 39.00	\$ 78.00
16	REAR NUMBER PLATE LAMP WIRE HARNESS <i>new</i>	1	\$ 490.00	\$ 490.00
17	TAIL LAMP <i>cracked LH</i>	2	\$ 349.00	\$ 698.00
18	TAIL LAMP PANEL LH <i>Dented</i>	1	\$ 198.00	\$ 198.00
19	REAR FENDER LH <i>Buckled</i>	1	\$ 894.00	\$ 894.00
20	REAR FENDER AIR VENT LH <i>Dented</i>	1	\$ 79.00	\$ 79.00
21	REAR FENDER INNER COWLING <i>new</i>	2	\$ 96.00	\$ 192.00
22	REAR FENDER INNER TRIM LH <i>Dented</i>	1	\$ 389.00	\$ 389.00
23	REAR WINDSCREEN GLASS <i>new</i>	1	\$ 986.00	\$ 986.00
24	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 121.00	\$ 121.00
25	REAR DOOR LH <i>Rep</i>	1	\$ 1,263.00	\$ 1,263.00
26	REAR DOOR INNER LOCK LH <i>2</i>	1	\$ 357.00	\$ 357.00
27	REAR DOOR OUTER STRIP LH <i>new</i>	1	\$ 173.00	\$ 173.00
28	REAR DOOR INNER TRIM LH <i>new</i>	1	\$ 542.00	\$ 542.00
29	REAR DOOR WEATHER STRIP LH	1	\$ 169.00	\$ 169.00

TO : CHINA MOTOR CLAIMS DEPTS
 VEHICLE NO : SJY7451K
 MODEL : MIT-LANCER
 DATE OF ACCIDENT : 04.05.19
 TIME OF ACCIDENT : 16:30HRS

30	REAR END PANEL <i>Dented</i>	1	\$ 467.00	\$ 467.00	✓
31	REAR END PANEL TOP GARNISH <i>selid</i>	1	\$ 144.00	\$ 144.00	✓
32	REAR FLOOR PANEL TOP BOARD <i>ton</i>	1	\$ 155.00	\$ 155.00	✓

5189
4670.10

TOTAL PRICE \$ 10,623.00
 LESS 10% \$ 1,062.30
 SUB TOTAL PRICE \$ 9,560.70

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>an</i>	1	\$ 50.00	\$ 50.00	30
3	TAIL LAMP CLIP (SET) <i>an</i>	1	\$ 30.00	\$ 30.00	10
4	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
5	BOOT LID EMBLEM 'C&C' (SPECIAL TYPE) <i>an</i>	1	\$ 120.00	\$ 120.00	45
6	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>an</i>	1	\$ 80.00	\$ 80.00	30
8	REAR WINDSCREEN SEALANT <i>3 an</i>	1	\$ 80.00	\$ 80.00	40
9	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	40
10	REAR WINDSCREEN GLASS SOLAR FILM <i>new</i>	1	\$ 550.00	\$ 550.00	+
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>an</i>	1	\$ 50.00	\$ 50.00	10
12	REAR END PANEL INSULATION SEAL <i>an</i>	1	\$ 150.00	\$ 150.00	60
13	REVERSE SENSOR <i>Dented</i>	1	\$ 220.00	\$ 220.00	200

465

\$ 1,540.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, GRAZE, KNOCK STRAIGHTEN, ADJUST AFFECTED PARTS	\$ 1,600.00	1200
2	TO PUTTY, SPRAY PAINT POLISH, WAX	\$ 1,600.00	1100
3	TO SPRAY TUFF COAT	\$ 250.00	60
4	WIRING, BULB CHECKING	\$ 120.00	30
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	80
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	+
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50

TO : CHINA MOTOR CLAIMS DEPTS
 VEHICLE NO : SJY7451K
 MODEL : MIT-LANCER
 DATE OF ACCIDENT : 04.05.19
 TIME OF ACCIDENT : 16:30HRS

8	TRANSFER BOOTLID MECHANISM	\$ 80.00	x
9	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	✓
10	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,540.00

2720

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,100.70
 TOTAL LABOUR COST : \$ 4,540.00
 TOTAL REPAIR COST : \$ 15,640.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian King
 v/s 06/05/19.

199 Days.

total: 7435.10.
 v/s: 5.9K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: