



Section A - Accident Details

Registration Number	SHC4747S
Case Reference Number	TAX/05/19/2026
Registration Date	19/2/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOHAMED AMANULLAH BIN PEER MOHAMED
Type of Accident	Head To Side
Accident Date and Time	6/5/2019 11:45 AM
Accident Reported Date and Time	6/5/2019 1:09 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101383
Special Instruction to ARC, if any	TP
Prepared Date and Time	7/5/2019 11:34 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,683.00	\$600.00
Total Spray Cost	\$2,630.00	\$860.00
Total Spare Part Cost	\$17,813.25	\$5,022.72
Total Other Cost	\$1,540.00	(\$1,032.72)
TOTAL COST	\$23,666.25	\$5,450.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	6.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / NTUC
ARC / Surveyor Sign Off Date	07/05/2019 3:09 PM	07/05/2019 4:22 PM
Signature		
Remarks	SUPPLEMENTARY = 2 DAYS	LUMP SUM REPAIR 4 DAYS CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0051	Invoice Number	
Quotation Date	04.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE AND REPLACE SUPPORT PANEL	\$300.00	\$100.00
TO REPAIR FRONT FENDER LH	\$200.00	\$100.00
TO REPAIR FRONT PORTION	\$1,183.00	\$400.00
Total Labour	\$1,683.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$80.00
TO RESPRAY FRONT CHASSIS	\$200.00	\$100.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$80.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,630.00	\$860.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$1,362.72)
TO ALIGN CHASSIS	\$350.00	\$150.00
TO TOP UP A/C GAS	\$120.00	\$30.00
TO REMOVE AND REFIT ENGINE MOUNTING	\$150.00	\$50.00
TO REMOVE & REFIT AIR-CON CONDENSER	\$120.00	\$50.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
TO REMOVE & REFIT FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,540.00	(\$1,032.72)

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655562
Estimator Telephone Number : 68602623
Accident Reporting Number : 88502672

Date Generated : 07/10/2019

User ID : PohSuan

55708-47101	WIPER GARNISH	0.00	\$614.00	0.00	\$0.00	Replace	Not Given	X
55084-47011	WIPER GARNISH COVER, LH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
55083-47011	WIPER GARNISH COVER, RH	0.00	\$23.80	0.00	\$0.00	Replace	Not Given	X
53510-47102	HOOD LOCK	0.00	\$128.90	0.00	\$0.00	Replace	Not Given	X
53630-47050	CABLE ASSY, HOOD	0.00	\$52.20	0.00	\$0.00	Replace	Not Given	X
53557-47010	HOOD AUXILIARY CATCH	0.00	\$8.60	0.00	\$0.00	Replace	Not Given	X
53614-47030	CLAMP, HOOD LOCK	0.00	\$5.90	0.00	\$0.00	Replace	Not Given	X
86510-28130	HORN ASSY, HIGH	0.00	\$110.40	0.00	\$0.00	Replace	Check	X
86520-28180	HORN ASSY, LOW	0.00	\$110.40	0.00	\$0.00	Replace	Check	X
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X
81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given	X
81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	X
88480-47150	A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Check	X
G9010-47031	RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Check	X
G9225-47021	HOSE, INVERTER NO.1	0.00	\$80.00	0.00	\$0.00	Replace	Check	X
G9229-47020	HOSE, INVERTER COOLING NO.5	0.00	\$125.30	0.00	\$0.00	Replace	Check	X
16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Check	X
16523-21050	CUSHION, RADIATOR	0.00	\$11.30	0.00	\$0.00	Replace	Check	X
16534-37010	SUPPORT, RADIATOR, LH	0.00	\$17.70	0.00	\$0.00	Replace	Check	X
16533-28051	SUPPORT, RADIATOR, RH	0.00	\$54.50	0.00	\$0.00	Replace	Check	X
16535-20030	SUPPORT, RADIATOR,	0.00	\$18.50	0.00	\$0.00	Replace	Check	X
16572-37120	RADIATOR HOSE LOWER	0.00	\$42.40	0.00	\$0.00	Replace	Check	X
16571-37140	RADIATOR TOP HOSE NO 1	0.00	\$42.40	0.00	\$0.00	Replace	Check	X
16261-37070	RADIATOR HOSE, BYPASS NO.1	0.00	\$37.20	0.00	\$0.00	Replace	Check	X
16264-37080	RADIATOR HOSE, BYPASS NO.2	0.00	\$29.00	0.00	\$0.00	Replace	Check	X
16267-37030	RADIATOR HOSE, BYPASS NO.3	0.00	\$37.20	0.00	\$0.00	Replace	Check	X
16281-37030	RADIATOR HOSE, BYPASS NO.4	0.00	\$37.20	0.00	\$0.00	Replace	Check	X
	COOLANT	0.00	\$12.32	0.00	\$0.00	Replace	Check	X
16711-37040	FAN SHROUD	0.00	\$244.50	0.00	\$0.00	Replace	Check	X
16712-37030	FAN SHROUD TOP	0.00	\$99.60	0.00	\$0.00	Replace	Check	X
16361-37010	FAN BLADE	0.00	\$156.60	0.00	\$0.00	Replace	Check	X
16361-28360	FAN BLADE NO 2	0.00	\$204.20	0.00	\$0.00	Replace	Check	X
16363-37010	FAN MOTOR NO 1	0.00	\$538.30	0.00	\$0.00	Replace	Check	X
16363-37020	FAN MOTOR NO 2	0.00	\$538.30	0.00	\$0.00	Replace	Check	X
53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X
53851-47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X
53802-47050	FENDER FRT/LH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X

SVC

SVC

SVC

NN

SVC

NN

	53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
	53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
Total				\$19,142.83		\$2,169.36			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52021-47023	BUMPER REINFORCEMENT FRT	1.00	\$498.40	25.00	\$373.80	Replace	Replace
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	1.00	\$250.40	25.00	\$187.80	Replace	Replace
		53294-47030	DEFLECTOR, RADIATOR LH	1.00	\$77.00	25.00	\$57.75	Replace	Replace
		52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace
		81210-12230	FOG LAMP RH	1.00	\$295.20	10.00	\$265.68	Replace	Replace
		53111-47040	GRILLE, RADIATOR	1.00	\$310.60	25.00	\$232.95	Replace	Replace
		53113-47040	GRILLE RADIATOR LOWER NO.2	1.00	\$94.60	25.00	\$70.95	Replace	Replace
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$127.70	25.00	\$95.78	Replace	Replace
		53420-47070	HOOD HINGE LH	1.00	\$55.90	25.00	\$41.93	Replace	Replace
		53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	25.00	\$1,095.30	Replace	Replace
			COOLANT	1.00	\$12.32	0.00	\$12.32	Replace	Replace
		12361-37090	ENGINE MOUNTING FRT	1.00	\$198.00	25.00	\$148.50	Replace	Replace
Total					3,741.32		2,853.36		

$$\begin{array}{r}
 5022.72 \\
 + 600.00 \\
 + 1210.00 \\
 \hline
 6832.72 \\
 - 20\% \\
 \hline
 5466.176 \\
 \hline
 \$5,450.00
 \end{array}$$

/6 DAYS.

FINALIZED LUMP SUM REPAIR \$5,450.00/6 DAYS.