

pol kin



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJZ7846A

Ashok Singhania

2 Harlyn Road
Singapore 299441

Mobile: 98236867

Vehicle & Document Information

WIP No 33161
Reg No/Reg Date SJZ7846A / 28/12/2010
Date In/Mileage / 0
Chassis No WDD2120472A343578
Engine No 27186030149047
Make/Model MB/E 250 CGI SEDAN (W212)
Colour/Trim 024 497 Cuprite Bro/ 042 205 Leather Bla

| Account No | Terms | Date/Time Printed | CSE | Operator | | | | |
|------------------------------------------------------------------------|-------|-------------------|-----|------------------------|------|------------|-------|-------------|
| CSM00128 | Cash | 07/05/2019/ 11:27 | AQ | 305 / Alan Quek Ai Lun | | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M BPNSUN | | | | | | | | |
| POLICY NO/ACC DATE : 2100242224 // 06-05-2019 | | | | | | | | |
| DRIVE IN: 06-05-2019 // TP CAR NO: SLE3393C (AXA INSURANCE) | | | | | | | | |
| DATE IN/DATE SURVEY: | | | | | | | | |
| BY/AUTHORIZED ON : | | | | | | | | |
| A BPILAB | | | | | | | 0.10 | 380.00 |
| USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO | | | | | | | | |
| STANDARD SETTINGS.NETT | | | | | | | | 960 1440.00 |
| A BPILAB | | | | | | | | |
| REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT | | | | | | | | 600 720.00 |
| ASSY COMPONENTS & REFINISH. | | | | | | | | xm 120.00 |
| A BPIRES | | | | | | | | |
| RESPRAY REAR BUMPER | | | | | | | | |
| A BPILAB | | | | | | | | |
| CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT | | | | | | | | |
| M RH/R TAIL LAMP | xsu | | | | 1.00 | 712.05 | 00.00 | 712.05 |
| M REAR BUMPER | de | | | | 1.00 | 1634.76 | 00.00 | 1634.76 |
| M LH/R BUMPER GARNISH | xsu | | | | 1.00 | 132.65 | 00.00 | 132.65 |
| M RH/R BUMPER GARNISH | xsu | | | | 1.00 | 132.65 | 00.00 | 132.65 |
| M CT/R BUMPER GARNISH | xsu | | | | 1.00 | 178.58 | 00.00 | 178.58 |
| M LH/R BOTTOM BRACKET | xsu | | | | 1.00 | 16.75 | 00.00 | 16.75 |
| M RH/R BOTTOM BRACKET | xsu | | | | 1.00 | 16.75 | 00.00 | 16.75 |
| M REAR PARKING SENSOR | xsu | | | | 4.00 | 281.99 | 00.00 | 1127.96 |
| M REAR PARKING SENSOR SEAL | xsu | | | | 4.00 | 7.18 | 00.00 | 28.72 |
| M REAR CROSS MEMBER | xsu | | | | 1.00 | 817.08 | 00.00 | 817.08 |

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on 7457.95

Total Payable 7,980.01

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJZ7846A

Finalization

Ashok Singhanian

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Rasul

Vehicle & Document Information
WIP No 33161
Reg No/Reg Date SJZ7846A / 28/12/2010
Date In/Mileage 10/06/2019 / 79825
Chassis No WDD2120472A343578
Engine No 27186030149047
Make/Model MB/E 250 CGI SEDAN (W212)
Colour/Trim 024 497 Cuprite Bro/ 042 205 Leather Bla

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|-------|-------------------|-----|------------------------|
| CSI00001 | Cash | 25/06/2019/ 09:45 | AQ | 305 / Alan Quek Ai Lun |

M BPNSUN

POLICY NO/ACC DATE : 21000242224 // 06-05-2019
DRIVE IN: 06-05-2019 // TP CAR NO: SLE3393C (AXA INSURANCE)
DATE IN/DATE SURVEY: 10-06-2019 // LKK RASUL
BY/AUTHORIZED ON : VIC ALPEH // 29-05-2019

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT
ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY REAR BUMPER

X REAR BUMPER

X LH/R BUMPER GARNISH

X RH/R BUMPER GARNISH

X CT/R BUMPER GARNISH

X REAR PARKING SENSOR SEAL

3D
ESTIMATE

0.10 380.00✓

960.00✓

600.00✓

| | | | |
|------|---------|-------|----------|
| 1.00 | 1634.76 | 00.00 | 1634.76✓ |
| 1.00 | 132.65 | 00.00 | 132.65✓ |
| 1.00 | 132.65 | 00.00 | 132.65✓ |
| 1.00 | 178.58 | 00.00 | 178.58✓ |
| 4.00 | 7.18 | 00.00 | 28.72✓ |

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

| | |
|---------------|----------|
| Nett | 4,047.36 |
| 7% GST on | 4047.36 |
| Total Payable | 4,330.68 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg