



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJZ7846A

Ashok Singhania

2 Harlyn Road
Singapore 299441

Mobile: 98236867

Vehicle & Document Information

WIP No **33161**
Reg No/Reg Date **SJZ7846A / 28/12/2010**
Date In/Mileage **/ 0**
Chassis No **WDD2120472A343578**
Engine No **27186030149047**
Make/Model **MB/E 250 CGI SEDAN (W212)**
Colour/Trim **024 497 Cuprite Bro/ 042 205 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	07/05/2019/ 11:27	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :2100242224 // 06-05-2019 DRIVE IN:06-05-2019 // TP CAR NO:SLE3393C (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960 1440.00
A BPIRES RESPRAY REAR BUMPER				600 720.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				120.00
M RH/R TAIL LAMP <i>de?</i>	1.00	712.05	00.00	712.05
M REAR BUMPER <i>de</i>	1.00	1634.76	00.00	1634.76
M LH/R BUMPER GARNISH <i>de</i>	1.00	132.65	00.00	132.65
M RH/R BUMPER GARNISH <i>de</i>	1.00	132.65	00.00	132.65
M CT/R BUMPER GARNISH <i>de</i>	1.00	178.58	00.00	178.58
M LH/R BOTTOM BRACKET <i>de</i>	1.00	16.75	00.00	16.75
M RH/R BOTTOM BRACKET <i>de</i>	1.00	16.75	00.00	16.75
M REAR PARKING SENSOR <i>de</i>	4.00	281.99	00.00	1127.96
M REAR PARKING SENSOR SEAL <i>de</i>	4.00	7.18	00.00	28.72
M REAR CROSS MEMBER <i>de</i>	1.00	817.08	00.00	817.08

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 7,457.95
7% GST on 7457.95 522.06
Total Payable 7,980.01

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg