



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SJZ7846A

Ashok Singhanian

2 Harlyn Road  
Singapore 299441

Mobile: 98236867

### Vehicle & Document Information

WIP No **33161**  
Reg No/Reg Date **SJZ7846A / 28/12/2010**  
Date In/Mileage **0**  
Chassis No **WDD2120472A343578**  
Engine No **27186030149047**  
Make/Model **MB/E 250 CGI SEDAN (W212)**  
Colour/Trim **024 497 Cuprite Bro/ 042 205 Leather Bla**

| Account No | Terms | Date/Time Printed | CSE | Operator               |
|------------|-------|-------------------|-----|------------------------|
| CSM00128   | Cash  | 07/05/2019/ 11:27 | AQ  | 305 / Alan Quek Ai Lun |

| Description of Goods / Services  | Qty  | Unit Price | Disc% | Amount  |
|--|------|------------|-------|---------|
| M BPNSUN<br>POLICY NO/ACC DATE : 2100242224 // 06-05-2019<br>DRIVE IN: 06-05-2019 // TP CAR NO: SLE3393C (AXA INSURANCE)<br>DATE IN/DATE SURVEY:<br>BY/AUTHORIZED ON : |      |            |       |         |
| A BPILAB<br>USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO<br>STANDARD SETTINGS.NETT  |      |            | 0.10  | 380.00  |
| A BPILAB<br>REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT<br>ASSY COMPONENTS & REFINISH.  |      |            |       | 1440.00 |
| A BPIRES<br>RESpray REAR BUMPER  |      |            |       | 720.00  |
| A BPILAB<br>CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT   |      |            |       | 120.00  |
| M RH/R TAIL LAMP   | 1.00 | 712.05     | 00.00 | 712.05  |
| M REAR BUMPER  | 1.00 | 1634.76    | 00.00 | 1634.76 |
| M LH/R BUMPER GARNISH  | 1.00 | 132.65     | 00.00 | 132.65  |
| M RH/R BUMPER GARNISH  | 1.00 | 132.65     | 00.00 | 132.65  |
| M CT/R BUMPER GARNISH  | 1.00 | 178.58     | 00.00 | 178.58  |
| M LH/R BOTTOM BRACKET  | 1.00 | 16.75      | 00.00 | 16.75   |
| M RH/R BOTTOM BRACKET  | 1.00 | 16.75      | 00.00 | 16.75   |
| M REAR PARKING SENSOR  | 4.00 | 281.99     | 00.00 | 1127.96 |
| M REAR PARKING SENSOR SEAL   | 4.00 | 7.18       | 00.00 | 28.72   |
| M REAR CROSS MEMBER  | 1.00 | 817.08     | 00.00 | 817.08  |

**Alan Quek**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **7,457.95**  
7% GST on **7457.95** **522.06**

Authorized signatory and company stamp

**Total Payable 7,980.01**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

