

Tanfer

III

8051/119

ASSIGNMENT

2015 July

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 Transport Vehicle No.: _____
 at Workshop no.: **Trans - Eurocam**
 of _____
 Insured: _____
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____
 (Claims Payout): _____
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. of Market Value: **\$160K.**
 IDAG Accident Report: _____
 CIRA / PIR Seen: _____
 Est. Repairs: **17 days** Res.: Yes or No
 Lump Sum: **2000** % Val: Yes or No
 CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKV3130S** Yt Regn: **2015 July**
 Type: **Car** / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Mazda 3** CC: **1496**
 Colour: **Bronze** A/C: Insured / Std / NI / NA
 Sp. Heading: **47065** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/Nr: **SM6BM42A86703/40 G5**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Mod: **Nil** / STD / RIM / STD / RIM or
 Tyre Size: F: **205/60R16**
 R: **205/60R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: **6** mm Rear: **6** mm
 R/Ral: **6** mm L/Ral: **6** mm
 D.O.A. **7/5/19 @ 350pm**
 Survey held at: **Eurocam**

Des. of Damages: **Front** / Rear / OIS / NIS / UIC / Rooftop or
Front o/s, f+w/s
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: **8/5/19** Action / Instruction: **Repair limit \$16K. \$17K. msg w/s. Survey. Rebate: \$43,516**

MV: **\$16K** UIC: **\$17K** [Red = \$20,547.64 / 55%]
 Rebate: **\$43,516**
 NV: **\$17,484**

*. **7 repair days + 2 sundays + 2 PPS + 1 PH + 2 sat = 23 days.**

End Time: File Place in? ☐ : Prel. Report
☐ : Final Report

Days Of Repair:
 Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation:
 Other:
 Other:

Report Format:
 Lump Sum / L.D.K (\$)



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Lo Yi Ling ADDRESS : 18 Lorong K Telok Karau #03-13 Singapore 425781 TEL : 85334733		WIP : 40694 EXCESS : DATE: 6-May-19	
VEH NO :	SKV3130S	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BM42A8G0314065	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	28-Jul-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	FRT BUMPER	1	MBHR3-50-0318BB	all	\$ 1,083.30
2	RETAINER RHS	1	MBHN1-50-0T1F	new	\$ 19.70
3	BRACKET RHS	1	MBHN1-50-152	new	\$ 15.90
4	CHROME RHS, FOGLAMP	1	MBJE1-50-C12	new	\$ 112.10
5	COVER RHS, FOGLAMP	1	MBJE1-50-C11A	new	\$ 48.80
6	FRONT REINFORCEMENT	1	MB45A-50-070A	new	\$ 466.80
7	STIFF'A', FRONT BUMPER	1	MBHN1-50-050B	new	\$ 87.90
8	CORD SHORT RHS, FOGLAMP	1	MBHN9-67-290	new	\$ 39.20
9	FASTENER, FRONT BUMPER	2	MB45A-56-146A	new	\$ 6.00
10	CLIP, FRONT BUMPER	12	MC274-50-133	new	\$ 44.40
11	GROMMET, FRONT BUMPER	2	MGHP9-50-025	new	\$ 5.80
12	RIVET, FRONT BUMPER	6	M5515-51-833	new	\$ 24.00
13	RIVET, FRONT BUMPER	4	MTK21-50-355	new	\$ 36.80
14	GRILLE TOP	1	MBHN1-50-033 53	new	\$ 351.80
15	BRACKET TOP, GRILLE	1	MBHN1-50-717D	new	\$ 107.60
16	FASTENER, GRILLE	8	MGD7A-50-EA1	new	\$ 25.60
17	CHROME RHS	1	MBHN1-50-711A	new	\$ 185.60
18	BRACKET RHS, FRONT GRILLE	1	MBHN1-50-153	new	\$ 15.90
19	RIVET, FRONT GRILLE	2	MEA01-50-037	new	\$ 16.00
20	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A	new	\$ 5.80
21	GROMMET, FRONT GRILLE	2	MKD45-50-E51	new	\$ 5.80
22	FRONT PANEL UPPER	1	MB45A-53-150A	new	\$ 130.20
23	FRONT SUPPORT PANEL	1	MGHR5-53-110B	new	\$ 493.20
24	PLATE SEAL RHS	1	MBHN1-50-1U1A	new	\$ 37.40
25	FASTENER, PLATE SEAL	4	MKD45-50-EA1	new	\$ 10.80
26	PLATE SET, FRONT REINFORCEMENT	1	MBHN3-50-1C0	new	\$ 97.40
27	FASTENER, PLATE SET	4	MGD7A-50-EA1	new	\$ 12.80
28	BONNET	1	MBHY0-52-31XA	new	\$ 1,120.70
29	HINGE LHS, BONNET	1	MB45A-52-420A	new	\$ 43.10

30	HINGE RHS, BONNET	1	MB45A-52-410A	ht	\$ 43.10
31	WEATHERSTRIP, BONNET	1	MBHN9-56-770A	wt	\$ 66.80
32	FRONT FENDER RHS	1	MB45A-52-111B	ht	\$ 350.60
33	STAY RHS, FENDER	1	MB4YA-52-10Y	ht	\$ 41.90
34	MUDGUARD RHS	1	MB45A-56-130H	de	\$ 101.90
35	FASTENER, MUDGUARD	15	MB45A-56-146A	wt	\$ 45.00
36	HEADLAMP LHS	1	MBHT6-51-041A	Xun	\$ 2,357.30
37	HEADLAMP RHS	1	MBHT6-51-031A	wt	\$ 2,357.30
38	HID CONTROL UNIT	1	MBHN3-51-0H3	Xun	\$ 394.80
39	GASKET, CONTROL UNIT	1	MC236-51-0B2	Xun	\$ 14.30
40	CLIP, HEADLAMP	4	MFB01-50-133C	wt	\$ 16.00
41	RIVET, HEADLAMP	2	MB092-51-833	wt	\$ 7.00
42	LAMP RHS, SIDE TURN	1	MB45A-51-350A	wt	\$ 165.20
43	FOGLAMP RHS	1	MTK21-51-680A	wt	\$ 369.00
44	BRACKET RHS, FOGLAMP	1	MBHR1-51-684A	dis	\$ 18.20
45	SCREW, FOGLAMP	6	M9986-50-516	wt	\$ 7.20
46	WASHER TANK	1	MGHP9-67-481A	de	\$ 109.20
47	SWITCH LEVEL, WASHER PUMP	1	MKD35-67-488	wt	\$ 118.50
48	GROMMET, WASHER TANK	1	MKD37-67-491	wt	\$ 14.70
49	FUNNEL, WASHER TANK	1	MBHN9-67-484	Xun	\$ 58.80
50	GROMMET, WASHER TANK	1	MKD35-67-491	wt	\$ 6.20
51	PIPE, WASHER TANK	1	MBHN9-67-500	Xun	\$ 18.40
52	HEADLAMP PANEL RHS	1	MB45A-53-140	Xun	\$ 156.50
53	ABS PUMP	1	MB4Y2-43-7A0C	Xun	\$ 1,818.30
54	BRACKET, ABS PUMP	1	MB45A-43-310	Xun	\$ 28.20
55	FRONT WHEEL RIM RHS	1	M9965-D0-6560	wt	\$ 722.30
56	FRONT BEARING RHS	1	MB45A-33-04X	?	\$ 568.80
57	FRONT KNUCKLE RHS	1	MB45A-33-021	?	\$ 402.60
58	FRONT DAMPER RHS	1	MBHS2-34-700A	?	\$ 360.80
59	RUB MTG TOP, FRONT DAMPER	1	MKD35-34-380C	?	\$ 96.50
60	BEARING TOP, FRONT DAMPER	1	MB45A-34-38XA	?	\$ 55.80
61	FRONT LOWER ARM RHS	1	MB60S-34-300G	?	\$ 454.70
62	FRONT LINK ROD RHS	1	MB45A-34-150	?	\$ 68.00
63	FRONT HARNESS	1	MBLF4-67-010C	wt	\$ 5,446.30
64	RADIATOR COOLANT	5		wt	\$ 68.50
	* Socket cover RH, Headlamp wt				
	* Pipe, Headlamp washer de				
	* Cover RHS, headlamp washer dis				
	* Actuator RH, headlamp washer dis				
TOTAL PARTS					\$ 21,579.10
LESS 10%					\$ 2,157.91
TOTAL PARTS COST					\$ 19,421.19
Labour Description					
1	M2-BR-FRONT6	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.		2310 660	\$ 2,640.00

2		TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH, FRONT FENDER RH, FRONT DOOR RH. <i>630</i>	<i>2835</i>	\$ 3,780.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	NETT ✓	\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	<i>530</i> NETT	\$ 630.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	<i>m</i> NETT X	\$ 70.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	<i>m</i> X	\$ 350.00
7		TO REMOVE AND REPLACE ABS PUMP, PIPING AND CHECK LEAK.	<i>m</i> NETT X	\$ 990.00
8		TO CONDUCT BRAKE SYSTEM CHECKING USING SPECIFIC BRAKING TEST MACHINE.	<i>m</i> NETT X	\$ 560.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>150.</i>	\$ 250.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>150.</i>	\$ 250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>180.</i>	\$ 350.00
12	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>invoice</i> ✓	NETT	\$ 120.00
13	MZ-BR-SUNDRI	SUNDRIES. <i>her 30</i>	NETT	\$ 100.00

* balancing \$1200 ✓
 * wheel alignment \$560.00 ✓
 * Front tyre RH \$300.00 out 80% ✓

TOTAL LABOUR	\$ -	\$ 10,750.00
TOTAL PARTS	\$ -	\$ 19,421.19
TOTAL	\$ -	\$ 30,171.19
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400 WILL BE APPLIED**, ACCORDINGLY FOR MAN HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TRANS EUROKARS PTE LTD

Tayfun 97495749
 'wp' 7/5/19 e3supr
 Resurvey before paint

Authorised Signature

sue (Mantrose)
 17 days
 suv

SUPPLEMENTARY ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L		NAME : Ms Lo Yi Ling		WIP : 40694	
64 CECIL STREET		ADDRESS : 18 Lorong K Telok Karau		EXCESS :	
#04-#05 IOB BUILDING		#03-13		DATE: 6-May-19	
SINGAPORE 049711		Singapore 425781			
ATTN : MOTOR CLAIMS		TEL : 85334733			
FAX :					
VEH NO :	SKV3130S	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BM42A8G0314065	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	28-Jul-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	SOCKET COVER RHS, HEADLAMP	1	MCS14-51-0A1A	out /	\$ 23.50
2	PIPE, HEADLAMP WASHER	1	MBHT4-51-4J0	de /	\$ 128.90
3	COVER RHS, HEADLAMP WASHER	1	MBHT4-51-8G1 53	dis /	\$ 89.40
4	CLAMP, ACTUATOR	1	MTK33-51-829	re /	\$ 17.30
5	ACTUATOR RHS	1	MBHT4-51-82X	dis /	\$ 254.60
6	FRONT CROSSMEMBER	1	MB45A-34-80X	bt /	\$ 1,880.60
7	PUMP, WASHER TANK	1	MKD53-51-811	de /	\$ 499.80
8	STOPPER, FRONT DAMEPR	1	MB45G-34-111	re /	\$ 46.40
		17311.90	TOTAL PARTS	\$ -	\$ 2,940.50
		10% 15580.71	LESS 10%	\$ -	\$ 294.05
		11475	TOTAL PARTS COST	\$ -	\$ 2,646.45
		27025.71			
45917.00 Labour Description					
1	MZ-BR-HARNES	TO MOUNT VEHICLE ON CAR O LINER AND RE-ALIGN CAR BODY ACCORDING MAZDA SPECIFICATION.		/ NETT	\$ 1,500.00
2		TO SUPPLY 1 PC TIRE.		out / NETT	\$ 240.00
3	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.		/ NETT	\$ 120.00
4	MZ-BR-CROSS1	TO REPLACE CROSSMEMBER ASSY.		/ NETT	\$ 990.00
5	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		/ NETT	\$ 560.00
6	MZ-BR-ENGINE	TO REMOVE & INSTALL ENGINE ASSY FOR ACCESS.		/ NETT	\$ 1,320.00
				TOTAL LABOUR	\$ - \$ 4,730.00



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L		NAME :	Ms Lo Yi Ling	WIP :	40694
64 CECIL STREET		ADDRESS :	18 Lorong K Telok Karau	EXCESS :	
#04-#05 IOB BUILDING			#03-13	DATE:	6-May-19
SINGAPORE 049711			Singapore 425781		
ATTN. :	MOTOR CLAIMS	TEL :	85334733		
FAX :					
VEH NO :	SKV31305	DATE IN :		CONTACT PERSON :	Vlon 63957877
CHASSIS NO :	JM6BM42ABG0314D65	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	28-Jul-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	FRT BUMPER old	1	MBHR3-50-0318BB \$ 1,083.30
2	RETAINER RHS	1	MBHN1-50-0T1F \$ 19.70
3	BRACKET RHS	1	MBHN1-50-152 \$ 15.90
4	CHROME RHS, FOGLAMP	1	MBJE1-50-C12 \$ 112.10
5	COVER RHS, FOGLAMP	1	MBJE1-50-C11A \$ 48.80
6	FRONT REINFORCEMENT	1	MB45A-50-070A \$ 466.80
7	STIFF'A', FRONT BUMPER	1	MBHN1-50-050B \$ 87.90
8	CORD SHORT RHS, FOGLAMP	1	MBHN9-67-290 \$ 39.20
9	FASTENER, FRONT BUMPER	2	MB45A-56-146A \$ 6.00
10	CLIP, FRONT BUMPER	12	MC274-50-133 \$ 44.40
11	GROMMET, FRONT BUMPER	2	MGHP9-50-025 \$ 5.80
12	RIVET, FRONT BUMPER	6	M5515-51-833 \$ 24.00
13	RIVET, FRONT BUMPER	4	MTY1-50-355 \$ 36.80
14	GRILLE TOP	1	MBHN1-50-033 53 \$ 351.80
15	BRACKET TOP, GRILLE	1	MBHN1-50-717D \$ 107.60
16	FASTENER, GRILLE	8	MGD7A-50-EA1 \$ 25.60
17	CHROME RHS	1	MBHN1-50-7J1A \$ 185.60
18	BRACKET RHS, FRONT GRILLE	1	MBHN1-50-153 \$ 15.90
19	RIVET, FRONT GRILLE	2	MEA01-50-037 \$ 16.00
20	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A \$ 5.80
21	GROMMET, FRONT GRILLE	2	MKD45-50-E51 \$ 5.80
22	FRONT PANEL UPPER	1	MB45A-53-150A \$ 130.20
23	FRONT SUPPORT PANEL	1	MGHR5-53-110B \$ 493.20
24	PLATE SEAL RHS	1	MBHN1-50-1U1A \$ 37.40
25	FASTENER, PLATE SEAL	4	MKD45-50-EA1 \$ 10.80
26	PLATE SET, FRONT REINFORCEMENT	1	MBHN3-50-1C0 \$ 97.40
27	FASTENER, PLATE SET	4	MGD7A-50-EA1 \$ 12.80
28	BONNET	1	MBHY0-52-31XA \$ 1,120.70
29	HINGE LHS, BONNET	1	MB45A-52-420A \$ 43.10

\$37,547.64

30	HINGE RHS, BONNET	1	MB45A-52-410A	bt	\$ 43.10
31	WEATHERSTRIP, BONNET	1	MBHN9-56-770A	cut	\$ 66.80
32	FRONT FENDER RHS	1	MB45A-52-111B	bt	\$ 350.60
33	STAY RHS, FENDER	1	MB4YA-52-10Y	bt	\$ 41.90
34	MUDGUARD RHS	1	MB45A-56-130H	de	\$ 101.90
35	FASTENER, MUDGUARD	15	MB45A-56-146A	de	\$ 45.00
36	HEADLAMP LHS	1	MBHT6-51-041A	?	\$ 2,357.30
37	HEADLAMP RHS	1	MBHT6-51-031A	cut	\$ 2,357.30
38	HID CONTROL UNIT	1	MBHN3-51-0H3	?	\$ 394.80
39	GASKET, CONTROL UNIT	1	MC236-51-0B2	?	\$ 14.30
40	CLIP, HEADLAMP	4	MF801-50-133C	de	\$ 16.00
41	RIVET, HEADLAMP	2	MB092-51-833	de	\$ 7.00
42	LAMP RHS, SIDE TURN	1	MB45A-51-350A	cut	\$ 165.20
43	FOGLAMP RHS	1	MTK21-51-680A	cut	\$ 369.00
44	BRACKET RHS, FOGLAMP	1	MBHR1-51-684A	dis	\$ 18.20
45	SCREW, FOGLAMP	6	M9986-50-516	de	\$ 7.20
46	WASHER TANK	1	MGHP9-67-481A	de	\$ 109.20
47	SWITCH LEVEL, WASHER PUMP	1	MKD35-67-488	cut	\$ 118.50
48	GROMMET, WASHER TANK	1	MKD37-67-491	de	\$ 14.70
49	FUNNEL, WASHER TANK	1	MBHNS-67-484	?	\$ 58.80
50	GROMMET, WASHER TANK	1	MKD35-67-491	de	\$ 6.20
51	PIPE, WASHER TANK	1	MBHN9-67-500	X	\$ 18.40
52	HEADLAMP PANEL RHS	1	MB45A-53-140	dis	\$ 156.50
53	ABS PUMP	1	MB4Y2-43-7A0C	?	\$ 1,818.30
54	BRACKET, ABS PUMP	1	MB45A-43-310	?	\$ 28.20
55	FRONT WHEEL RIM RHS	1	M9965-D0-6560	cut	\$ 722.30
56	FRONT BEARING RHS	1	MB45A-33-04X	?	\$ 568.80
57	FRONT KNUCKLE RHS	1	MB45A-33-021	?	\$ 402.60
58	FRONT DAMPER RHS	1	MBHS2-34-700A	?	\$ 360.80
59	RUB MTG TOP, FRONT DAMPER	1	MKD35-34-380C	?	\$ 96.50
60	BEARING TOP, FRONT DAMPER	1	MB45A-34-38XA	?	\$ 55.80
61	FRONT LOWER ARM RHS	1	MB605-34-300G	?	\$ 454.70
62	FRONT LINK ROD RHS	1	MB45A-34-150	?	\$ 68.00
63	FRONT HARNESS	1	MBLF4-67-010C	cut	\$ 5,446.30
64	RADIATOR COOLANT	5		de	\$ 68.50
#	Socket over RH, headlamp cut				
#	Pipe, Headlamp washer de				
#	Color RHS, headlamp washer dis				
#	Actuator RH, headlamp washer dis				
TOTAL PARTS					\$ 21,579.10
LESS 10%					\$ 2,157.91
TOTAL PARTS COST					\$ 19,421.19
Labour Description					
1	MZ-BR-FRONT6	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			
				2310	\$ 2,640.00
				660	

2		TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH, FRONT FENDER RH, FRONT DOOR RH. <i>630</i>	2835	\$ 3,780.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	NETT ✓	\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	<i>330</i> NETT	\$ 630.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT X	\$ 70.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
7		TO REMOVE AND REPLACE ABS PUMP, PIPING AND CHECK LEAK.	NETT ?	\$ 990.00
8		TO CONDUCT BRAKE SYSTEM CHECKING USING SPECIFIC BRAKING TEST MACHINE.	NETT ?	\$ 560.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150.	\$ 250.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
12	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>invoice ?</i>	NETT	\$ 120.00
13	MZ-BR-SUNDRI	SUNDRIES. <i>30</i>	NETT	\$ 100.00

* balancing \$120.00 ✓
 * wheel alignment \$560.00 ✓
 * front tyre RH \$300.00 cut 80% ✓

TOTAL LABOUR	\$ -	\$ 10,750.00
TOTAL PARTS	\$ -	\$ 19,421.19
TOTAL	\$ -	\$ 30,171.19
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Tayfun 97495749
 'wp' 7/5/19 e 350pm
 Resung before paint

Authorised Signature

sure (handwritten)

11 days

sure 17 days

TOTAL PARTS	\$ -	\$ 2,646.45
TOTAL	\$ -	\$ 7,376.45
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Vehicle Ident no.

Repair order no.
R000495Technician
NG EE SENGDate
31.5.19License plate no.
SKV3130S

First reg. date

Model

Odometer reading: km/miles

Mazda : Mazda3 : 2013- (BM/BN) : except Rough Road
Suspension

47068

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left		-0°59' +/-1°00'	-0°59'
		right			-0°54'
		cross		0°00' +/-1°30'	-0°05'
	Toe	left		0°05' +/-0°10'	0°08'
		right			0°03'
		total		0°10' +/-0°20'	0°11'
	Geometrical driving axis			0°00' +/-0°48'	0°03'
Front axle	Camber	left		-0°12' +/-1°00'	-0°28'
		right			-1°25' *
		cross		0°00' +/-1°30'	0°57'
	Caster	left		6°29' +/-1°00'	6°10'
		right			5°09' *
		cross		0°00' +/-1°30'	1°02'
	SAI	left		14°00'	14°15'
		right			14°37'
		cross		0°00'	-0°22'
	Track differential angle	left			
		right			
	Toe	left		0°06' +/-0°10'	-0°36' *
		right			1°18' *
		total		0°11' +/-0°20'	0°42' *
	Setback			0°00'	
	Max steering lock	left steer	left	-39°24' +/-3°00'	
			right	32°12' +/-3°00'	
		right steer	left	32°12' +/-3°00'	
			right	-39°24' +/-3°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L		NAME : Ms Lo Yi Ling		WIP : 40694	
64 CECIL STREET		ADDRESS : 18 Lorong K Telok Karau		EXCESS :	
#04-#05 IOB BUILDING		#03-13		DATE: 6-May-19	
SINGAPORE 049711		Singapore 425781			
ATTN : MOTOR CLAIMS		TEL : 85334733			
FAX :					
VEH NO :	SKV3130S	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BM42A8G0314065	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	28-Jul-15	POLICY NO. :	
<u>NATURE OF WORKS</u>					
NO					REVISED
1	REPAIR SUM				\$ 17,000.00
			TOTAL		\$ 17,000.00
			GST 7%		\$ 1,190.00
			GRAND TOTAL		\$ 18,190.00

REMARKS:

17 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



AUTOSWIFT RECOVERY PTE LTD

TOW JOB WORK ORDERGST Reg No. : 19-8806389-N
Co. Reg No. : 199806389NContract : MAZ 11005

W/Order No. : T 162695

PART A: JOB DETAILS

Service Date

04/06/2019

Time Received

1412

Member / Customer's Name

MRS. Lim

Time Arrived

1445

Membership / NRIC No.

85334733/

Time Completed

1537

Contact No.

85334733/

Total Mileage

41

Vehicle Registration No.

SKV 2130C

Car Make / Model




Mazda 3

Breakdown Location

ST 11 Rd

Towed Destination

27A 79 Perimeter

NORMAL TOWING	ADDITIONAL SERVICES
☒ Straight Towing ☐ Straight Towing with King Dolly ☐ Flat Bed / Car Carrier ☐ Flat Bed / Car Carrier with King Dolly ☐ Heavy Goods Vehicle (Class 5 Towing)	☐ Multi-Storey / Basement Car Park ☐ Woodlands Checkpoint / Tuas 2nd Link ☒ Accident Towing ☐ Car Ditched / Winched Up / Crane Up ☐ Dismantle Shaft / Release Brakes
SURCHARGES / OTHERS	ROADSIDE SERVICES
☐ Sunday / Public Holiday Towing (full day) ☐ Midnight Towing (2400hrs to 0700hrs) ☐ Call Cancelled / Car Missing ☐ Standby / Waiting Time Duration : _____ ☐ AA Membership Enrolment / AA Renewal	☐ Jump Start ☐ Tyre Replacement ☐ Patch Tyre Service ☐ Repair Tyre & Returned ☐ Battery Replacement Battery Receipt No. : _____
REMARKS / COMMENTS BY TOW CREW  Tow Crew ID / Signature <u>YN18442</u> Truck No. _____ Operation Officer's Signature	
PART B: MEMBER / CUSTOMER ACKNOWLEDGEMENT 1 I authorise AutoSwift Recovery Pte Ltd to tow my vehicle to the above-mentioned workshop of my choice. 2 I have been advised to remove all valuables (handphone, laptop, parking coupons, cash cards etc) from the vehicle. 3 I understand that items left behind are at my own risk and that AutoSwift Recovery Pte Ltd will not be held responsible for any losses. 4 I accept that there may be damages to my vehicle arising from the towing operation and I will not hold AutoSwift Recovery liable for the damages. 5 Remarks : _____  Member / Customer Signature _____ Date	
PART C: WORKSHOP / AGENT DECLARATION 1 I hereby represent the company receiving the above mentioned vehicle. 2 AutoSwift Recovery Pte Ltd will not be held responsible for any damages or loss of valuables discovered while the vehicle is in our possession. 3 Remarks : _____  Workshop's Representative Signature _____ Workshop's Stamp _____ Date	

WORKSHOP COPY

Swift and Safe

AutoSwift Recovery Pte Ltd
(A wholly-owned subsidiary of AA Singapore)
 Head Office: 535 Kallang Bahru #02-08 GB Point Singapore 339351 Office: 6333 8811 Fax: 6733 5094
 Branch Office: 10 Kallang Way Singapore 340215 24 Hours Hotline: 8844 3611 Office: 6389 4261 Fax: 6473 4996



Without Prejudice
to Injury Claim

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
repairers my/our vehicle No: SKV31305 which has been
repaired to my satisfaction and I/we admit that the payment for such
repairs by Trans Eurokars Pte Ltd is in full and final discharge of my claim
under policy number: _____ in respect of damage
caused to the said vehicle as a result of an accident that occurred on
4/5/19 at STILL RO / EAST COAST RO.




Witnessed by Repairers

6/6/19

Date



Signature by Insured

6/6/19.

Date



Corporate Head Office

Trans Eurokars Pte Ltd, Eurokars Centre, 12 Sengul Kadut Ave Singapore 729648
Tel: 6363 3003 Fax: 6369 3003 EMail: 19910385@te.com

Showroom & Service Centre:

23 Long Koo Road Singapore 159095
Sales Hotline: 6803 6116 Service Hotline: 6803 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417
5 Ubi Close Singapore 408606
Sales Hotline: 6395 6886 Service Hotline: 6395 6899
Sales Fax: 6846 1700 Service Fax: 6744 8402

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 7 May, 2019 1:48 PM
To: vion.lim@eurokars.com.sg; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: samuel.ng@eurokars.com.sg; Sherini Pillai
Subject: RE: ACCIDENT ON 04/5/19 INVOLVING SKV3130S & SHC1862L
Attachments: EST.PDF; RPT.PDF; FRT 1.mp4; FRT 2.mp4

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKV3130S and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

3:31pm @ 7/5/19
Person @ Vion
vehicle in
sur @ Steve.

From: vion.lim@eurokars.com.sg [mailto:vion.lim@eurokars.com.sg]
Sent: 07 May, 2019 11:37 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: samuel.ng@eurokars.com.sg
Subject: RE: ACCIDENT ON 04/5/19 INVOLVING SKV3130S & SHC1862L

Dear Gabriel,

Please assist to assign LKK for the above. Thank you. Car is in 27A Tanjong Penjuru.

Best Regards.

 **EUROKARS GROUP**

Vion Lim

Insurance Claims Officer

EUROKARS SERVICES PTE LTD
27A Tanjong Penjuru, Singapore 609042
D: (65) 6331 0684 H: (65) 9111 7463
E: vion.lim@eurokars.com.sg
Website: www.eurokars.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: 07 May 2019 9:18 AM
To: Vion Lim <vion.lim@eurokars.com.sg>
Cc: Samuel Ng <samuel.ng@eurokars.com.sg>
Subject: RE: ACCIDENT ON 04/5/19 INVOLVING SKV3130S & SHC1862L

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: vion.lim@eurokars.com.sg [<mailto:vion.lim@eurokars.com.sg>]
Sent: 06 May, 2019 8:23 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: samuel.ng@eurokars.com.sg
Subject: ACCIDENT ON 04/5/19 INVOLVING SKV3130S & SHC1862L

Dear Sir / Mdm,

Your Ref: SHC1862L

Please assist to arrange survey for the above vehicle in 27A Tanjong Penjuru.
Kindly revert the liability for the above case. Thank you.

Best Regards,



Vion Lim
Insurance Claims Officer

EUROKARS SERVICES PTE LTD
27A Tanjong Penjuru, Singapore 609042
D: (65) 6331 0684 H: (65) 9111 7463
E: vion.lim@eurokars.com.sg
Website: www.eurokars.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Date: 09 January 2020

**c/o LKK AUTO CONSULTANTS PTE LTD
INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attn : Motor Claims Department**

Your Ref : SHC1862L

Our Ref : SKV3130S

RE: Accident involving SKV3130S & SHC1862L on 04/05/2019

Enclosed is the duly signed **Express Settlement discharge voucher** for your perusal.

Please pay **Trans Eurokars Pte Ltd** the sum of **S19,810.00** and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648.**

Yours faithfully,

Stephanie Loke
Manager – Service & Development
DID: 63310686
FAX: 63310690
e-mail: Stephanie.loke@eurokars.com.sg



Without Prejudice
to Injury Claim

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
repairers my/our vehicle No: SKV31305 which has been
repaired to my satisfaction and I/we admit that the payment for such
repairs by Trans Eurokars Pte Ltd is in full and final discharge of my claim
under policy number: _____ in respect of damage
caused to the said vehicle as a result of an accident that occurred on
4/5/19 at STILL RD / EAST COAST RD.



Witnessed by Repairers



6/6/19

Date



Signature by Insured

6/6/19

Date



Corporate Head Office :

Trans Eurokars Pte Ltd, Eurokars Centre, 12 Sungei Kadut Ave Singapore 729648
Tel: 6363 3003 Fax: 6369 3003 ERM.199103856N

Showroom & Service Centre :

23 Ling Kee Road Singapore 158095

Sales Hotline : 6603 6118

Service Hotline : 6603 6128

Sales Fax : 6476 7073

Service Fax : 6476 7417

5 Ubi Close Singapore 408608

Sales Hotline : 6395 8886

Service Hotline : 6395 8899

Sales Fax : 6846 1700

Service Fax : 6744 9402

Print Received Message

This mail is associated with :

***SKV3130S (MCT19050089)**

[SHC1862L]

TP

LO YILING

May 4 2019 1:00PM

[-]

Trans Eurokars Pte Ltd - Tanjong Penjuru

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/01/2020 15:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$19810.00) - SKV3130S - Claim Handler: Sherini Pillai

Approved:19810.00:AS DISCUSSED, PLEASE GIVE TRANSEUROKARS GLOBAL \$19,810.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2019 Edit Reg		07 May 2019 00:00 Edit Adj Rpt	S\$17,000.00 Edit Estimates	S\$17,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	LO YILING, ID: S2663984		
Vehicle Reg. No.:	SKV3130S	Date of Loss:	04/05/2019 13:00 - :59 [45 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19050089	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC1862L	Policy No. (Claimant):	5081770402-02
		Excess:	
Repairer:	Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru, 609042 West Coast - Tel: 6331 0680		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (02/01/2020): Alert - Adj Mandate Approved (S\$19810.00) - SKV3130S - Claim Handler: Sherini Pl...
- III_SG (20/12/2019): Alert - Adj Mandate Approved (S\$19340.00) - SKV3130S - Claim Handler: Sherini Pl...
- III_SG (26/11/2019): Alert - Adj Mandate Maintained - SKV3130S - Claim Handler: Sherini Pillai
- III_SG (07/11/2019): Alert - Adj Mandate Maintained - SKV3130S - Claim Handler: Sherini Pillai
- III_SG (01/11/2019): Alert - Adj Mandate Approved (S\$19040.00) - SKV3130S - Claim Handler: Sherini Pl...
- III_SG (08/05/2019): Alert - Adj Mandate Approved (S\$0.00) - SKV3130S - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV3130S (MCT19050089)
 [SHC1862L]
 TP
 LO YILING
 May 4 2019 1:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Trans Eurokars Pte Ltd - Tanjong Penjuru

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		☒
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail	Print	
1	08/05/19 09:01	Video - TP							Load MP4		
2	08/05/19 09:01	Video - TP video 2							Load MP4		
Photos/Images									1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	17/10/19 15:17	General View							Load JPG	☒	
2	17/10/19 15:17	General View							Load JPG	☒	
3	17/10/19 15:17	General View							Load JPG	☒	
4	17/10/19 15:17	General View							Load JPG	☒	
5	17/10/19 15:17	General View							Load JPG	☒	
6	17/10/19 15:17	General View							Load JPG	☒	
7	17/10/19 15:17	General View							Load JPG	☒	
8	17/10/19 15:17	General View							Load JPG	☒	
9	17/10/19 15:17	General View							Load JPG	☒	
10	17/10/19 15:17	General View							Load JPG	☒	
11	17/10/19 15:17	General View							Load JPG	☒	
12	17/10/19 15:17	General View							Load JPG	☒	
13	17/10/19 15:17	General View							Load JPG	☒	
14	17/10/19 15:17	General View							Load JPG	☒	
15	17/10/19 15:17	General View							Load JPG	☒	
16	17/10/19 15:17	General View							Load JPG	☒	
17	17/10/19 15:17	General View							Load JPG	☒	
18	17/10/19 15:17	General View							Load JPG	☒	
19	17/10/19 15:17	General View							Load JPG	☒	
20	17/10/19 15:17	General View							Load JPG	☒	
21	17/10/19 15:17	General View							Load JPG	☒	
22	17/10/19 15:17	General View							Load JPG	☒	
23	17/10/19 15:17	General View							Load JPG	☒	
24	17/10/19 15:17	General View							Load JPG	☒	
25	17/10/19 15:17	General View							Load JPG	☒	
26	17/10/19 15:17	General View							Load JPG	☒	
27	17/10/19 15:17	General View							Load JPG	☒	
28	17/10/19 15:17	General View							Load JPG	☒	
29	17/10/19 15:17	General View							Load JPG	☒	
30	17/10/19 15:17	General View							Load JPG	☒	
31	17/10/19 15:17	General View							Load JPG	☒	
32	17/10/19 15:17	General View							Load JPG	☒	
33	17/10/19 15:17	General View							Load JPG	☒	
34	17/10/19 15:17	General View							Load JPG	☒	
35	17/10/19 15:17	General View							Load JPG	☒	
36	17/10/19 15:17	General View							Load JPG	☒	
37	17/10/19 15:17	General View							Load JPG	☒	
38	17/10/19 15:17	General View							Load JPG	☒	
39	17/10/19 15:17	General View							Load JPG	☒	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
40	17/10/19 15:17	General View	 Load JPG	☒
41	17/10/19 15:17	General View	 Load JPG	☒
42	17/10/19 15:17	General View	 Load JPG	☒
43	17/10/19 15:17	General View	 Load JPG	☒
44	17/10/19 15:17	General View	 Load JPG	☒
45	17/10/19 15:17	General View	 Load JPG	☒
46	17/10/19 15:17	General View	 Load JPG	☒
47	17/10/19 15:17	General View	 Load JPG	☒
48	17/10/19 15:17	General View	 Load JPG	☒
49	17/10/19 15:17	General View	 Load JPG	☒
50	17/10/19 15:17	General View	 Load JPG	☒
51	17/10/19 15:17	General View	 Load JPG	☒
52	17/10/19 15:17	General View	 Load JPG	☒
53	17/10/19 15:17	General View	 Load JPG	☒
54	17/10/19 15:17	General View	 Load JPG	☒
55	17/10/19 15:17	General View	 Load JPG	☒
56	17/10/19 15:17	General View	 Load JPG	☒
57	17/10/19 15:17	General View	 Load JPG	☒
58	17/10/19 15:17	General View	 Load JPG	☒
59	17/10/19 15:17	General View	 Load JPG	☒
60	17/10/19 15:17	General View	 Load JPG	☒
61	17/10/19 15:17	General View	 Load JPG	☒
62	17/10/19 15:17	General View	 Load JPG	☒
63	17/10/19 15:17	General View	 Load JPG	☒
64	17/10/19 15:17	General View	 Load JPG	☒
65	17/10/19 15:17	General View	 Load JPG	☒
66	17/10/19 15:17	General View	 Load JPG	☒
67	17/10/19 15:17	General View	 Load JPG	☒
68	17/10/19 15:17	General View	 Load JPG	☒
69	17/10/19 15:17	General View	 Load JPG	☒
70	17/10/19 15:17	General View	 Load JPG	☒
71	17/10/19 15:17	General View	 Load JPG	☒
72	17/10/19 15:17	General View	 Load JPG	☒
73	17/10/19 15:17	General View	 Load JPG	☒
74	17/10/19 15:17	General View	 Load JPG	☒
75	17/10/19 15:17	General View	 Load JPG	☒
76	17/10/19 15:17	General View	 Load JPG	☒
77	17/10/19 15:17	General View	 Load JPG	☒
78	17/10/19 15:17	General View	 Load JPG	☒
79	17/10/19 15:17	General View	 Load JPG	☒
80	17/10/19 15:17	General View	 Load JPG	☒
81	17/10/19 15:17	General View	 Load JPG	☒
82	17/10/19 15:17	General View	 Load JPG	☒
83	17/10/19 15:17	General View	 Load JPG	☒
84	17/10/19 15:17	General View	 Load JPG	☒
85	17/10/19 15:17	General View	 Load JPG	☒
86	17/10/19 15:17	General View	 Load JPG	☒
87	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
88	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
89	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
90	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
91	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
92	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
93	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
94	26/11/19 14:19	Reinspection Photo	 Load JPG	☒
95	26/11/19 14:19	Reinspection Photo	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
96	26/11/19 14:19	Reinspection Photo		Load JPG	☒
97	26/11/19 14:19	Reinspection Photo		Load JPG	☒
98	26/11/19 14:19	Reinspection Photo		Load JPG	☒
99	26/11/19 14:19	Reinspection Photo		Load JPG	☒
100	26/11/19 14:19	Reinspection Photo		Load JPG	☒
101	26/11/19 14:19	Reinspection Photo		Load JPG	☒
102	26/11/19 14:19	Reinspection Photo		Load JPG	☒
103	26/11/19 14:19	Reinspection Photo		Load JPG	☒
104	26/11/19 14:19	Reinspection Photo		Load JPG	☒
105	26/11/19 14:19	Reinspection Photo		Load JPG	☒
106	26/11/19 14:19	Reinspection Photo		Load JPG	☒
107	26/11/19 14:19	Reinspection Photo		Load JPG	☒
108	26/11/19 14:19	Reinspection Photo		Load JPG	☒
109	26/11/19 14:19	Reinspection Photo		Load JPG	☒
110	26/11/19 14:19	Reinspection Photo		Load JPG	☒
111	26/11/19 14:19	Reinspection Photo		Load JPG	☒
112	26/11/19 14:19	Reinspection Photo		Load JPG	☒
113	26/11/19 14:19	Reinspection Photo		Load JPG	☒
114	26/11/19 14:19	Reinspection Photo		Load JPG	☒
115	26/11/19 14:19	Reinspection Photo		Load JPG	☒
116	26/11/19 14:19	Reinspection Photo		Load JPG	☒
117	26/11/19 14:19	Reinspection Photo		Load JPG	☒
118	26/11/19 14:19	Reinspection Photo		Load JPG	☒
119	26/11/19 14:19	Reinspection Photo		Load JPG	☒
120	26/11/19 14:19	Reinspection Photo		Load JPG	☒
121	26/11/19 14:19	Reinspection Photo		Load JPG	☒
122	26/11/19 14:19	Reinspection Photo		Load JPG	☒
123	26/11/19 14:19	Reinspection Photo		Load JPG	☒
124	26/11/19 14:19	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/05/19 20:30	TP ESTIMATE		Load PDF	
2	07/05/19 20:30	TP GIA REPORT		Load PDF	
3	07/05/19 20:30	ACKNOWLEDGEMENT EMAIL TO III DD 07.05.2019		Load PDF	
4	13/05/19 10:03	TP ESTIMATE - MARKED		Load PDF	
5	17/10/19 15:16	LOD AND OTHER DOCUMENTS		Load PDF	
6	31/10/19 14:33	LOD		Load PDF	
7	06/11/19 17:52	TP NUMBER OF DAYS FOR LOU		Load JPG	☒
8	17/01/20 10:14	WORKSHOP INVOICE		Load PDF	
9	17/01/20 10:14	AUTHORISATION TO ACT FORM		Load PDF	
10	17/01/20 10:14	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	08/05/19 08:46	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19008051/T1GA3Q2

Date: 17/01/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No : SKV3130S Insured Vehicle No : SHC1862L
 Date of Loss: 04/05/2019 Nature of Claim: TP Claim No: MCT19050089

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV3130S
 Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A) Engine No: P520299699
 Reg. Date: 28/07/2015 (Man. Year: 2015) Chassis No: JM6BM42A8G0314065
 Colour: Bronze Odometer: 47065 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,477.64	15,534.09	6,943.55	30.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,070.00	11,225.00	3,845.00	25.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,547.64	26,759.09	10,788.55	28.73
Approved Total (Overridden) (S\$)		17,000.00		
(S\$)	37,547.64	17,000.00	20,547.64	54.72
+ GST 7.00/7.00% (S\$)	2,628.33	1,190.00	1,438.33	54.72
Nett Amount (S\$)	40,175.97	18,190.00	21,985.97	54.72
+ Loss of Use (27.0 x S\$60.00/day) (S\$)		1,620.00		
Nett Liability (S\$)		19,810.00		

INSPECTION

Date of Assignment: 07/05/2019
 Date Inspected: 07/05/2019 Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
 27A Tanjong Penjuru
 Singapore 609025
 Estimated Period of Repair: 17.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Oct 2019)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV3130S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	1,083.30 FL	*1,083.30 FL
2	1		*RETAINER RHS	Necessary	19.70 FL	*19.70 FL
3	1		*BRACKET RHS	Necessary	15.90 FL	*15.90 FL
4	1		*CHROME RHS ,FOGLAMP	Missing	112.10 FL	*112.10 FL
5	1		*COVER RHS ,FOGLAMP	Missing	48.80 FL	*48.80 FL
6	1		*FRONT REINFORCEMENT	Bent	466.80 FL	*466.80 FL
7	1		*STIFF A ,FRONT BUMPER	Not Necessary	87.90 FL	*- FL
8	1		*CORD SHORT RHS ,FOGLAMP	Distorted	39.20 FL	*39.20 FL
9	2		*FASTENER ,FRONT BUMPER	Necessary	6.00 FL	*6.00 FL
10	12		*CLIPS,FRONT BUMPER	Necessary	44.40 FL	*44.40 FL
11	2		*GROMMET ,FRONT BUMPER	Necessary	5.80 FL	*5.80 FL
12	6		*RIVET ,FRONT BUMPER	Necessary	24.00 FL	*24.00 FL
13	4		*RIVET ,FRONT BUMPER	Necessary	36.80 FL	*36.80 FL
14	1		*GRILLE TOP	Not Necessary	351.80 FL	*- FL
15	1		*BRACKET TOP ,GRILLE	Not Necessary	107.60 FL	*- FL
16	8		*FASTENER ,GRILLE	Necessary	25.60 FL	*25.60 FL
17	1		*CHROME RHS	Cut	185.60 FL	*185.60 FL
18	1		*BRACKET RHS ,FRONT GRILLE	Deformed	15.90 FL	*15.90 FL
19	2		*RIVET ,FRONT GRILLE	Necessary	16.00 FL	*16.00 FL
20	2		*PIN LOCATOR ,FRONT GRILLE	Necessary	5.80 FL	*5.80 FL
21	2		*GROMMET ,FRONT GRILLE	Necessary	5.80 FL	*5.80 FL
22	1		*FRONT PLATE UPPER	Bent	130.20 FL	*130.20 FL
23	1		*FRONT SUPPORT PANEL	Cracked	493.20 FL	*493.20 FL
24	1		*PLATE SEAL RHS	Not Necessary	37.40 FL	*- FL
25	4		*FASTENER ,PLATE SEAL	Not Necessary	10.80 FL	*- FL
26	1		*PLATE SET ,FRONT REINFORCEMENT	Not Necessary	97.40 FL	*- FL
27	4		*SET FASTENER ,PLATE	Not Necessary	12.80 FL	*- FL
28	1		*BONNET	Bent	1,120.70 FL	*1,120.70 FL
29	1		*HINGE LHS ,BONNET	Bent	43.10 FL	*43.10 FL
30	1		*HINGE RHS ,BONNET	Bent	43.10 FL	*43.10 FL
31	1		*WEATHERSTRIP ,BONNET	Cut	66.80 FL	*66.80 FL
32	1		*FRONT FENDER RHS	Bent	350.60 FL	*350.60 FL
33	1		*STAY RHS ,FENDER	Bent	41.90 FL	*41.90 FL
34	1		*MUDGUARD RHS	Deformed	101.90 FL	*101.90 FL
35	15		*FASRTENER ,MUDGUARD	Necessary	45.00 FL	*45.00 FL
36	1		*HEADLAMP LHS	Not Necessary	2,357.30 FL	*- FL
37	1		*HEADLAMP RHS	Cracked	2,357.30 FL	*2,357.30 FL
38	1		*HID CONTROL UNIT	Not Necessary	394.80 FL	*- FL
39	1		*GASKET ,CONTROL UNIT	Not Necessary	14.30 FL	*- FL
40	4		*CLIP ,HEADLAMP	Necessary	16.00 FL	*16.00 FL
41	2		*RIVET ,HEADLAMP	Necessary	7.00 FL	*7.00 FL
42	1		*LAMP RHS ,SIDE TURN	Cracked	165.20 FL	*165.20 FL
43	1		*FOGLAMP RHS	Cracked	369.00 FL	*369.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*BRACKET RHS ,FOGLAMP	Distorted	18.20 FL	*18.20 FL
45	6		*SCREW ,FOGLAMP	Necessary	7.20 FL	*7.20 FL
46	1		*WASHER TANK	Deformed	109.20 FL	*109.20 FL
47	1		*SWITCH LEVEL ,WASHER PUMP	Cracked	118.50 FL	*118.50 FL
48	1		*GROMMET ,WASHER TANK	Necessary	14.70 FL	*14.70 FL
49	1		*FUNNEL ,WASHER TANK	Not Necessary	58.80 FL	*- FL
50	1		*GROMMET ,WASHER TANK	Necessary	6.20 FL	*6.20 FL
51	1		*PIPE ,WASHER TANK	Not Necessary	18.40 FL	*- FL
52	1		*HEADLAMP PANEL RHS	Repair	156.50 FL	*- FL
53	1		*ABS PUMP	Not Necessary	1,818.30 FL	*- FL
54	1		*BRACKET ,ABS PUMP	Not Necessary	28.20 FL	*- FL
55	1		*FRONT WHEEL RIM RHS	Cut	722.30 FL	*722.30 FL
56	1		*FRONT BEARING RHS	Not Necessary	568.80 FL	*- FL
57	1		*FRONT KNUCKLE RHS	Not Necessary	402.60 FL	*- FL
58	1		*FRONT DAMPER RHS	Not Necessary	360.80 FL	*- FL
59	1		*RUB MTG TOP ,FRONT DAMPER	Not Necessary	96.50 FL	*- FL
60	1		*BEARING TOP ,FRONT DAMPER	Not Necessary	55.80 FL	*- FL
61	1		*FRONT LOWER ARM RHS	Not Necessary	454.70 FL	*- FL
62	1		*FRONT LINK ROD RHS	Not Necessary	68.00 FL	*- FL
63	1		*FRONT HARNESS	Cut	5,446.30 FL	*5,446.30 FL
64	5		*RADIATOR COOLANT	Necessary	68.50 FL	*68.50 FL
65	1		*SOCKET COVER RHS ,HEADLAMP	Cut	23.50 FL	*23.50 FL
66	1		*PIPE ,HEADLAMP WASHER	Deformed	128.90 FL	*128.90 FL
67	1		*COVER RHS ,HEADLAMP WASHER	Distorted	89.40 FL	*89.40 FL
68	1		*CLAMP ,ACTUATOR	Necessary	17.30 FL	*17.30 FL
69	1		*ACTUATOR RHS	Distorted	254.60 FL	*254.60 FL
70	1		*FRONT CROSSMEMBER	Bent	1,880.60 FL	*1,880.60 FL
71	1		*PUMP ,WASHER TANK	Deformed	499.80 FL	*499.80 FL
72	1		*STOPPER ,FRONT DAMPER	Necessary	46.40 FL	*46.40 FL
73	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
74	1		*NUMBER PLATE	Not Necessary	70.00 FS	*- FS
75	1		*TIRE	Cut	240.00 FS	*240.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	24,929.60	17,230.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,451.96	1,696.01
Total Parts (\$\$)	22,477.64	15,534.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO MOUNT VEHICLE ON CAR O LINER AND RE-ALIGN CAR BODY ACCORDING MAZDA SPECIFICATION	New	1,500.00	1,500.00
2	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	120.00
3	TO REPLACE CROSSMEMBER ASSY	New	990.00	990.00
4	TO CHECK STEERING GEOMETRY & CONTROL FULL WHEEL ALIGNMENT	New	560.00	560.00
5	TO REMOVE & INTALL ENGINE ASSY FOR ACCESS	New	1,320.00	1,320.00
6	TO REPLACE FRONT BUMPER ,FRONT REINFORCEMENT ,GRILLE TOP ,HEADLAMP PANEL RH,BONNET AND FRONT FENDER RH .TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT	New	2,640.00	2,310.00
7	TO RESPRAY FRONT BUMPER ,FRONT REINFORCEMENT ,GRILLE TOP ,HEADLAMP PANEL RH ,BONNET AND FRONT FENDER RH,FRONT FENDER RH ,FRONT DOOR RH	New	3,780.00	2,835.00
8	TO REMOVE & INSTALL RADIATOR ,RADIATOR FAN AND FRONT SUPPORT PANEL .TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST	New	660.00	660.00
9	TO REMOVE & INSTALL CONDENSOR ,AIR COND PIPE AND TOP -UP GAS COOLING SYSTEM	New	630.00	330.00
10	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	350.00	0.00
11	TO REMOVE AND REPLACE ABS PUMP ,PIPING AND CHECK LEAK	New	990.00	0.00
12	TO CONDUCT BRAKE SYSTEM CHECKING USING SPECIFIC BRAKING TEST MECHINE	New	560.00	0.00
13	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
14	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
15	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
16	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	New	120.00	120.00
Gross Labour Cost (S\$)			15,070.00	11,225.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >