



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Ms Lo Yi Ling ADDRESS: 18 Lorong K Telok Karau #03-13 Singapore 425781 TEL: 85334733	WIP: 40694 EXCESS: DATE: 6-May-19
---	--	--	---

VEH NO:	SKV3130S	DATE IN:		CONTACT PERSON:	Vion 63957877
CHASSIS NO:	JM6BM42A8G0314065	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3	DATE REG.:	28-Jul-15	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	FRT BUMPER BM MBHR3-50-031BBB	all	\$ 1,083.30
2	1	RETAINER RHS MBHN1-50-0T1F	ner	\$ 19.70
3	1	BRACKET RHS MBHN1-50-152	ner	\$ 15.90
4	1	CHROME RHS, FOGLAMP MBJE1-50-C12	mis	\$ 112.10
5	1	COVER RHS, FOGLAMP MBJE1-50-C11A	mis	\$ 48.80
6	1	FRONT REINFORCEMENT MB45A-50-070A	bt	\$ 466.80
7	1	STIFF'A', FRONT BUMPER MBHN1-50-0S0B	?	\$ 87.90
8	1	CORD SHORT RHS, FOGLAMP MBHN9-67-290	dis	\$ 39.20
9	2	FASTENER, FRONT BUMPER MB45A-56-146A	ner	\$ 6.00
10	12	CLIP, FRONT BUMPER MC274-50-133	ner	\$ 44.40
11	2	GROMMET, FRONT BUMPER MGHP9-50-025	ner	\$ 5.80
12	6	RIVET, FRONT BUMPER MS51S-51-833	ner	\$ 24.00
13	4	RIVET, FRONT BUMPER MTK21-50-355	ner	\$ 36.80
14	1	GRILLE TOP MBHN1-50-033 53	de	\$ 351.80
15	1	BRACKET TOP, GRILLE MBHN1-50-717D	?	\$ 107.60
16	8	FASTENER, GRILLE MGD7A-50-EA1	ner	\$ 25.60
17	1	CHROME RHS MBHN1-50-7J1A	ner	\$ 185.60
18	1	BRACKET RHS, FRONT GRILLE MBHN1-50-153	all	\$ 15.90
19	2	RIVET, FRONT GRILLE MEA01-50-037	ner	\$ 16.00
20	2	PIN LOCATOR, FRONT GRILLE MKD45-50-1K5A	ner	\$ 5.80
21	2	GROMMET, FRONT GRILLE MKD45-50-ES1	ner	\$ 5.80
22	1	FRONT PANEL UPPER MB45A-53-150A	bt	\$ 130.20
23	1	FRONT SUPPORT PANEL MGHR5-53-110B	ner	\$ 493.20
24	1	PLATE SEAL RHS MBHN1-50-1U1A	?	\$ 37.40
25	4	FASTENER, PLATE SEAL MKD45-50-EA1	?	\$ 10.80
26	1	PLATE SET, FRONT REINFORCEMENT MBHN3-50-1C0	?	\$ 97.40
27	4	FASTENER, PLATE SET MGD7A-50-EA1	?	\$ 12.80
28	1	BONNET MBHY0-52-31XA	bt	\$ 1,120.70
29	1	HINGE LHS, BONNET MB45A-52-420A	bt	\$ 43.10

30	HINGE RHS, BONNET	1	MB45A-52-410A	bt	\$ 43.10
31	WEATHERSTRIP, BONNET	1	MBHN9-56-770A	cut	\$ 66.80
32	FRONT FENDER RHS	1	MB45A-52-111B	bt	\$ 350.60
33	STAY RHS, FENDER	1	MB4YA-52-10Y	bt	\$ 41.90
34	MUDGUARD RHS	1	MB45A-56-130H	de	\$ 101.90
35	FASTENER, MUDGUARD	15	MB45A-56-146A	de	\$ 45.00
36	HEADLAMP LHS	1	MBHT6-51-041A	?	\$ 2,357.30
37	HEADLAMP RHS	1	MBHT6-51-031A	cut	\$ 2,357.30
38	HID CONTROL UNIT	1	MBHN3-51-0H3	?	\$ 394.80
39	GASKET, CONTROL UNIT	1	MC236-51-0B2	?	\$ 14.30
40	CLIP, HEADLAMP	4	MFB01-50-133C	de	\$ 16.00
41	RIVET, HEADLAMP	2	MB092-51-833	de	\$ 7.00
42	LAMP RHS, SIDE TURN	1	MB45A-51-350A	cut	\$ 165.20
43	FOGLAMP RHS	1	MTK21-51-680A	cut	\$ 369.00
44	BRACKET RHS, FOGLAMP	1	MBHR1-51-684A	dis	\$ 18.20
45	SCREW, FOGLAMP	6	M9986-50-516	de	\$ 7.20
46	WASHER TANK	1	MGHP9-67-481A	de	\$ 109.20
47	SWITCH LEVEL, WASHER PUMP	1	MKD35-67-488	cut	\$ 118.50
48	GROMMET, WASHER TANK	1	MKD37-67-491	de	\$ 14.70
49	FUNNEL, WASHER TANK	1	MBHN9-67-484	?	\$ 58.80
50	GROMMET, WASHER TANK	1	MKD35-67-491	de	\$ 6.20
51	PIPE, WASHER TANK	1	MBHN9-67-500	X	\$ 18.40
52	HEADLAMP PANEL RHS	1	MB45A-53-140	Rx	\$ 156.50
53	ABS PUMP	1	MB4Y2-43-7A0C	?	\$ 1,818.30
54	BRACKET, ABS PUMP	1	MB45A-43-310	?	\$ 28.20
55	FRONT WHEEL RIM RHS	1	M9965-D0-6560	cut	\$ 722.30
56	FRONT BEARING RHS	1	MB45A-33-04X	?	\$ 568.80
57	FRONT KNUCKLE RHS	1	MB45A-33-021	?	\$ 402.60
58	FRONT DAMPER RHS	1	MBHS2-34-700A	?	\$ 360.80
59	RUB MTG TOP, FRONT DAMPER	1	MKD35-34-380C	?	\$ 96.50
60	BEARING TOP, FRONT DAMPER	1	MB45A-34-38XA	?	\$ 55.80
61	FRONT LOWER ARM RHS	1	MB60S-34-300G	?	\$ 454.70
62	FRONT LINK ROD RHS	1	MB45A-34-150	?	\$ 68.00
63	FRONT HARNESS	1	MBLF4-67-010C	cut	\$ 5,446.30
64	RADIATOR COOLANT	5		de	\$ 68.50
#	Socket over RH, Headlamp at				
#	Pipe, Headlamp washer				
#	Coil RHS, headlamp washer				
#	Activator RH, headlamp washer				
TOTAL PARTS					\$ 21,579.10
LESS 10%					\$ 2,157.91
TOTAL PARTS COST					\$ 19,421.19
Labour Description					
1	MZ-BR-FRONT6	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			
				2310	\$ 2,640.00

2		TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH, FRONT FENDER RH, FRONT DOOR RH. <i>630</i>	<i>2835</i>	\$ 3,780.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	NETT ✓	\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	<i>330</i> NETT	\$ 630.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT X	\$ 70.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
7		TO REMOVE AND REPLACE ABS PUMP, PIPING AND CHECK LEAK.	NETT ?	\$ 990.00
8		TO CONDUCT BRAKE SYSTEM CHECKING USING SPECIFIC BRAKING TEST MACHINE.	NETT ?	\$ 560.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>150.</i>	\$ 250.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>150</i>	\$ 250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>180</i>	\$ 350.00
12	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>invoice ?</i>	NETT	\$ 120.00
13	MZ-BR-SUNDRI	SUNDRIES. <i>30</i>	NETT	\$ 100.00

* balancing \$120.00 ✓
 * wheel alignment \$560.00 ✓
 * Front tyre RH \$300.00 cut 80% ✓

TOTAL LABOUR	\$ -	\$ 10,750.00
TOTAL PARTS	\$ -	\$ 19,421.19
TOTAL	\$ -	\$ 30,171.19
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED. ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TRANS EUROKARS PTE LTD

Tan Kah 97495749
 'WP' 7/5/19 @ 350pm
 Resurvey before paint

Authorised Signature

suve (Mantrose)

11 days

suve