

SUPPLEMENTARY ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L			NAME : Ms Lo Yi Ling		WIP : 40694	
64 CECIL STREET			ADDRESS : 18 Lorong K Telok Karau		EXCESS :	
#04-#05 IOB BUILDING			#03-13		DATE: 6-May-19	
SINGAPORE 049711			Singapore 425781			
ATTN. : MOTOR CLAIMS			TEL : 85334733			
FAX :						
VEH NO :		SKV3130S	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :		JM6BM42A8G0314065	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :		MAZDA3	DATE REG.:		POLICY NO. :	
NATURE OF WORKS						
Parts Description						
NO	QTY				REVISED	PRICES
1	SOCKET COVER RHS, HEADLAMP		1	MC514-51-0A1A	cut	\$ 23.50
2	PIPE, HEADLAMP WASHER		1	MBHT4-51-4J0	de	\$ 128.90
3	COVER RHS, HEADLAMP WASHER		1	MBHT4-51-8G1 53	dis	\$ 89.40
4	CLAMP, ACTUATOR		1	MTK33-51-829	re	\$ 17.30
5	ACTUATOR RHS		1	MBHT4-51-82X	dis	\$ 254.60
6	FRONT CROSSMEMBER		1	MB45A-34-80X	b1	\$ 1,880.60
7	PUMP, WASHER TANK		1	MKD53-51-811	de	\$ 499.80
8	STOPPER, FRONT DAMEPR		1	MB45G-34-111	re	\$ 46.40
TOTAL PARTS					\$ -	\$ 2,940.50
10% 15580.71					\$ -	\$ 294.05
TOTAL PARTS COST					\$ -	\$ 2,646.45
27025.71						
45917.00 Labour Description						
1	MZ-BR-HARNES	TO MOUNT VEHICLE ON CAR O LINER AND RE-ALIGN CAR BODY ACCORDING MAZDA SPECIFICATION.			NETT	\$ 1,500.00
2		TO SUPPLY 1 PC TIRE.			NETT	\$ 240.00
3	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.			NETT	\$ 120.00
4	MZ-BR-CROSS1	TO REPLACE CROSSMEMBER ASSY.			NETT	\$ 990.00
5	MZ-BR-WHEAL1	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			NETT	\$ 560.00
6	MZ-BR-ENGINE	TO REMOVE & INSTALL ENGINE ASSY FOR ACCESS.			NETT	\$ 1,320.00
TOTAL LABOUR					\$ -	\$ 4,730.00



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX:		NAME: Ms Lo Yi Ling ADDRESS: 18 Lorong K Telok Karau #03-13 Singapore 425781 TEL: 85334733		WIP: 40694 EXCESS: DATE: 6-May-19	
VEH NO:	SKV3130S	DATE IN:		CONTACT PERSON:	Vion 63957877
CHASSIS NO:	JM6BM42A8G0314065	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3	DATE REG.:	28-Jul-15	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	FRT BUMPER BM MBHR3-50-031BBB	all	\$ 1,083.30	
2	1	RETAINER RHS MBHN1-50-0T1F	ner	\$ 19.70	
3	1	BRACKET RHS MBHN1-50-152	ner	\$ 15.90	
4	1	CHROME RHS, FOGLAMP MBJE1-50-C12	mi's	\$ 112.10	
5	1	COVER RHS, FOGLAMP MBJE1-50-C11A	mi's	\$ 48.80	
6	1	FRONT REINFORCEMENT MB45A-50-070A	bt	\$ 466.80	
7	1	STIFF'A', FRONT BUMPER MBHN1-50-0S0B	?	\$ 87.90	
8	1	CORD SHORT RHS, FOGLAMP MBHN9-67-290	di's	\$ 39.20	
9	2	FASTENER, FRONT BUMPER MB45A-56-146A	ner	\$ 6.00	
10	12	CLIP, FRONT BUMPER MC274-50-133	ner	\$ 44.40	
11	2	GROMMET, FRONT BUMPER MGHP9-50-0Z5	ner	\$ 5.80	
12	6	RIVET, FRONT BUMPER MS51S-51-833	ner	\$ 24.00	
13	4	RIVET, FRONT BUMPER MTV1-50-355	ner	\$ 36.80	
14	1	GRILLE TOP MBHN1-50-033 53	all	\$ 351.80	
15	1	BRACKET TOP, GRILLE MBHN1-50-717D	?	\$ 107.60	
16	8	FASTENER, GRILLE MGD7A-50-EA1	ner	\$ 25.60	
17	1	CHROME RHS MBHN1-50-7J1A	ner	\$ 185.60	
18	1	BRACKET RHS, FRONT GRILLE MBHN1-50-153	all	\$ 15.90	
19	2	RIVET, FRONT GRILLE MEA01-50-037	ner	\$ 16.00	
20	2	PIN LOCATOR, FRONT GRILLE MKD45-50-1K5A	ner	\$ 5.80	
21	2	GROMMET, FRONT GRILLE MKD45-50-ES1	ner	\$ 5.80	
22	1	FRONT PANEL UPPER MB45A-53-150A	bt	\$ 130.20	
23	1	FRONT SUPPORT PANEL MGHR5-53-110B	ner	\$ 493.20	
24	1	PLATE SEAL RHS MBHN1-50-1U1A	?	\$ 37.40	
25	4	FASTENER, PLATE SEAL MKD45-50-EA1	?	\$ 10.80	
26	1	PLATE SET, FRONT REINFORCEMENT MBHN3-50-1C0	?	\$ 97.40	
27	4	FASTENER, PLATE SET MGD7A-50-EA1	?	\$ 12.80	
28	1	BONNET MBHY0-52-31XA	bt	\$ 1,120.70	
29	1	HINGE LHS, BONNET MB45A-52-420A	bt	\$ 43.10	

30	HINGE RHS, BONNET	1	MB45A-52-410A	bt	\$ 43.10
31	WEATHERSTRIP, BONNET	1	MBHN9-56-770A	cut	\$ 66.80
32	FRONT FENDER RHS	1	MB45A-52-111B	bt	\$ 350.60
33	STAY RHS, FENDER	1	MB4YA-52-10Y	bt	\$ 41.90
34	MUDGUARD RHS	1	MB45A-56-130H	de	\$ 101.90
35	FASTENER, MUDGUARD	15	MB45A-56-146A	cut	\$ 45.00
36	HEADLAMP LHS	1	MBHT6-51-041A	?	\$ 2,357.30
37	HEADLAMP RHS	1	MBHT6-51-031A	cut	\$ 2,357.30
38	HID CONTROL UNIT	1	MBHN3-51-0H3	?	\$ 394.80
39	GASKET, CONTROL UNIT	1	MC236-51-0B2	?	\$ 14.30
40	CLIP, HEADLAMP	4	MFB01-50-133C	cut	\$ 16.00
41	RIVET, HEADLAMP	2	MB092-51-833	cut	\$ 7.00
42	LAMP RHS, SIDE TURN	1	MB45A-51-350A	cut	\$ 165.20
43	FOGLAMP RHS	1	MTK21-51-680A	cut	\$ 369.00
44	BRACKET RHS, FOGLAMP	1	MBHR1-51-684A	dis	\$ 18.20
45	SCREW, FOGLAMP	6	M9986-50-516	cut	\$ 7.20
46	WASHER TANK	1	MGHP9-67-481A	de	\$ 109.20
47	SWITCH LEVEL, WASHER PUMP	1	MKD35-67-488	cut	\$ 118.50
48	GROMMET, WASHER TANK	1	MKD37-67-491	cut	\$ 14.70
49	FUNNEL, WASHER TANK	1	MBHN9-67-484	?	\$ 58.80
50	GROMMET, WASHER TANK	1	MKD35-67-491	cut	\$ 6.20
51	PIPE, WASHER TANK	1	MBHN9-67-500	X	\$ 18.40
52	HEADLAMP PANEL RHS	1	MB45A-53-140	Rp	\$ 156.50
53	ABS PUMP	1	MB4Y2-43-7A0C	?	\$ 1,818.30
54	BRACKET, ABS PUMP	1	MB45A-43-310	?	\$ 28.20
55	FRONT WHEEL RIM RHS	1	M9965-D0-6560	cut	\$ 722.30
56	FRONT BEARING RHS	1	MB45A-33-04X	?	\$ 568.80
57	FRONT KNUCKLE RHS	1	MB45A-33-021	?	\$ 402.60
58	FRONT DAMPER RHS	1	MBHS2-34-700A	?	\$ 360.80
59	RUB MTG TOP, FRONT DAMPER	1	MKD35-34-380C	?	\$ 96.50
60	BEARING TOP, FRONT DAMPER	1	MB45A-34-38XA	?	\$ 55.80
61	FRONT LOWER ARM RHS	1	MB60S-34-300G	?	\$ 454.70
62	FRONT LINK ROD RHS	1	MB45A-34-150	?	\$ 68.00
63	FRONT HARNESS	1	MBLF4-67-010C	cut	\$ 5,446.30
64	RADIATOR COOLANT	5		cut	\$ 68.50
	Socket over RH, headlamp cut				
	Pipe, headlamp washer de				
	Cover RHS, headlamp washer dis				
	Activator RH, headlamp washer dis				
	TOTAL PARTS				\$ 21,579.10
	LESS 10%				\$ 2,157.91
	TOTAL PARTS COST				\$ 19,421.19
Labour Description					
1	MZ-BR-FRONT6	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			2310 \$ 2,640.00

2		TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, HEADLAMP PANEL RH, BONNET AND FRONT FENDER RH, FRONT FENDER RH, FRONT DOOR RH. <i>630</i>	2835	\$ 3,780.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	NETT ✓	\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	<i>330</i> NETT	\$ 630.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT X	\$ 70.00
6	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	X	\$ 350.00
7		TO REMOVE AND REPLACE ABS PUMP, PIPING AND CHECK LEAK.	NETT ?	\$ 990.00
8		TO CONDUCT BRAKE SYSTEM CHECKING USING SPECIFIC BRAKING TEST MACHINE.	NETT ?	\$ 560.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150.	\$ 250.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
12	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>invoice ?</i>	NETT	\$ 120.00
13	MZ-BR-SUNDRI	SUNDRIES. <i>30</i>	NETT	\$ 100.00

* balancing \$120.00 ✓
 * wheel alignment \$560.00 ✓
 * front tyre RH \$300.00 cut 80% ✓

TOTAL LABOUR	\$ -	\$ 10,750.00
TOTAL PARTS	\$ -	\$ 19,421.19
TOTAL	\$ -	\$ 30,171.19
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Tan Kah 97495749
WP 7/5/19 e350pr
Respray before paint

Authorised Signature

see (Mantowan)
11 days

see

TOTAL PARTS	\$ -	\$ 2,646.45
TOTAL	\$ -	\$ 7,376.45
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

Vehicle ident no.

Repair order no.

R000495

Technician
NG EE SENGDate
31.5.19License plate no.
SKV3130S

First reg. date

Model

Mazda : Mazda3 : 2013- (BM/BN) : except Rough Road
Suspension

Odometer reading: km/miles

47068

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left		-0°59' +/-1°00'	-0°59'
		right			-0°54'
		cross		0°00' +/-1°30'	-0°05'
	Toe	left		0°05' +/-0°10'	0°08'
		right			0°03'
		total		0°10' +/-0°20'	0°11'
	Geometrical driving axis			0°00' +/-0°48'	0°03'
Front axle	Camber	left		-0°12' +/-1°00'	-0°28'
		right			-1°25' *
		cross		0°00' +/-1°30'	0°57'
	Caster	left		6°29' +/-1°00'	6°10'
		right			5°09' *
		cross		0°00' +/-1°30'	1°02'
	SAI	left		14°00'	14°15'
		right			14°37'
		cross		0°00'	-0°22'
	Track differential angle	left			
		right			
	Toe	left		0°06' +/-0°10'	-0°36' *
		right			1°18' *
		total		0°11' +/-0°20'	0°42' *
	Setback			0°00'	
	Max steering lock	left steer	left	-39°24' +/-3°00'	
		right steer	right	32°12' +/-3°00'	
			left	32°12' +/-3°00'	
			right	-39°24' +/-3°00'	

* This value is not within specification. Tire wear, handling and safety problems may result.



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN.: MOTOR CLAIMS FAX :		NAME : Ms Lo Yi Ling ADDRESS : 18 Lorong K Telok Karau #03-13 Singapore 425781 TEL : 85334733		WIP : 40694 EXCESS : DATE: 6-May-19	
VEH NO :	SKV3130S	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6BM42A8G0314065	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	28-Jul-15	POLICY NO. :	
NATURE OF WORKS					
NO					REVISED
1	REPAIR SUM				\$ 17,000.00
				TOTAL	\$ 17,000.00
				GST 7%	\$ 1,190.00
				GRAND TOTAL	\$ 18,190.00

REMARKS:

17 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



AUTOSWIFT RECOVERY PTE LTD

TOW JOB WORK ORDERGST Reg No. : 19-9806389-N
Co. Reg No. : 199806389N

Contract :

MAZ TRANS

W/Order No. : T 162695

PART A: JOB DETAILS

Service Date

04/05/2019

Time Received

1418

Member / Customer's Name

MRS. Lim

Time Arrived

1445

Membership / NRIC No.

Time Completed

1537

Contact No.

85334733

Total Mileage

41

Vehicle Registration No.

SKV 3130S

Car Make / Model


Mazda 3

Breakdown Location

Still Rd

Towed Destination

27A 79 Penjuru

NORMAL TOWING		ADDITIONAL SERVICES	
☒ Straight Towing	☐ Multi-Storey / Basement Car Park	☐ Woodlands Checkpoint / Tuas 2nd Link	☒ Accident Towing
☐ Straight Towing with King Dolly	☐ Car Ditched / Winched Up / Crane Up	☐ Dismantle Shaft / Release Brakes	
☐ Flat Bed / Car Carrier			
☐ Flat Bed / Car Carrier with King Dolly			
☐ Heavy Goods Vehicle (Class 5 Towing)			
SURCHARGES / OTHERS		ROADSIDE SERVICES	
☐ Sunday / Public Holiday Towing (full day)	☐ Jump Start	☐ Tyre Replacement	☐ Patch Tyre Service
☐ Midnight Towing (2400hrs to 0700hrs)	☐ Repair Tyre & Returned	☐ Battery Replacement	
☐ Call Cancelled / Car Missing			
☐ Standby / Waiting Time			
Duration : _____	Battery Receipt No: _____		
☐ AA Membership Enrolment / AA Renewal			
REMARKS / COMMENTS BY TOW CREW			
 Tow Crew ID / Signature YN1894E Truck No. _____ Operation Officer's Signature			
PART B: MEMBER / CUSTOMER ACKNOWLEDGEMENT			
1 I authorise AutoSwift Recovery Pte Ltd to tow my vehicle to the above-mentioned workshop of my choice. 2 I have been advised to remove all valuables (handphone, laptop, parking coupons, cash cards etc) from the vehicle. 3 I understand that items left behind are at my own risk and that AutoSwift Recovery Pte Ltd will not be held responsible for any losses. 4 I accept that there may be damages to my vehicle arising from the towing operation and I will not hold AutoSwift Recovery liable for the damages.			
5 Remarks : _____			
Member / Customer Signature			Date
PART C: WORKSHOP / AGENT DECLARATION			
1 I hereby represent the company receiving the above mentioned vehicle. 2 AutoSwift Recovery Pte Ltd will not be held responsible for any damages or loss of valuables discovered while the vehicle is in our possession.			
3 Remarks : _____			
Workshop's Representative Signature		Workshop's Stamp	Date

WORKSHOP COPY

Swift and Safe

AutoSwift Recovery Pte Ltd
(A wholly-owned subsidiary of AA Singapore)
Head Office: 535 Kallang Bahru #02-08 GB Point Singapore 339351 Office: 6333 8811 Fax: 6733 5094
Branch Office: 10 Kallang Way Singapore 349215 24 Hours Hotline: 6844 3811 Office: 6389 4261 Fax: 6473 4996