

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

KH RL

ESTIMATE : SMJ 5156 U

Vehicle & Document Information

Date: 10/05/2019
Vehicle No: SMJ 5156 U
Make/Model: GLA180

S/N	Description	Qty	Repairer's Est	Revised Est
1	FRONT BUMPER	1	\$ 1,480.00	\$ 1,480.00 ✓
2	RH HEADLAMP	1	\$ 2,955.00	\$ 2,955.00 ✓
3	RH HEADLAMP BRACKET	1	\$ 28.00	\$ 28.00 X
4	RH FOG LAMP	1	\$ 323.00	\$ 323.00 X
5	RH FOG LAMP COVER	1	\$ 582.00	\$ 582.00 ✓
6	FRONT BUMPER GRILLE SET	1	\$ 1,533.00	\$ 1,533.00 X
7	RHF TOW HOOK COVER	1	\$ 198.00	\$ 198.00 ✓
8	FRONT BUMPER LOWER GRILLE	1	\$ 165.00	\$ 165.00 X
9	FRONT BUMPER LOWER LIP	1	\$ 365.00	\$ 365.00 ✓
			Total :	\$ 7,629.00
			10% -20%	\$ 1,545.80
			Parts Total :	\$ 6,083.20

1	FRONT CAR PLATE SET	\$ 30.00	\$ 30.00 X
1	ANTIRUST PROOFING; GALVANISING SPOT WIELD	\$ 200.00	\$ 200.00 X
1	TO CHECK LIGHTING, WIRING & FUSES	\$ 280.00	\$ 280.00
1	LABOUR TO DISMANTLE, REPAIR AND REPLACE PARTS	\$ 600.00	\$ 600.00
1	TO PUTTY, PRIMER, RE-SPRAY FRONT BUMPER	\$ 800.00	\$ 800.00
		Labour Total :	\$ 1,880.00
		Parts Total :	\$ 6,083.20
		Total :	\$ 7,963.20
		-20%	\$ 1,592.64
		Grand Total :	\$ 6,370.56
		Lump Sum :	\$ 6,400.00

CHUAN HO AUTO SERVICE



Not Authorised
Lump Sum 3800k
Money After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: