

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

24-09-19

Accident Date : 06-05-2019

OUR REF : SGJ 3252J/T/19

In the Estate Marian Tay-Mi-Lian

36C Dunearn Road

#01-14

Singapoer 309428

Lk - Morris

Date In/out: 06-05-19 to 14-05-19

8/5/19
Not Allowed
1/5 = 3600
6th.

SUPPLEMENTARY BILL ON VEH. NO. : SGJ 3252J

MODEL : NISSAN SUNNY

CHASSIS NO. : JN1CFAN16Z0101497

LIST ITEM *Nett item*

BOOT LID	613.70		Surf/Suc	753.00	
BOOT LID CHORME (TOP)			17	351.00	X
BOOT LID CHORME (BOTTOM)			17	173.80	X
REAR BUMPER FASCIA	442.50		Dis	433.50	
REAR BUMPER CHORME MOULDING			2u	168.60	
REAR BUMPER STAY LH	84.20		Surf	91.70	
REAR BUMPER SIDE ATTACHMENT	30.50	2pcs @ 35.20	als surf	70.40	1pc
REAR BUMPER SPONGE	126.40		Bin	133.80	
REAR END PANEL	335.60		17	376.20	
REAR END PANEL TOP TRIM			17	69.60	X
REAR END PANEL INNER FABRIC			17	131.10	X
				2,752.70	

NETT ITEM

BOOT LID LOCK			17	43.30	X
BOOT LID LOCK STICKER			17	50.60	X
BOOT LID LOCK CABLE			17	73.30	X
BOOT LID STOPPER		2pcs @ 5.90	17	11.80	X
BOOT LID CHORME CLIPS		8pcs @ 6.50	17	52.00	X
BOOT LID BADGE			2u	35.20	

emblem
BOOT LID EMBLEM EX SALOON

BOOT LID EMBLEM CVTC

BOOT LID EMBLEM E-THROTTE

BOOT LID EMBLEM SUNNY

TAIL LAMP

2pcs @ 283.20

rec 56.20 /

TAIL LAMP CLIPS

4pcs @ 6.50

rec 41.80 /

REAR BUMPER SIDE RETAINER

2pcs @ 27.00

rec 39.60 /

REAR BUMPER CLIPS

10pcs @ 6.50

rec 66.40 /

REAR END PANEL TOP TRIM CLIPS

4pcs @ 6.50

rec 566.40 /

REAR END PANEL INNER FABRIC CLIPS

4pcs @ 6.50

11 26.00 X

reput 54.00 X

30 rec 65.00 /

11 26.00 X

11 26.00 X

1,233.60

Less Discount 10% :

123.36

1,110.24

SPECIAL NETT ITEM

1ser/ REVERSE SENSOR WITH CONTROL UNIT

shut 380.00 200

LABOUR CHARGE

TOWING

11 80.00 X

TO CHECK WIRING SYSTEM

80.00 30

TO REMOVE AND REFIX INTERIOR UPHOLSTERY

150.00 80

TO REMOVE AND REFIX REVERSE SENSOR

120.00 50

TO RESPRAY AFFECTED AREAS

1,000.00 /

TO RENEW DAMAGED PARTS STRAIGHTENED & REPAIR AND ALIGNED ALL PARTS

1,200.00 800

4,120.24

288.42

4,408.66

GST 7% :

AMOUNT DUE :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-26281

102

P-2365.29

S.N-200.00

L-1960.00

4525.29

202

3620.