

Motoricarz Garage

53 Ubi Avenue 1#01-19 Paya Ubi Industrial Park Singapore 408934
Tel: 6844 4290 Fax: 6841 6043 Email: motoricarzgarage@gmail.com
Register No.: 53188526K

Estimate

Vehicle: GBG6918C

Make & Model: MITSUBISHI CANTER

No	Particular	Qty	Amount (\$)	
	<u>List Price</u>			
1	FRONT BUMPER <i>Distorted</i>	1PC	700.00	✓
2	FRONT BUMPER SIDE COVER <i>Missing</i>	2PCS	170.00	✓
3	FRONT BUMPER BRACKET <i>Best</i>	2PCS	510.00	✓
4	FRONT BUMPER REINFORCEMENT <i>new</i>	1PC	190.00	✓
5	FRONT GRILLE <i>Cracked</i>	1PC	550.00	✓
6	FRONT GRILLE EMBLEM <i>new</i>	1PC	75.00	✓
7	FRONT PANEL <i>Buckled</i>	1PC	1,155.00	✓
8	FRONT PANEL GARNISH <i>new</i>	1PC	501.00	✓
9	FRONT CORNER PANEL <i>Repld</i>	1PC	375.00	✓
10	FRONT HEADLAMP ASSY <i>Smashed.</i>	1PC	975.00	✓
11	FRONT WINDSCREEN <i>Cracked</i>	1PC	1,541.00	✓
12	FRONT WINDSCREEN RUBBER <i>new</i>	1PC	305.00	✓
13	FRONT WINDSCREEN OUTER PILLAR <i>? Repair</i>	1PC	378.00	✓
14	FRONT WINDSCREEN INNER PILLAR	1PC	378.00	✓
15	FRONT SIDE MIRROR (BIG) <i>? Missing</i>	1PC	296.00	✓
16	FRONT WIND MIRROR STAY	1PC	295.00	✓
17	ENGINE MOUNTING ?	1PC	135.00	✓
18	RH FRONT PILLAR <i>Distorted</i>	1PC	378.00	✓
19	RH FRONT PILLAR INNER GARNISH <i>Distorted</i>	1PC	207.00	✓
20	RH FRONT PILLAR ILOWER GARNISH <i>Distorted</i>	1PC	175.00	✓
21	FRONT VERTICAL CROSS MEMBER ?	1PC	550.00	?
22	FRONT LOWER CROSS MEMBER ?	1PC	975.00	?
23	STEERING COLUMN ?	1PC	2,755.00	?
24	STEERING COLUMN SHAFT ?	1PC	985.00	?
25	BRAKE PEDAL ?	1PC	300.00	?
26	ACCELERATOR PEDAL ?	1PC	389.00	?
27	CLUTCH PEDAL ?	1PC	295.00	?
28	RH SIDE DOOR <i>Distorted Buckled</i>	1PC	1,800.00	✓
29	DASHBOARD ASSY ?	1PC	950.00	?
30	FRONT RH DOOR PANEL <i>Distorted</i>	1PC	1,600.00	✓
31	FHFRONT RH DOOR HINGE <i>? Distorted</i>	1PC	95.00	✓
32	FRONT RH DOOR CHECKER	1PC	150.00	✓
33	FRONT RH DOOR GLASS <i>shattered</i>	1PC	725.00	✓
34	FRONT RH DOOR GLASS REGULATOR MOTOR ?	1PC	58.00	?

35	FRONT RH DOOR GLASS REGULATOR ?	1PC	580.00	?
36	FRONT RH DOOR RUBBER <i>cut</i>	1PC	195.00	✓
37	FRONT RH DOOR OUTER HANDLE <i>new</i>	1PC	195.00	+
38	FRONT RH DOOR LOCK <i>new</i>	1PC	355.00	✓
39	FRONT RH DOOR INNER TRIM BOARD <i>cut</i>	1PC	670.00	✓
40	FRONT STEP PANEL <i>Disturbed</i>	1PC	225.00	✓
41	FRONT STEP PANEL TOP GARNISH <i>Rebuilt</i>	1PC	145.00	✓
42	FRONT STEP PANEL INNER GARNISH <i>Rebuilt</i>	1PC	107.00	✓
43	STEERING RACK ?	1PC	1,540.00	?
44	KNUCKLE ?	1PC	1,912.00	?
45	BRAKE CALIPER ?	1PC	1,599.00	?
46	BRAKE CALIPER PIPE ?	1PC	286.00	?
47	LOWER ARM ?	1PC	750.00	?
48	ABSOBER ?	1PC	266.00	?
49	ABOSBER BODY HOUSING ?	1PC	480.00	?
50	ABS SENSOR ?	1PC	816.00	?
51	CABIN OPENER HOLDER ?	1PC	350.00	?
52	AIR CON PIPE ?	1PC	92.00	?
53	AIR CON DISCHARGE SUCTION PIPE ?	1PC	194.00	?
54	AIR METAL BOX HOUSING ?	1PC	450.00	?
55	CROSS MEMBER ?	1PC	713.00	?
56	FRONT RH RIM <i>Best</i>	1PC	<u>750.00</u>	
57	FRONT RH TYRES <i>Delivered</i>	1PC	250.00	180 (sw)
58	REAR RH RIM <i>Best</i>	1PC	<u>850.00</u>	
59	DIESEL TANK <i>Dented</i>	1PC	950.00	✓
60	DIESEL TANK HOLDER <i>Best</i>	1PC	300.00	✓
	Sub-Total cost for parts		35,936.00	
	Labour & MISC Charges			
1	LABOUR TO PANEL BEAT, REPAIR, REMOVE, REFIX, WELD & CUT		2,800.00	2200
2	LABOUR TO REMOVE, REFIX UNDERCARRAIGE		800.00	480
3	SPRAY PAINT TO ACCIDENT AREAS		1,600.00	1500
	Sub-Total Labour		5,200.00	
	Grand Total		41,136.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij

W/s 08/05/19.

Not Authorised

18 Days.

Excess to be advised