

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 053/IC/TCAC/CCR/2019
DATE : 07-MAY-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR QUEK CHOR CHYE
ADDRESS : 250 LORONG CHUAN
#13-01
S(556748)
TELEPHONE NO : 96864275

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1700017364-01
VEHICLE NO : SLP7344K
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2426286A
CHASSIS NO : SJNFEAJ11U1958314
MILEAGE : 26081 KM
DATE IN : 07/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 06/05/2019

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP7344K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	
3 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	
4 ZZ/001	REPLACE FRONT BUMPER,RIGHT GHEADLAMP,FRONT RIGHT FENDER & TRIM,FRONT RIGHT DOOR,RIGHT WING MIRROR		
5 ZZ/002	COVER ETC REPAIR PANELS	1000.00	
6 ZZ/003	REPLACE FRONT RIGHT RIM & CAP	30.00	
7 ZZ/004	RESPRAY FRONT BUMPER,FRONT RIGHT FENDER,FRONT RIGHT DOOR,RIGHT WING MIRROR COVER ETC	1000.00	
8 ZZ/005	QC, RETUNE & CONSULT CHECK		
9 ZZ/006	COMPLIMENTARY WASH & VACUUM		
	TOTAL LABOUR CHARGES	2563.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP7344K

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	WHEEL CAP	40342-BR01A			32.90	
2	FRONT RIGHT RIM	D0300-4EA1B			1231.90	
3	FENDER TRIM	63810-4EA0A	483.00			
4	RIGHT WING MIRROR COVER	96373-4EA8E	105.70			
5	DOOR TOP CHROME MOULDING	80282-4EA1B	100.70			
6	DOOR CENTER MOULDING	80820-4EA0A	188.90			
7	DOOR B-PILLAR TAPE	80812-4EA0A	29.90			
8	FRONT RIGHT DOOR	H0100-HVOMA	1104.80			
9	FRONT RIGHT FENDER	F3100-4EAMB	622.70			
10	RIGHT BUMPER BRACKET	62222-4EA0A	20.90			
11	FRONT BUMPER	62022-4EA0H	614.60			
12	RIGHT HEADLAMP	26010-4EA0A	559.00			
SUB TOTAL			3830.20	0.00	1264.80	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			766.04	0.00	0.00	
GRAND TOTAL			3064.16	0.00	1264.80	
OVERALL TOTAL			4328.96			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLP7344K

TOTAL LABOUR CHARGES	2563.00
TOTAL SPARE PARTS CHARGES	4328.96

GRAND TOTAL	6891.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.