



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R **11/05/2019**

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAxA.
Poh Kin.

Accident date: 07/05/2019

Estimated repair cost for vehicle no: SJL9500H TOYOTA VIOS J 1.5 A '08

CHASSIS: MR053HY9305090466

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Not New</i>		\$525.00 +
2	2	Front Bonnet Hinge <i>New</i>	\$50.00	\$100.00 +
3	2	Front Head Lamp <i>Both R & L</i>	\$425.00	\$850.00 +425
4	1	Front Bumper <i>torn</i>		\$485.00 ✓
5	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
6	2	Front Bumper Side Retainer <i>new</i>	\$102.00	\$204.00 -
7	1	Front Bumper Emblem Logo <i>new</i>		\$55.00 -
8	1	Front Bumper Number Plate <i>cracked</i>		\$50.00 -
9	1	Front Bumper Centre Lower Garnish <i>cracked</i>		\$86.00 -
10	1	Front Bumper Towing Cover <i>behind</i>		\$28.00 -
11	1	Front Bumper Grille <i>cracked</i>		\$255.00 2
12	1	Front Bumper Chrome <i>not in</i>		\$138.00 +
13	1	Front Bumper Reinforcement <i>Best</i>		\$395.00 2
14	2	Front Bumper Fog Lamp Cover <i>new</i>	\$68.00	\$136.00 +
15	1	Front Support Panel <i>Not in</i>		\$925.00 +.
16	1	Front Air-Con Condenser <i>2 New</i>		\$1,155.00 +
17	1	Front Radiator		\$1,819.00 +
18	1	Front Radiator Fan Motor Assy		\$486.00 +

1 Front Bumper Inner Center Bracket *behind* \$106 ✓

Subtotal :- **\$7,757.00**

2119
1589.25

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$280.00 +
To check wiring	\$100.00 30
Tuff kote	\$150.00 +
Panel beating	\$1,200.00 400
Spray painting	\$1,200.00 400

Subtotal :- \$2,930.00

Total:- \$10,687.00

Adrian Ly
H/s 13/05/19.
03 days.

total: 2419.25

H/s: 1.9K.

1.9K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: