

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 254T**AAD1905-050**

Not withark
61 Smp @ 2350

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 254T

VF1ABL15AUC282287

RENAULT

LATITUDE

3.5.19

AIG

20/11/2015

PART**LIST**

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	TOW COVER FRT
1	FRONT BRACE PANEL
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	WIPER RESERVOIR MOTOR
1	WIPER RESERVOIR
1	WIPER RESERVOIR NECK

\$	<i>Bu</i> 1,259.42 ✓
\$	<i>Sn</i> 181.75 X
\$	<i>Sn</i> 394.68 X
\$	<i>Dir</i> 151.41 ✓
\$	<i>Sn</i> 123.88 X
\$	<i>Sn</i> 472.83 X
\$	<i>Sn</i> 266.80 X
\$	<i>Sn</i> 207.21 X
\$	<i>N</i> 914.08 X
\$	<i>Sn</i> 1,184.43 X
\$	<i>N</i> 152.15 X
\$	<i>Bu</i> 783.83 ✓
\$	<i>Sn</i> 278.84
\$	<i>Sn</i> 15.79
\$	<i>Sn</i> 130.84
\$	<i>Sn</i> 28.61
\$	<i>N</i> 177.22
\$	<i>Sn</i> 1,707.78 } X
\$	<i>Sn</i> 225.36
\$	<i>Sn</i> 1,353.75
\$	<i>N</i> 615.90
\$	<i>N</i> 89.79
\$	<i>Sn</i> 270.06
\$	<i>Sn</i> 348.25
\$	<i>Sn</i> 136.11

Trans-cab Auto Services Pte Ltd**AAD1905-050**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 254T

TOTAL	\$	11,470.78
10%	\$	1,147.08
	\$	10,323.70

Special Nett

1	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	}
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	69.00	
1SET	RADIATOR GRILLE SCREW	\$	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	} X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1	WHEELARCH CLIP FRT RH	\$	30.50	}
1	FRONT RIGHT TYRE	\$	300.00	
1	FRONT RIGHT TYRE RIM	\$	380.00	

TOTAL	\$	1,056.00
--------------	-----------	-----------------

TOTAL PARTS	\$	11,379.70
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	4,200.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	4001
To transfer of front windscreen fittings and conduct water seepage test.	\$	170.00	X
To rust-proofing of the affected areas.	\$	170.00	301
To Check Electrical Lighting Concerned.	\$	170.00	101

Trans-cab Auto Services Pte Ltd**AAD1905-050**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 254T

To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00 X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00 X

TOTAL	\$	10,440.00
--------------	-----------	------------------

Over All Total	\$	21,819.70
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10 DAYS~~*2 day,*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: