

VEHICLE NO. SKS 1702X

VOLVO V40

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front Bumper <i>Re</i>		1782.00	
1	Bonnet <i>X Repair</i>	REPAIR	0.00	
1	RHS Front Fender <i>/ bmc</i>		982.00	
1	RHS Front Fender inner shield <i>/ Re</i>		182.00	
1	RHS Headlamp <i>X / Re</i>		1980.00	
1	RHS Side View Mirror assembly <i>/ Cut</i>		780.00	
1	RHS Front door <i>/ bmc</i>		1245.00	
1	RHS Front door lock <i>X NN</i>		250.00	
1	RHS Front door check strap <i>X / TN</i>		72.00	
2	RHS Front door hinges @42.00 <i>/ DT</i>		84.00	
1	RHS Front door weatherstrip <i>X / NN</i>		78.00	
1	RHS Front door outer handle <i>X</i>		172.00	
1	RHS Front door outer moulding (lower) <i>X</i>		98.00	
1	RHS Front door outer moulding (upper) <i>X</i>		122.00	
1	RHS Front door side black tape <i>/ Re</i>		64.00	
1	RHS Front door glass channel <i>X</i>		72.00	
1	RHS Front door glass channel rubber <i>X</i>		68.00	
1	RHS Front door regulator <i>?</i>		192.00	
1	RHS Front door regulator motor <i>X</i>		294.00	
1	RHS Front door inner trim board <i>X</i>		482.00	
1	RHS Rear door <i>/ DT</i>		1250.00	
1	RHS Rear door lock <i>X</i>	REFIX	0.00	
1	RHS Rear door check strap <i>X</i>	REFIX	0.00	
2	RHS Front door hinges @42.00 <i>X</i>	REFIX	0.00	
1	RHS Rear door outer handle <i>X</i>	REFIX	0.00	
1	RHS Rear door outer moulding (lower) <i>X</i>		98.00	
1	RHS Rear door outer moulding (upper) <i>X</i>	<i>NN</i>	122.00	
1	RHS Rear door glass channel <i>X</i>		72.00	
1	RHS Rear door glass channel rubber <i>X</i>		68.00	
1	RHS Rear door regulator <i>X</i>	REFIX	0.00	
1	RHS Rear door regulator motor <i>X</i>	REFIX	0.00	
1	RHS Rear door inner trim board <i>X</i>	REFIX	0.00	
1	RHS Front door pillar (A Pillar) <i>X</i>		798.00	
	PARTS C/F		11407.00	

VEHICLE NO. SKS 1702X

VOLVO V40

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT	
	PARTS (LIST ITEMS)	PARTS B/F		11407.00		
1	RHS Lower sill (rocker panel) <i>x repair.</i>			785.00		
1	RHS Front shock absorber ?			592.00		
1	RHS Front shock absorber coil spring ?			154.00		
1	RHS Front knuckle arm ?			378.00		
1	RHS Front lower arm ?			278.00		
1	RHS Front wheel bearing ?			242.00		
1	RHS Front stabiliser bar <i>x NN</i>			172.00		
				14008.00		
		less 10%		1400.80	10%	
				12607.20		
	SPECIAL NETT ITEMS					
1 set	Front Fender Inner Shield Clips /			40.00		
1set	Front Bumper clips /			60.00		
1	RHS Front door inner trim board clips /			60.00		
1	RHS Rear door inner trim board clips /			60.00		
1	RHS Front sports rim <i>cut</i>			1280.00		<i>350</i>
1	RHS Front tyre (80%) /			280.00		<i>140.</i>
1set	RHS Lower sill clips / <i>ML</i>			60.00		
				14447.20		

VEHICLE NO. SKS 1702X VOLVO V40

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (bonnet)	1500.00	1200.
3	To remove and replace RHS Front undercarriage parts (suspension system)	300.00	150.
4	To remove and replace/refix RHS front and rear doors inner trim, garnish etc	200.00	120
5	To check and refix wiring and focus headlamp beam	150.00	30
6	To conduct full computerised wheel alignment test	120.00	60
7	To clear fault code with diagnostic computer and reset to specifications	300.00	x NN
8	To perform anti-rust treatment on affected areas	240.00	60.
Labour Total :		4210.00	
TOTAL (PARTS & LABOUR):		18657.20	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

7 Days.

Lump sum repair.

After repair photos.

Gmo Qiang - 82880282

08/5/19.

Liik Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: