

22/03/2003

ASS. REC. BY:

REF: CS/CH9008102/ Es d3m2 Special Instruction:

Surveyor

STEVE

ASSIGNMENT (Office)

Date/Time: 8.5.19 14.55pm

From (Person): Elaine Cheong

of CT1

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SFE 462R

To Inspect Vehicle No: SKA 3035V

Tel: 81261237

at Workshop m/s Wearnes Automotive

of 28 Long Kae Road

Policy No: DMPCSN3008261901

Claim No: SNM19D202017C02

Sum Insured:

Excess:

D.O.A. 6.5.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

rup

Date/Time: 8.5.19 3.15p.m

Person Contacted:

Paul

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKA 3035 V -X

SFE 462R -X

Surveyor: Steve

REF: CT1

ASSIGNMENT

From: _____ Date: 22.5.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 3035U

at Workshop m/s WEARNS AUTOMOTIVE (Pvt)
of 45 Leng Kong Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: After lunch

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

sup

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SKA 3035U

Yr Regit: 28/4/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Infinity Q50

c.c. 1991

Colour: Dark Brown

A/C: Insured / Std / NI / NA

Sp. Reading: 57985

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BCAV 3720510168

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

225/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 6/5/19

D.O.I. 22/5/19

Survey held at

WEARNS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/5/19 MV-105K
Finalize (Gntm \$6,151.30, 4 days. (Richard Wines))
(\$7,964.50 Red - 56%)

RECEIVED 31 MAY 2019

Date/Time, File Pass to?

31/05/19

1)

Typsp

Date/Time, File Return to?

2)



: Preli. Report

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 6,151.30 P/P

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2019		08 May 2019 14:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEONG TZEH SHI, ID: S6984877Z		
Main Claimant:	SKA3035U	Date of Loss:	06/05/2019 17:00 - :59
Vehicle Reg. No.:	TP / SNM19D202017C02	Policy/Cover Note No.:	DMPCSN3008261901
Claim Type:	SFE4662R	Policy No. (Claimant):	SD19V04813
Vehicle Reg. No. (Insured):		Excess:	\$5750.00
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/05/2019]		

View All

Compose Case Mail

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

The information contained herein is correct as at 22 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/05/2019 14:19
Date Of Accident	06/05/2019 17:50
Exact Location Of Accident	ALONG CLEMENTI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA3035U
Insured/Policyholder	
Name Of Registered Owner	LEONG TZEH SHI
NRIC No	S6984877Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90118845
Alternative Phone No	OFFICE-90118845

Vehicle Particulars

Manufacturer	INFINITI
Model	Q50-2.0 T PREMIUM (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V04813
Cover Note Number	

Driver

Name of Driver	LEONG TZEH SHI
NRIC No	S6984877Z
Date Of Birth	22/09/1969
Occupation	INDOOR
Date Of Driving Pass	16/07/2004
Driving Experience	14 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90118845
Fax Number	
Contact Number	OFFICE 90118845

Address	85 PASIR RIS GROVE
	#07-10
Postcode	518212
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 427 CLEMENTI AVENUE 3 , POSTCODE: 120427 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7759999 - FAX NO: 67764246
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFE4662R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHB5047C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



SINGAPORE POLICE FORCE



T/20190506/2149

1 of 4

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

Report No. T/20190506/2149

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/05/2019 19:16	Vide Report No.:	Station Diary No.: 31
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LEONG TZEH SHI			Address: 85 PASIR RIS GROVE #07-10 SINGAPORE 518212		
ID Type / ID No.: NRIC NO / S6984877Z			Contact No.: Home/Office:		Mobile: 90118845
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 22/09/1969	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PRODUCT MANAGER			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 06/05/2019 17:50	Type of Location: Straight Road
Location: Along Road 1 CLEMENTI ROAD				
Clementi Road towards West Coast Road, near bus terminal				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFE4662R					Slightly Damaged	0
SHB5047C						0
SKA3035U					Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



SINGAPORE POLICE FORCE



T/20190506/2149

2 of 4

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

Report No. T/20190506/2149

CONTINUATION OF REPORT

Driver				
Name	SHARI BIN AHMAD		ID No.	S7331285Z
Related Vehicle	SFE4662R		Contact No.	96966487
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	LEONG TZE SHI		ID No.	S6984877Z
Related Vehicle	SKA3035U		Contact No.	90118845
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location, I was driving along Clementi Rd twds West Coast Road, on the left lane of the 3 lane road. As I was travelling, I noticed some road works ahead on the left lane, before the bus terminal on the left. I attempted to filter onto the middle lane due to the road works. As I was about to enter the middle lane, the taxi - SHB 5047C, sped up and horned, blocking me from entering the lane. After the taxi passed, I entered the middle lane and I was then behind SHB 5047C, while another vehicle SFE4662R was travelling behind me, on the middle lane.

As we were travelling past the bus terminal, the said taxi - SHB5047C, suddenly jammed his brakes and I was not able to stop in time. I collided into SHB5047C, SFE4662R also could not stop in time and collided into my vehicle. Head to rear collision for all three cars.

The driver of SFE4662R, Mr Sharin exit his vehicle, the driver taxi also exit his vehicle, he looked to be a Chinese man in his 60s. We all took pictures of the damage and the driver of the taxi expressed his unhappiness over me trying to enter the lane and honking at him hence he stopped his car. After that exchange, the taxi driver left abruptly without giving us a chance to get his particulars. Mr Sharin and I exchanged contact details and proceeded to lodge a police report regarding this matter

My vehicle suffered damage on my front & rear bumper, there are scratches and dents on the front portion, in bumper & grill area, some paint has also peeled off, there is also a big dent and some scratches on the rear bumper. I also have an in-car camera that was recording at that point of time. At this point of time both Mr Sharin and I is not experiencing any pain, however in the event that I do, I will seek medical treatment.



**SINGAPORE
POLICE FORCE**



T/20190506/2149

3 of 4

Police Station Of Origin:

Clementi NPP

427 Clementi Avenue 3 #01-456

SINGAPORE 120427

Tel No: 1800-7759999

Report No. T/20190506/2149

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20190506/2149

4 of 4

Report No. T/20190506/2149

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

D /

Sgt 3 KANG HUI MING, DON

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151



SINGAPORE
POLICE FORCE

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:

06/05/2019 19:16

Classification Of Case:

SN 40

SIGNATURE

Steve (LKK)

W. P. 1/2
4 days

P/P

Ry bef sy

22/5/19, 2.33 pm

SERVICE ESTIMATE

89623 - C00001

SL: SERVICE SALES - PC

Mr Leong Tzeh Shi
85 PASIR RIS GROVE
#07-10

Singapore 518212

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 07/05/2019

WIP.No. : 13435

Veh.In/Out:

*Tel.No. : Mobile: 90118845

Reg.No. : SKA3035U

Reg.date : 28/04/2017

Mileage : 0

Chassis No: JN1BCAV37Z0510168

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Leong Tzeh Shi

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

① 802	TO REPLACE FRT BUMPER, RADIATOR GRILLE, REAR BUMPER, REAR BUMPER BEAM, ETC	0	3600.00	0	3,600.00	\$ 1800	
-------	--	---	---------	---	----------	---------	--

② 800	TO PUTTY SPRAYPAINT ON FRT BUMPER, REAR BUMPER, REAR BOOTLID, ETC	0	2400.00	0	2,400.00	\$ 1600	
-------	---	---	---------	---	----------	---------	--

③ 802	TO REPLACE REAR LH EXHAUST ASS	0	1800.00	0	1,800.00	\$ X	
-------	--------------------------------	---	---------	---	----------	------	--

④ R06	FRT, REAR BUMPER PLATE & HODLE	0	120.00	0	120.00	\$ 60	
-------	--------------------------------	---	--------	---	--------	-------	--

⑤ 280	TO CHECK WIRING INCLUDE	0	390.00	0	390.00	\$	
-------	-------------------------	---	--------	---	--------	----	--

RESETTING OF ALL ELECTRICAL MODULES

⑤ BUMPER REAR Q50 2.0	1.0 EA	800.10		800.10	\$ 720.09	
REINFORCEMENT-BUMPER	1.0 EA	567.40		567.40	\$	
BRACKET-BUMPER RR LH	1.0 EA	30.80		30.80	\$	
BUMPER REAR LH BRACK	1.0 EA	30.80		30.80	\$	
BRACKET-BUMPER RR RH	1.0 EA	30.80		30.80	\$	
BUMPER REAR RH BRACK	1.0 EA	30.80		30.80	\$	

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4930 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

LKK Auto Consultants hence notify

the Repairer of the following:

- To repair before the spray painting
- To repair major parts during survey
- To repair subject to the survey
- To repair on a regular basis
- To repair subject to the survey
- To repair subject to the survey and subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

89623 - C00001 SL: SERVICE SALES - PC

Mr Leong Tzeh Shi
85 PASIR RIS GROVE
#07-10

Singapore 518212

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 07/05/2019

WIP No. : 13435

Veh.In/Out:

*Tel.No. : Mobile: 90118845

Reg.No. : SKA3035U

Reg.date. : 28/04/2017

Mileage : 0

Chassis No: JN1BCAV37Z0510168

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Leong Tzeh Shi

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	CLIP X ALL X MIN	5.0 EA	7.00			35.00 S	
	MUFFLER ASSY X	1.0 EA	1405.60			1,405.60 S	
	DIFFUSER ASSY X	1.0 EA	81.20			81.20 S	
	GASKET X	2.0 EA	16.80			33.60 S	
⑥	BUMPER FRT Q50 PREM	1.0 EA	685.80			685.80 S	617.22
	CLIP	1.0 EA	112.00			112.00 S	
	CLIP	1.0 EA	50.40			50.40 S	
	CLIP	1.0 EA	50.40			50.40 S	
	BUMPER FRT RETAINER	1.0 EA	56.00			56.00 S	
	BUMPER FRT RETAINER	1.0 EA	56.00			56.00 S	
	BRACKET-BUMPER FRT R	1.0 EA	14.00			14.00 S	
	BRACKET-BUMPER FRT L	1.0 EA	14.00			14.00 S	
	ENERGY ABSORBER FOAM	1.0 EA	168.60			168.60 S	
	REINFORCEMENT-BUMPER	1.0 EA	481.40			481.40 S	
⑦	GRILLE-RADIATOR Q50	1.0 EA	522.00			522.00 S	469.20
⑧	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10 S	494.19

Gross Total. 14,115.80

Labour Total	8,310.00
Parts Total	5,805.80
Package Total	0.00

Net.....	14,115.80
GST @ 7.0%	988.11
Total.....	15,103.90
Paid.....	0.00
Please Pay..	15,103.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date : 30/05/2019
 SINGAPORE 079909 WIP No. : 13435
 Veh.In/Out: 22/05/2019 29/05/2019

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Leong Tzeh Shi

*Tel.No. : 63896111
 Reg.No. : 9KA3035U
 Reg.date : 28/04/2017
 Mileage : 57,985
 Chassis No: JN18CAV37Z0510168

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
0	802 TO REPLACE FRT BUMPER, RADIATOR GRILLE, REAR BUMPER	0	1800.00	0		1,800.00	S
0	800 TO PUTTY SPRAYPAINT ON FRT BUMPER, REAR BUMPER	0	1600.00	0		1,600.00	S
2	R06 FRT, REAR NUMBER PLATE & HODLE	0	60.00	0		60.00	S
3	280 TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	390.00	0		390.00	S
5	5 BUMPER REAR Q50 2.0	1.0 EA	800.10	10		720.09	S
6	6 BUMPER FRT Q50 PREM	1.0 EA	685.80	10		617.22	S
7	7 GRILLE-RADIATOR Q50	1.0 EA	522.00	10		469.80	S
8	8 ADHESIVE SEALER FL2	1.0 EA	549.10	10		494.19	S

Gross Total. 6,151.30 ✓

Labour Total 3,850.00
 Parts Total 2,301.30
 Package Total 0.00

Net..... 6,151.30
 GST @ 7.0% 430.59
 Total..... 6,581.89
 Paid..... 0.00
 Please Pay.. 6,581.89

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119008102/ESD3N2
Date: 03/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3008261901
Claimant Vehicle No :	SKA3035U	Insured Vehicle No :	SFE4662R
Date of Loss:	06/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202017C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA3035U	Engine No:	274AE054693A
Make & Model:	INFINITI Q50, 2.0 T Premium (A)	Chassis No:	JN1BCAV37Z0510168
Reg. Date:	28/04/2017 (Man. Year: 2016)	Odometer:	57985 km
Colour:	Brown		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50RF18	Rear Tyre Size:	225/50RF18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,805.80	2,301.30	3,504.50	60.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,310.00	3,850.00	4,460.00	53.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,115.80	6,151.30	7,964.50	56.42
+ GST 7.00/7.00% (S\$)	988.11	430.59	557.52	56.42
Nett Amount (S\$)	15,103.91	6,581.89	8,522.02	56.42

INSPECTION

Date of Assignment:	08/05/2019	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road Singapore 159105
Date Inspected:	22/05/2019 Inspected At:	

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jun 2019)
 Parts: 143 INFINITI Q50 2.0 T Premium (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKA3035U)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR Q50 2.0	Broken	800.10 FS	*720.09 FS
2	1		*REINFORCEMENT-BUMPER	Not Necessary	567.40 FS	*- FS
3	1		*BRACKET-BUMPER RR LH	Not Necessary	30.80 FS	*- FS
4	1		*BUMPER REAR LH BRACK	Not Necessary	30.80 FS	*- FS
5	1		*BRACKET-BUMPER RR RH	Not Necessary	30.80 FS	*- FS
6	1		*BUMPER REAR RH BRACK	Not Necessary	30.80 FS	*- FS
7	5		*CLIP	Not Necessary	35.00 FS	*- FS
8	1		*MUFFLER ASSY	Not Necessary	1,405.60 FS	*- FS
9	1		*DIFFUSER ASSY	Not Necessary	81.20 FS	*- FS
10	2		*GASKET	Not Necessary	33.60 FS	*- FS
11	1		*BUMPER FRT Q50 PREM	Cut	685.80 FS	*617.22 FS
12	1		*BUMPER FRT BASE SPOI	Not Necessary	112.00 FS	*- FS
13	1		*CLIP	Not Necessary	50.40 FS	*- FS
14	1		*CLIP	Not Necessary	50.40 FS	*- FS
15	1		*BUMPER FRT RETAINER	Not Necessary	56.00 FS	*- FS
16	1		*BUMPER FRT RETAINER	Not Necessary	56.00 FS	*- FS
17	1		*BRACKET-BUMPER FRT R	Not Necessary	14.00 FS	*- FS
18	1		*BRACKET-BUMPER FRT L	Not Necessary	14.00 FS	*- FS
19	1		*ENERGY ABSORBER FOAM	Not Necessary	168.60 FS	*- FS
20	1		*REINFORCEMENT-BUMPER	Not Necessary	481.40 FS	*- FS
21	1		*GRILLE-RADIATOR Q50	Broken	522.00 FS	*469.80 FS
22	1		*ADHESIVE SEALER FL2	Necessary	549.10 FS	*494.19 FS
Total Parts (S\$)					5,805.80	2,301.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER RADIATOR GRILLE, REAR BUMPER, REAR BUMPER BEAM, ETC	New	3,600.00	1,800.00
2	TO PUTTY SPRAYPAINT ON FRT BUMPER, REAR BUMPER, REAR BOOTLID, ETC	New	2,400.00	1,600.00
3	TO REPLACE REAR LH EXHAUST ASS	New	1,800.00	0.00
4	FRT NUMBER PLATE & HODLE	New	120.00	60.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	390.00	390.00
Gross Labour Cost (S\$)			8,310.00	3,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >