

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 09 May 2019

## Preliminary Advice

Vehicle No	: SGL5415H	Accident Date	: 30/04/2019
Make	: TOYOTA VIOS	Policy No.	: MPC18A00240902
Assignment Date	: 08/05/2019	Excess	: S\$500.00
Date of Inspection	: 09/05/2019	Est. Duration of Repair	: 8 days
Inspection At	: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 6,456.30
Revised Amount	:S\$ 3,403.50
Check Items (Estimated)	:S\$ 776.50
Total	:S\$ 4,180.00
 Lump Sum Repair	:S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 16,000.00
COE / PARF Rebate	:S\$ 11,993.00
Salvage Value	:S\$
Margin for Repair	:S\$ 4,007.00

### Remarks

- (    ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- (    ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We are pending repair cost from repairer.