

ASS. REC. BY:

REF: CS/ICS19008106/ Rlsd321 Special Instruction:

: Surveyor

RASU1

ASSIGNMENT (Office)

From (Person): Crystabella TAN of ECICS Date/Time: 8-5-2019 15:28pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 5415H Insured:

at Workshop m/s BH Auto Service Tel: 65598944

of Blk 1 Sin Ming Industrial Estate Sector C

Policy No: MPC18A0040902 Claim No: DMPCL9001194 / CT

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A 30.4.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 8-5-19 3:45pm Person Contacted: Yun Shi

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGL 5415H - CS/ICS19008106 / VAD3 D.O.A - 30/04/2019
09/05/19	@ 17:02 pm revised IA to Crystabelle Tan via minimun
09/05/19	@ 17:04 pm mandate requested authorization to Crystabelle via via minimun.
13/05/19	@ 15:12 pm mandate approved by Crystabelle via minimun
13/05/19	@ 15:22 pm revert authorisation report to Wen zhong (reporter)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2019 10:34 Sendback Est	08 May 2019 10:59 \$46,456.30	08 May 2019 15:23 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SOH CHONG ZEH, ID: S8361455B, Email: ALANSOH3842@YAHOO.COM.SG		
Vehicle Reg. No.:	SGL5415H	Date of Loss:	30/04/2019 17:00 - :59 [151 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1900119H/CT	Policy/Cover Note No.:	MPC18A00240902 (Comprehensive)
		Excess:	S\$500.00
Reparer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/05/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 28 June 2019 3:14 PM
To: 'BHAS - Moo Wen Zheng'; Rasul (LKKAuto)
Cc: 'BHAS - Bernard Kee'; 'BHAS - Chan Yun Shi'
Subject: RE: FINALIZE SGL5415H OD ECICS DOA 30.04.2019

Dear Wen Zheng,

Final invoice and all supporting documents sent over to ECICS Limited.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Moo Wen Zheng [mailto:wenzheng.moo@bhauto.com.sg]
Sent: Friday, 28 June 2019 2:55 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Subject: RE: FINALIZE SGL5415H OD ECICS DOA 30.04.2019

Dear Shirley,

COR \$3,350.00 Before excess \$500 @ 8 days confirmed.

Thank you.

Best Regards,

Wen Zheng
Senior Claim Estimator



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117
SINGAPORE 575636 TEL: (65) 6559 8944 FAX: (65) 6269 2404
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

(W) +65-6559 8945 (F) +65-6269 2404 (HP) +65 9621 2084

(E) wenzheng.moo@bhauto.com.sg <http://www.bhauto.com.sg>

biSAFE,

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 28 June 2019 1:21 PM
To: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Subject: RE: FINALIZE SGL5415H OD ECICS DOA 30.04.2019

Dear Wen Zheng,

Please re-confirmed final fig \$ 3,350.00 @ 8 days of repairs before excess \$ 500/- & GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Moo Wen Zheng [<mailto:wenzheng.moo@bhauto.com.sg>]

Sent: Wednesday, 26 June 2019 11:27 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>;

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: RE: FINALIZE SGL5415H OD ECICS DOA 30.04.2019

Dear Rasul,

Kindly find the attached file for as per requested.

Thank you.

Best Regards,

Wen Zheng

Senior Claim Estimator



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117
SINGAPORE 575836 TEL: (65) 6559 8944 FAX: (65) 6269 2404
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

(W) +65-6559 8945 (F) +65-6269 2404 (HP) +65 9621 2084

(E) wenzheng.moo@bhauto.com.sg <http://www.bhauto.com.sg>



From: Rasul (LKKAuto) <Rasul@lkkauto.com>

Sent: Tuesday, 11 June 2019 10:58 AM

To: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>

Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>;

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: RE: FINALIZE SGL5415H OD ECICS DOA 30.04.2019

Hi Wen Zheng,

Kindly forward the towing receipt

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 13 May 2019 3:22 PM
To: 'BHAS - Moo Wen Zheng'
Cc: SUR; 'BHAS - Chan Yun Shi'; 'BHAS - Bernard Kee'
Subject: RE: SGL 5415H OD (ECICS) DOA - 30/04/2019

Dear Wen Zheng,

As Spoken, instructed by our client, please proceed at repair cost not exceeding \$4,000.00 (inclusive supplementary) to repair the insured vehicle **SGL 5415H (Excess \$ 500/-)** on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Moo Wen Zheng [mailto:wenzheng.moo@bhauto.com.sg]
Sent: Thursday, 9 May 2019 4:53 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>; BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>
Subject: RE: SGL 5415H OD (ECICS) DOA - 30/04/2019

Dear Shirley,

We are able to accept repair cost limit not exceeding \$4,000.00 before excess lump sum.

Kindly do update once authorise.

Thank you.

Best Regards,

Wen Zheng
Senior Claim Estimator



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/112/115/117
SINGAPORE 575636 TEL: (65) 6559 8944 FAX: (65) 6269 2404
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

(W) +65-6559 8945 (F) +65-6269 2404 (HP) +65 9621 2084

(E) wenzheng.moo@bhauto.com.sg <http://www.bhauto.com.sg>



From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 9 May 2019 4:34 PM
To: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SGL 5415H OD (ECICS) DOA - 30/04/2019

Hi Wen Zheng,

As spoken, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 4,000.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SGL5415H (DMPC1900119H/CT)

OD

Apr 30 2019 5:00PM

[SOH CHONG ZEH]

BH Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 13/05/2019 15:12 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4000.00) - SGL5415H - Claim Handler: Crystabelle Tan

Approved:4000.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 09 May 2019

Preliminary Advice

Vehicle No	: SGL5415H	Accident Date	: 30/04/2019
Make	: TOYOTA VIOS	Policy No.	: MPC18A00240902
Assignment Date	: 08/05/2019	Excess	: S\$500.00
Date of Inspection	: 09/05/2019	Est. Duration of Repair	: 8 days
Inspection At	: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,456.30
Revised Amount	:S\$	3,403.50
Check Items (Estimated)	:S\$	776.50
Total	:S\$	4,180.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	11,993.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,007.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer able to undertake the repair cost not exceeding \$ 4,000.00 on lump sum basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 09 May 2019

Preliminary Advice

Vehicle No	: SGL5415H	Accident Date	: 30/04/2019
Make	: TOYOTA VIOS	Policy No.	: MPC18A00240902
Assignment Date	: 08/05/2019	Excess	: S\$500.00
Date of Inspection	: 09/05/2019	Est. Duration of Repair	: 8 days
Inspection At	: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,456.30
Revised Amount	:S\$	3,403.50
Check Items (Estimated)	:S\$	776.50
Total	:S\$	4,180.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	11,993.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,007.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We are pending repair cost from repairer.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/04/2019 20:28
Date Of Accident	30/04/2019 17:00
Exact Location Of Accident	AIRPORT ROAD TURN TO EUNOS LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL5415H
Insured/Policyholder	
Name Of Registered Owner	SOH CHONG ZEH
NRIC No	S8361455B
Email Address	ALANSOH3842@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98524938
Alternative Phone No	OFFICE-98524938

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00240902
Cover Note Number	

Driver

Name of Driver	SOH CHONG ZEH
NRIC No	S8361455B
Date Of Birth	06/09/1983
Occupation	INDOOR
Date Of Driving Pass	12/12/2011
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98524938
Fax Number	
Contact Number	OFFICE-98524938
EEmail Address	ALANSOH3842@YAHOO.COM.SG

Address	BLK 720 TAMPINES STREET 72 #02-35
Postcode	520720
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF8627J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

AIRPORT ROAD

EUNOS LINK

(A) 86L5415H
(B) 8627J
G8FB627J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was at Airport Road, about to turn right into Eunos Link. I looked at my right side and there was no car at the moment, so I go straight and bumped into the car in front of me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: ERIC CHENG
NRIC/FIN No.: 72014112

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1455B

Vehicle Details

Vehicle No.: SGL5415H
Vehicle to be Exported: No
Intended Deregistration Date: 02 May 2019
Vehicle Make: TOYOTA
Vehicle Model: VIOS 1.5E A
Primary Colour: Silver
Manufacturing Year: 2006
Engine No.: 1NZX475462
Chassis No.: MR053HY4204203084
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$12,347.00
Original Registration Date: 20 Sep 2006
First Registration Date: 20 Sep 2006
Transfer Count: 1
Actual ARF Paid: \$13,582.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$25,759.00
COE Rebate Amount: \$11,993.00
Total Rebate Amount: \$11,993.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 May 2019

OK

16,000
11,993

4007



Toyota Vios 1.5A G (COE till 02/2024) \$25,800 \$5,370 /yr 19-Feb-2009 1,497 cc - Sedan Available

2.98% P.A. \$448 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims 16" Tyres. New Pioneer DVD An...

GV Credit Pte Ltd

Posted: 25-Apr-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A G (New 5-yr COE) \$25,800 \$5,150 /yr 13-May-2009 1,497 cc - Sedan Available

(Interest Rate From 3.18% Monthly Of \$444) 2 Owners Car, New 5 Years COE, Showroom Condition Guaranteed, Low Mileage Unit, Price Include New \$2K Paint/New Leather Seat, Rims) Comes With 6 Months Engine...

Car World Automobile

Posted: 24-Apr-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 12/2023) \$26,666 \$5,770 /yr 15-Dec-2008 1,497 cc 117,000 km Sedan Available

Owned This Car With 90% Loan Stated, Various Finance Plans To Cater Individuals Needs, Hassle Free With Workshop Service, Extended Warranty Available, One Of Our Company Carefully Selected Range Of CO...

Creative Auto

Posted: 24-Apr-2019 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Sell your Car for \$3,000 More

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3,000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - if we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!



Toyota Vios 1.5A E (COE till 04/2024) \$26,300 \$5,310 /yr 14-Apr-2009 1,497 cc - Sedan Available

100% No Gimmick On Price Only \$26,3K, Just Did Major Service Inc Engine Oil And ATF Oil. 100% No Repair Needed. Fully Stock Condition. Good Condition, Excellent Exterior And Neat Interior, Accident Fr...

Posted: 24-Apr-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (OPC) (COE till 12/2023) \$29,800 \$6,440 /yr 17-Dec-2008 1,497 cc 89,000 km Sedan Available

We Will Be At Singapore Expo Hall 4 On 27/04/19 & 28/04/19 For SPH Cars Carnival.

Carwey

Posted: 24-Apr-2019 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A J (COE till 12/2023) \$26,800 \$5,750 /yr 29-Dec-2008 1,497 cc 121,430 km Sedan Available

1 Owner, Low Mileage, In House Loan/Bank Available, At Low Monthly Instalment, Flexible Loan Available, Fully Agent Service, Low Mileage Done, 100% Accident Free. Trade In Are Welcome, View To Believ...

Posted: 24-Apr-2019 Tags: 2008 Toyota Vios, 2008 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A G (New 5-yr COE) \$27,800 \$5,550 /yr 23-Apr-2009 1,497 cc 130,000 km Sedan Available

We Are Full Loan Specialist, Over 50 Car To Choose From. Very Well Maintained, With All Wear And Tear Parts Recently Replaced. Fuel Economy Car Suitable For Daily Usage, Act Now Before It's Gone.

lasts

Posted: 23-Apr-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 01/2021) \$12,800 \$7,400 /yr 23-Jan-2006 1,497 cc - Sedan Available

Well Known For It's Fuel Economy, Reliable And Low On Maintenance, New Coat Of Paintwork And Free Servicing Will Be Given, STA Evaluation Can Be Arrange For Peace Of Mind Purchase, Easy Financing.

88 Motor Trading

Posted: 23-Apr-2019 Tags: 2006 Toyota Vios, 2006 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (New 5-yr COE) \$28,800 \$5,750 /yr 29-May-2009 1,497 cc 127,296 km Sedan Available

Evaluated By Vicom, Free 6 Months Maintenance And 1 Grooming.

Yong Lee Seng Motor

Posted: 23-Apr-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



Toyota Vios 1.5A E (COE till 03/2024) \$25,500 \$5,190 /yr 01-Apr-2009 1,497 cc 90,000 km Sedan Available

Cheapest Depreciation In The Car Market! Showroom Condition! Loan \$20K, \$406 x 59 Months! 100% Loan Approval! Original Toyota Paint! 120 Point Check I

Compare

Posted: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota



明輝汽車服務私人有限公司

BH AUTO SERVICES PTE LTD

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC18A00240902	Date of Loss:	30/04/2019
Vehicle Reg. No.:	SGL5415H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SOH CHONG ZEH		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	20/09/2006
Vehicle Colour:	SILVER		
Engine No:	1NZX475462	Chassis No:	MR053HY4204203084
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Remarks:	VEHICLE IN		
Present Location:	BH AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	2,896.30
Miscellaneous Items	290.00
Labour	2,070.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	6,456.30
+ GST 7.00% (S\$)	451.94
Nett Amount (S\$)	6,908.24

This claim is handled by: MOO WEN ZHENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 May 2019)

Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Gino Rpl
15/5/19

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>neu</i>	0.00	0.00	*160.00 F
2	1		*Bonnet hinge LH <i>bt</i>	0.00	0.00	*15.00 F
3	1		*Bonnet hinge RH <i>bt</i>	0.00	0.00	*15.00 F
4	1		*Bonnet lock assy <i>bt</i>	0.00	0.00	*20.00 F
5	1		*Bonnet stopper LH <i>neu</i>	0.00	0.00	*7.00 F
6	1		*Bonnet stopper RH <i>neu</i>	0.00	0.00	*7.00 F
	1		*Bonnet weatherstrip <i>neu</i>	0.00	0.00	*10.00 F
8	1		*Bonnet insulator <i>bt</i>	0.00	0.00	*45.00 F
9	10		*Bonnet insulator clip <i>neu</i> X10PCS	0.00	0.00	*15.00 F
10	1		*Bonnet stand retainer <i>X</i>	0.00	0.00	*3.00 F
11	1		*Front grille <i>CRA</i>	0.00	0.00	*95.00 F
12	1		*Front grille stopper LH <i>neu</i>	0.00	0.00	*7.00 F
13	1		*Front grille stopper RH <i>neu</i>	0.00	0.00	*7.00 F
14	1		*Headlamp assy LH <i>pro</i>	0.00	0.00	*100.00 F
15	1		*Headlamp assy RH <i>scr</i>	0.00	0.00	*100.00 F
16	1		*Front support panel <i>bt</i>	0.00	0.00	*200.00 F
17	1		*Front brace panel <i>bt</i>	0.00	0.00	*25.00 F
18	1		*Front bumper <i>neu</i>	0.00	0.00	*100.00 F
19	1		*Front bumper side retainer LH <i>neu</i>	0.00	0.00	*10.00 F
20	1		*Front bumper side retainer RH <i>neu</i>	0.00	0.00	*10.00 F
21	12		*Front bumper clip <i>neu</i> X12PCS	0.00	0.00	*12.00 F
22	1		*Front bumper reinforcement <i>bt</i>	0.00	0.00	*110.00 F
23	1		*Front bumper reinforcement bracket LH <i>bt</i>	0.00	0.00	*18.00 F
	1		*Front bumper lower grille <i>?</i>	0.00	0.00	*15.00 F
25	1		*Front bumper fog lamp garnish LH <i>?</i>	0.00	0.00	*20.00 F
26	1		*Front bumper fog lamp garnish RH <i>?</i>	0.00	0.00	*20.00 F
27	1		*Horn (High Pitch) <i>X</i>	0.00	0.00	*25.00 F
28	1		*Aircon condenser <i>?</i> (OEM)	0.00	0.00	*130.00 F
29	1		*Radiator <i>?</i>	0.00	0.00	*250.00 F
30	1		*Radiator fan cowling <i>?</i>	0.00	0.00	*85.00 F
31	1		*Radiator fan blade <i>?</i>	0.00	0.00	*40.00 F
32	1		*Radiator fan motor <i>X</i>	0.00	0.00	*120.00 F
33	1		*Radiator air duct RH <i>X</i>	0.00	0.00	*45.00 F
34	1		*Radiator top hose <i>X</i>	0.00	0.00	*20.00 F
35	1		*Engine inlet manifold <i>X</i>	0.00	0.00	*180.00 F
36	1		*Air cleaner assembly <i>X</i>	0.00	0.00	*200.00 F
37	1		*Windscreen wiper tank <i>?</i>	0.00	0.00	*30.00 F
38	1		*Wiper grille garnish LH <i>neu</i>	0.00	0.00	*45.00 F
39	1		*Wiper grille garnish RH <i>X</i>	0.00	0.00	*45.00 F
40	1		*Transmission and engine mounting set <i>X</i>	0.00	0.00	*145.00 F
41	1		*Front fender LH <i>bt</i>	0.00	0.00	*90.00 F
42	1		*Front fender shield LH <i>?</i>	0.00	0.00	*25.00 F

BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	12		*Front fender shield clip <i>see ✓</i> X12PCS	0.00	0.00	*12.00 F
Sub Total (\$\$)						2,633.00
+ Margin on L,N Items 10.00% (\$\$)						263.30
Total Parts (\$\$)						2,896.30

F=Franchise part.

BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Part : \$ 2068.00

S/N : \$ 215.00

Labour : \$ 1910.00

Total : \$ 4193.00 - 20%

= \$ 3354.40

L/S - 3,350 8 days

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Fender inner seal gum <i>new</i>	40 80.00
2	1	Front number plate with casing <i>new</i>	35 50.00
3	1	Radiator coolant <i>new</i>	60 80.00
4	1	Top up aircon gas R134 <i>new</i>	80 80.00
<i>\$215.00</i>			
Sub Total (S\$)			290.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Provide skill labour & material to putty all damaged parts & panel to respray with 2k paint with oven spray booth facilities	New	900 1,200.00
<u>Labour Items</u>			
2	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts	New	800 1,400.00
3	Provide skill labour to disconnect and check electrical wiring	New	30 50.00
4	Provide skill labour to remove and replace aircon condenser, pipes and radiator	New	100 120.00
5	Provide skill labour to mount vehicle onto chassis alignment bench	New	X 250.00
6	Provide skill labour to remove and replace engine, transmission mounting and related part	New	X 150.00
7	Towing charges (TOW FROM ACCIDENT SCENE TO WORKSHOP)	New	<i>receipt ?</i> 100.00
<i>\$1910.00</i>			<i>\$80</i>
Gross Labour Cost (S\$)			3,270.00

BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
8 days
HS
09/05/19 @ 1450
EXCESS: 500
REVERT
Resurvey after repair



明輝汽車服務私人有限公司

BH AUTO SERVICES PTE LTD

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC18A00240902	Date of Loss:	30/04/2019
Vehicle Reg. No.:	SGL5415H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SOH CHONG ZEH		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	20/09/2006
Vehicle Colour:	SILVER		
Engine No:	1NZX475462	Chassis No:	MR053HY4204203084
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Remarks:	VEHICLE IN		
Present Location:	BH AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	2,896.30
Miscellaneous Items	290.00
Labour	2,070.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	6,456.30
+ GST 7.00% (S\$)	451.94
Nett Amount (S\$)	6,908.24

This claim is handled by: MOO WEN ZHENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 08 May 2019)

Parts: 143

TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>new</i>	0.00	0.00	*160.00 F
2	1		*Bonnet hinge LH <i>bt</i>	0.00	0.00	*15.00 F
3	1		*Bonnet hinge RH <i>bt</i>	0.00	0.00	*15.00 F
4	1		*Bonnet lock assy <i>bt</i>	0.00	0.00	*20.00 F
5	1		*Bonnet stopper LH <i>new</i>	0.00	0.00	*7.00 F
6	1		*Bonnet stopper RH <i>new</i>	0.00	0.00	*7.00 F
7	1		*Bonnet weatherstrip <i>new</i>	0.00	0.00	*10.00 F
8	1		*Bonnet insulator <i>new</i>	0.00	0.00	*45.00 F
9	10		*Bonnet insulator clip <i>new</i> X10PCS	0.00	0.00	*15.00 F
10	1		*Bonnet stand retainer <i>X sur</i>	0.00	0.00	*3.00 F
11	1		*Front grille <i>new</i>	0.00	0.00	*95.00 F
12	1		*Front grille stopper LH <i>new</i>	0.00	0.00	*7.00 F
13	1		*Front grille stopper RH <i>new</i>	0.00	0.00	*7.00 F
14	1		*Headlamp assy LH <i>new</i>	0.00	0.00	*100.00 F
15	1		*Headlamp assy RH <i>new</i>	0.00	0.00	*100.00 F
16	1		*Front support panel <i>bt</i>	0.00	0.00	*200.00 F
17	1		*Front brace panel <i>bt</i>	0.00	0.00	*25.00 F
18	1		*Front bumper <i>new</i>	0.00	0.00	*100.00 F
19	1		*Front bumper side retainer LH <i>new</i>	0.00	0.00	*10.00 F
20	1		*Front bumper side retainer RH <i>new</i>	0.00	0.00	*10.00 F
21	12		*Front bumper clip <i>new</i> X12PCS	0.00	0.00	*12.00 F
22	1		*Front bumper reinforcement <i>bt</i>	0.00	0.00	*110.00 F
23	1		*Front bumper reinforcement bracket LH <i>bt</i>	0.00	0.00	*18.00 F
24	1		*Front bumper lower grille <i>?</i>	0.00	0.00	*15.00 F
25	1		*Front bumper fog lamp garnish LH <i>?</i>	0.00	0.00	*20.00 F
26	1		*Front bumper fog lamp garnish RH <i>?</i>	0.00	0.00	*20.00 F
27	1		*Horn (High Pitch) <i>X sur</i>	0.00	0.00	*25.00 F
28	1		*Aircon condenser <i>?</i> (OEM)	0.00	0.00	*130.00 F
29	1		*Radiator <i>?</i>	0.00	0.00	*250.00 F
30	1		*Radiator fan cowl <i>?</i>	0.00	0.00	*85.00 F
31	1		*Radiator fan blade <i>?</i>	0.00	0.00	*40.00 F
32	1		*Radiator fan motor <i>X</i>	0.00	0.00	*120.00 F
33	1		*Radiator air duct RH <i>X</i>	0.00	0.00	*45.00 F
34	1		*Radiator top hose <i>X</i>	0.00	0.00	*20.00 F
35	1		*Engine inlet manifold <i>X</i>	0.00	0.00	*180.00 F
36	1		*Air cleaner assembly <i>X</i>	0.00	0.00	*200.00 F
37	1		*Windscreen wiper tank <i>X</i>	0.00	0.00	*30.00 F
38	1		*Wiper grille garnish LH <i>X</i>	0.00	0.00	*45.00 F
39	1		*Wiper grille garnish RH <i>X</i>	0.00	0.00	*45.00 F
40	1		*Transmission and engine mounting set <i>X</i>	0.00	0.00	*145.00 F
41	1		*Front fender LH <i>bt</i>	0.00	0.00	*90.00 F
42	1		*Front fender shield LH <i>?</i>	0.00	0.00	*25.00 F

BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
43	12		*Front fender shield clip <i>all ✓</i> X12PCS	0.00	0.00	*12.00 F
F=Franchise part.						
Sub Total (S\$)						2,633.00
+ Margin on L,N Items 10.00% (S\$)						263.30
Total Parts (S\$)						2,896.30

BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Fender inner seal gum <i>ne</i>	<i>40</i> 80.00
2	1	Front number plate with casing <i>cha</i>	<i>35</i> 50.00
3	1	Radiator coolant <i>ne</i>	<i>60</i> 80.00
4	1	Top up aircon gas R134 <i>ne</i>	80.00
Sub Total (S\$)			290.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Provide skill labour & material to putty all damaged parts & panel to respray with 2k paint with oven spray booth facilities	New	<i>900</i> 1,200.00
Labour Items			
2	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts	New	<i>800</i> 1,400.00
3	Provide skill labour to disconnect and check electrical wiring	New	<i>30</i> 50.00
4	Provide skill labour to remove and replace aircon condenser, pipes and radiator	New	<i>100</i> 120.00
5	Provide skill labour to mount vehicle onto chassis alignment bench	New	<i>125</i> 250.00
6	Provide skill labour to remove and replace engine, transmission mounting and related part	New	<i>125</i> 150.00
7	Towing charges (TOW FROM ACCIDENT SCENE TO WORKSHOP)	New	<i>receipt ?</i> 100.00 <i>80</i>
Gross Labour Cost (S\$)			3,270.00

BH Auto Services Pte Ltd/SGL5415H/08/05/2019 10:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
13/5/19
8 days
HS
09/05/19 @ 1450
EXCESS: 500
REVERT
Resurvey after repair

BH Auto Services Pte Ltd

GST No: 200817912K
Blk 1, Sector C, 801-111/113/115/117
Sin Ming Industrial Estate
Singapore - 575636
Mobile no: 6597478383
Email: bernard.kee@bhauto.com.sg

Customer :

ECICS LIMITED
Singapore -

Standard Rated Invoice No:

A 550 R

Dated:

June 18, 2018

Make and Model :

Model/Term: Of Payment:

Due upon receipt

Mileage :

Chassis/ Car Plate No :
/ BGL5415H

S No	Product	Description	Qty	Price(SGD)	Amount (SGD)
1	TOWING	TOWING FEES	1	80.00	80.00
Sub Total (SGD)					85.00
GST 7% (7%)					5.80
Total (SGD)					85.80

Amount in words :

Eighty Five and Sixty cents Singapore Dollar (SGD) Only

Declaration:

We declare that this Standard Rated Invoice shows the actual price of the goods described and that all particulars are true and correct.

For BH Auto Services Pte Ltd

Authorized Signatory

Income Terms:
TermsNotes:
Notes

Receiver Chop & Sign

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2019 10:34 Sendback Est	08 May 2019 10:59 S\$6,456.30	08 May 2019 15:23 Edit Adj Rpt	S\$3,350.00 Edit Estimates	S\$3,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SOH CHONG ZEH , ID: S8361455B, Email: ALANSOH3842@YAHOO.COM.SG									
Vehicle Reg. No.: SGL5415H		Date of Loss: 30/04/2019 17:00 - :59 [151 Months and 10 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DMPC1900119H/CT		Policy/Cover Note No.: MPC18A00240902 (Comprehensive)							
		Excess: S\$500.00							
Repairer: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
ECICS (13/05/2019): Alert - Adj Mandate Approved (S\$4000.00) - SGL5415H - Claim Handler: Crystabelle...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGL5415H (DMPC1900119H/CT)

OD

Apr 30 2019 5:00PM

[SOH CHONG ZEH]

BH Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
1	08/05/19 10:59	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/19 16:23	Adjuster Immediate Advice	 Load HTM	
2	09/05/19 17:02	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/19 16:08	General View	 Load JPG	☒
2	10/05/19 16:08	General View	 Load JPG	☒
3	10/05/19 16:08	General View	 Load JPG	☒
4	10/05/19 16:08	General View	 Load JPG	☒
5	10/05/19 16:08	General View	 Load JPG	☒
6	10/05/19 16:08	General View	 Load JPG	☒
7	10/05/19 16:08	General View	 Load JPG	☒
8	10/05/19 16:08	General View	 Load JPG	☒
9	10/05/19 16:08	General View	 Load JPG	☒
10	10/05/19 16:08	General View	 Load JPG	☒
11	10/05/19 16:08	General View	 Load JPG	☒
12	10/05/19 16:08	General View	 Load JPG	☒
13	10/05/19 16:08	General View	 Load JPG	☒
14	10/05/19 16:08	General View	 Load JPG	☒
15	10/05/19 16:08	General View	 Load JPG	☒
16	10/05/19 16:08	General View	 Load JPG	☒
17	10/05/19 16:08	General View	 Load JPG	☒
18	10/05/19 16:08	General View	 Load JPG	☒
19	10/05/19 16:08	General View	 Load JPG	☒
20	10/05/19 16:08	General View	 Load JPG	☒
21	10/05/19 16:08	General View	 Load JPG	☒
22	10/05/19 16:08	General View	 Load JPG	☒
23	10/05/19 16:08	General View	 Load JPG	☒
24	10/05/19 16:08	General View	 Load JPG	☒
25	10/05/19 16:08	General View	 Load JPG	☒
26	10/05/19 16:08	General View	 Load JPG	☒
27	10/05/19 16:08	General View	 Load JPG	☒
28	10/05/19 16:08	General View	 Load JPG	☒
29	10/05/19 16:08	General View	 Load JPG	☒
30	10/05/19 16:08	General View	 Load JPG	☒
31	10/05/19 16:08	General View	 Load JPG	☒
32	10/05/19 16:08	General View	 Load JPG	☒
33	10/05/19 16:08	General View	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	BH Auto Services Pte Ltd (Sin Ming)	Thumbnail	Print
				☒
34	10/05/19 16:08	General View	 Load JPG	☒
35	10/05/19 16:08	General View	 Load JPG	☒
36	10/05/19 16:08	General View	 Load JPG	☒
37	10/05/19 16:08	General View	 Load JPG	☒
38	10/05/19 16:08	General View	 Load JPG	☒
39	10/05/19 16:08	General View	 Load JPG	☒
40	10/05/19 16:08	General View	 Load JPG	☒
41	10/05/19 16:08	General View	 Load JPG	☒
42	10/05/19 16:08	General View	 Load JPG	☒
43	10/05/19 16:08	General View	 Load JPG	☒
44	10/05/19 16:08	General View	 Load JPG	☒
45	10/05/19 16:08	General View	 Load JPG	☒
46	10/05/19 16:08	General View	 Load JPG	☒
47	10/05/19 16:08	General View	 Load JPG	☒
48	10/05/19 16:08	General View	 Load JPG	☒
49	10/05/19 16:08	General View	 Load JPG	☒
50	10/05/19 16:08	General View	 Load JPG	☒
51	10/05/19 16:08	General View	 Load JPG	☒
52	10/05/19 16:08	General View	 Load JPG	☒
53	10/05/19 16:08	General View	 Load JPG	☒
54	10/05/19 16:08	General View	 Load JPG	☒
55	10/05/19 16:08	General View	 Load JPG	☒
56	10/05/19 16:08	General View	 Load JPG	☒
57	10/05/19 16:08	General View	 Load JPG	☒
58	10/05/19 16:08	General View	 Load JPG	☒
59	10/05/19 16:08	General View	 Load JPG	☒
60	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
61	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
62	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
63	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
64	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
65	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
66	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
67	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
68	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
69	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
70	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
71	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
72	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
73	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
74	28/06/19 10:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/19 16:18	SLG 5415H GIA.pdf	 Load PDF	
2	09/05/19 16:18	ESTIMATE.pdf	 Load PDF	
3	28/06/19 15:32	ESTIMATE MARKED.pdf	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS19008106/R1SD3E2

Date: 10/07/2019

REFERENCE

Insured/Claimant: SOH CHONG ZEH Policy No: MPC18A00240902
Date of Loss: 30/04/2019 Nature of Claim: OD Claim No: DMPC1900119H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGL5415H**
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX475462
Reg. Date: 20/09/2006 (Man. Year: 2006) Chassis No: MR053HY4204203084
Colour: Grey Odometer: 239390 km
Engine Capacity: 1497 cc
Market Value/New Car Price: S\$16,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R14 Rear Tyre Size: 185/60 R14
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,896.30	2,068.00	828.30	28.60
Miscellaneous Items	290.00	215.00	75.00	25.86
Labour	2,070.00	1,010.00	1,060.00	51.21
Paintwork Labour	1,200.00	900.00	300.00	25.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,456.30	4,193.00	2,263.30	35.06
Approved Total (Overridden) (S\$)		3,350.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	6,456.30	2,850.00	3,606.30	55.86
+ GST 7.00/7.00% (S\$)	451.94	199.50	252.44	55.86
Nett Amount (S\$)	6,908.24	3,049.50	3,858.74	55.86

INSPECTION

Date of Assignment: 08/05/2019 Present Location:
Date Inspected: 09/05/2019 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C,
#01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGL5415H)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Bonnet (WCP)	Buckled	160.00 F	*160.00 F
2	1		*Bonnet hinge LH (WCP)	Bent	15.00 F	*15.00 F
3	1		*Bonnet hinge RH (WCP)	Bent	15.00 F	*15.00 F
4	1		*Bonnet lock assy (WCP)	Bent	20.00 F	*20.00 F
5	1		*Bonnet stopper LH (WCP)	Necessary	7.00 F	*7.00 F
6	1		*Bonnet stopper RH (WCP)	Necessary	7.00 F	*7.00 F
7	1		*Bonnet weatherstrip (WCP)	Necessary	10.00 F	*10.00 F
8	1		*Bonnet insulator (WCP)	Deformed	45.00 F	*45.00 F
9	10		*Bonnet insulator clip (WCP)	Necessary	15.00 F	*15.00 F
10	1		*Bonnet stand retainer (WCP)	Serviceable	3.00 F	*- F
11	1		*Front grille (WCP)	Cracked	95.00 F	*95.00 F
12	1		*Front grille stopper LH (WCP)	Necessary	7.00 F	*7.00 F
13	1		*Front grille stopper RH (WCP)	Necessary	7.00 F	*7.00 F
14	1		*Headlamp assy LH (WCP)	Broken	100.00 F	*100.00 F
15	1		*Headlamp assy RH (WCP)	Scratched	100.00 F	*100.00 F
16	1		*Front support panel (WCP)	Bent	200.00 F	*200.00 F
17	1		*Front brace panel (WCP)	Bent	25.00 F	*25.00 F
18	1		*Front bumper (WCP)	Deformed	100.00 F	*100.00 F
19	1		*Front bumper side retainer LH (WCP)	Necessary	10.00 F	*10.00 F
20	1		*Front bumper side retainer RH (WCP)	Necessary	10.00 F	*10.00 F
21	12		*Front bumper clip (WCP)	Necessary	12.00 F	*12.00 F
22	1		*Front bumper reinforcement (WCP)	Bent	110.00 F	*110.00 F
23	1		*Front bumper reinforcement bracket LH (WCP)	Bent	18.00 F	*18.00 F
24	1			Serviceable	15.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*Front bumper lower grille (WCP)			
25	1		*Front bumper fog lamp garnish LH (WCP)	Serviceable	20.00 F	*- F
26	1		*Front bumper fog lamp garnish RH (WCP)	Serviceable	20.00 F	*- F
27	1		*Horn (High Pitch) (WCP)	Serviceable	25.00 F	*- F
28	1		*Aircon condenser (OEM)(WCP)	Bent	130.00 F	*130.00 F
29	1		*Radiator (WCP)	Bent	250.00 F	*250.00 F
30	1		*Radiator fan cowling (WCP)	Cracked	85.00 F	*85.00 F
31	1		*Radiator fan blade (WCP)	Serviceable	40.00 F	*- F
32	1		*Radiator fan motor (WCP)	Serviceable	120.00 F	*- F
33	1		*Radiator air duct RH (WCP)	Serviceable	45.00 F	*- F
34	1		*Radiator top hose (WCP)	Serviceable	20.00 F	*- F
35	1		*Engine inlet manifold (WCP)	Cracked	180.00 F	*180.00 F
36	1		*Air cleaner assembly (WCP)	Serviceable	200.00 F	*- F
37	1		*Windscreen wiper tank (WCP)	Serviceable	30.00 F	*- F
38	1		*Wiper grille garnish LH (WCP)	Cut	45.00 F	*45.00 F
39	1		*Wiper grille garnish RH (WCP)	Serviceable	45.00 F	*- F
40	1		*Transmission and engine mounting set (WCP)	Serviceable	145.00 F	*- F
41	1		*Front fender LH (WCP)	Bent	90.00 F	*90.00 F
42	1		*Front fender shield LH (WCP)	Serviceable	25.00 F	*- F
43	12		*Front fender shield clip (WCP)	Necessary	12.00 F	*12.00 F
F=Franchise part.						
Sub Total (S\$)					2,633.00	1,880.00
+ Margin on L,N Items 10.00/10.00% (S\$)					263.30	188.00
Total Parts (S\$)					2,896.30	2,068.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Fender inner seal gum (NECESSARY)	80.00	40.00
2	1	Front number plate with casing (CRACKED)	50.00	35.00
3	1	Radiator coolant (NECESSARY)	80.00	60.00
4	1	Top up aircon gas R134 (NECESSARY)	80.00	80.00
Sub Total (\$\$)			290.00	215.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Provide skill labour & material to putty all damaged parts & panel to respray with 2k paint with oven spray booth facilities	New	1,200.00	900.00
Labour Items				
2	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts	New	1,400.00	800.00
3	Provide skill labour to disconnect and check electrical wiring	New	50.00	30.00
4	Provide skill labour to remove and replace aircon condenser, pipes and radiator	New	120.00	100.00
5	Provide skill labour to mount vehicle onto chassis alignment bench	New	250.00	0.00
6	Provide skill labour to remove and replace engine, transmission mounting and related part	New	150.00	0.00
7	Towing charges (TOW FROM ACCIDENT SCENE TO WORKSHOP)	New	100.00	80.00
Gross Labour Cost (\$\$)			3,270.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >