

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Cuttilan Tuan Azhari BLK 149 BISHAN ST 11 #09-19 SINGAPORE 570149 Contact No Mobile: 96645013	Cust No/Name	/CUTTILAN TUAN AZHARI
	Reg No/Reg Date	SKZ8201S*1F / 04/02/201
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY1AGU004034
	Engine No	4A92CG5829
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	07/05/2019/ 16:03	QUE	261 / Edwin Caina	39516			
Description of Goods / Services						Qty	Unit Price	Disc% Amount
E PNT88000								3300.00
RENEW & RE-ALIGN RR DAMAGED PORTION:								
-RENEW RR BUMPER , BOOTLID & RR END PNL								
-REPAIR RR FLR PNL , RR FENDER LH & RR FENDER RH								2520.00
E PNT98000								
RESpray RR BUMPER , RR END PNL , RR FLR PNL , RR FENDER LH ,								
RR FENDER RH & BOOTLID								120.00
E PNT88000								
REMOVE & REFIT BOOTLID COMPONENT								120.00
E PNT88000								
REMOVE & REFIT RR FLR BOARD, TRIM & CARPET								50.00
A 54900099								
CHECK WIRING & ELECTRICAL SYSTEM								200.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								120.00
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY								
SUPPLY RR NUMBER PLATE WITH CASING								100.00
E PNT88000								
REMOVE & REFIT REVERSE SENSOR								220.00
M SUNDRY								
SUPPLY REVERSE SENSOR								40.00
M SUNDRY								
SUPPLY C&C BADGE								50.00
M SUNDRY								
Sundries								
M	FACE,RR BUMPER	1.00	852.00	00.00				852.00
M	COVER,RR BUMPER	1.00	20.00	00.00				20.00
M	CLIP,ENG ROOM COVER	8.00	2.00	00.00				16.00
M	BRKT,R/BMPR FACE SUPT,LH	1.00	17.00	00.00				17.00
M	BRKT,R/BMPR FACE SUPT,RH	1.00	17.00	00.00				17.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Cuttilan Tuan Azhari BLK 149 BISHAN ST 11 #09-19 SINGAPORE 570149 Contact No Mobile: 96645013	Cust No/Name	/CUTTILAN TUAN AZHARI
	Reg No/Reg Date	SKZ8201S*1F / 04/02/201
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY1AGU004034
	Engine No	4A92CG5829
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	D00 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	07/05/2019/ 16:03	QUE	261 / Edwin Caina	39516			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REINFORCEMENT,RR BUMPER	bt ✓			1.00	231.00	00.00	231.00
M	BRACKET,LICENSE PLATE LAMP	ms ✓			2.00	13.00	00.00	26.00
M	PANEL,TRUNK LID	bt ✓			1.00	760.00	00.00	760.00
M	HINGE,TRUNK LID,LH	?			1.00	92.00	00.00	92.00
M	HINGE,TRUNK LID,RH	?			1.00	92.00	00.00	92.00
M	WEATHERSTRIP,TRUNK LID	ms ✓			1.00	182.00	00.00	182.00
M	GAS SPRING,TRUNK LID	?			2.00	66.00	00.00	132.00
M	LATCH,TRUNK LID	?			1.00	74.00	00.00	74.00
M	MARK,THREE-DIA	ms ✓			1.00	51.00	00.00	51.00
M	MARK,LANCER	ms ✓			1.00	54.00	00.00	54.00
M	PANEL,RR END	bt ✓			1.00	556.00	00.00	556.00
M	TRIM,TRUNK ROOM RR END	at ✓			1.00	164.00	00.00	164.00
M	CLIP,RR END TRIM	ms ✓			2.00	3.00	00.00	6.00
M	LAMP ASSY,COMB,RR LH	?			1.00	365.00	00.00	365.00
M	LAMP ASSY,COMB,RR RH	?			1.00	365.00	00.00	365.00
M	LAMP ASSY,TAIL,LH	?			1.00	191.00	00.00	191.00
M	LAMP ASSY,TAIL,RH	?			1.00	191.00	00.00	191.00
M	REFLECTOR LH	ms ✓			1.00	36.00	00.00	36.00
M	REFLECTOR RH	?			1.00	36.00	00.00	36.00

SURVEYOR NAME : RASUL - Hp 90010068SURVEYOR SIGNATURE : RulDATE : 03/06/19 @ 1630 hrsREMARKS : 10 daysResurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett	11,446.00
7% GST on	801.22
Total Payable	12,247.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.