

樹發汽車修理廠 SHU FATT AUTO WORKS



BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo 6th May 2019 TP19-axa

SJY 7751 U VOLKSWAGEN JETTA

		· S\$	
Spare Parts 1	Rear boot.	61/1935.15	Nett
1	Rear boot logo.	114.65	Nett
1	Rear boot 'Jetta' emblem.	Me 84.05	Nett
1	Rear boot 'TSi' emblem.	14/ 68.75	
1	Rear boot lock.	bt-159.35	Nett
1	Rear boot rubber.	cut 332.85	Nett
7.1.7	Rear boot inner garnish.	X190.65	Nett
6 200 3028	Set rear boot inner garnish clips.	×72.00	Nett
2	Rear boot reflectors. @\$255.85	χ 511.70	Nett
2	Rear tail lights. @\$377.85	755.70	
nection that the 2 s	Rear tail light holders. @\$95.65		Nett
1	Rear support panel.	? 2029.85	Nett
1	Rear panel inner garnish.	7 165.75	Nett
1	Set rear panel inner garnish clips.	7 36.00	Nett
1	Rear bumper.	de 1279.05	Nett
1	Rear bumper reinforcement.	bt-696.45	Nett
1	Rear bumper foam.	~	Nett
2	Rear bumper brackets. @\$112.45	7 224.90	Nett
1	Set rear bumper clips.	NU - 72.00	Nett
2	Rear bumper side retainers. @\$76.95	, 7,153.90	Nett
1	Rear lower bumper.	aut 721.85	Nett
1	Rear spare wheel cover.	X 339.15	Nett
1	Set rear reverse sensors.	200 MW 280.00	Snet
1	Rear number plate.	HV45 55.00	Snet
		10587.80	
		1025.28	

9562.52

1350.00 200

Labour

Tayfill 97495749 Sure Illanto. com

To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, rear lower member, left rear fender, rt rear fender, left rear fender inner panel, rt rear fender inner panel, renew rear boot, rear support panel, rear lights, rear bumper, rear exhaust and assembly

To respray damaged parts.

To remove, replace rear windscreen. To remove rear garnishes, carpets, upholstery, seats to

facilitate repairs and assembly.

To reseal joint, reinsulate, anti rust panels and assembly.

1350.00 180.00 180.0060.

150.00 50 >

hence notify

205/55R16 WVWZZZ1KZAM140303 162467

'ollowing: the Rebu . To resurve, before after spray painting . To display dan aged part(s) during resurvey · Parts price: are subject to confirmation

. Third party survey is on a "Without Prejudice" basis

· No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

12772.52