



樹發汽車修理廠 SHU FATT AUTO WORKS

0-11

BLOCK 100B BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
6th May 2019
TP19- axa

21/4/2019: Called Mr Tee
to fix approx 1/2
lower or bumper.

Suppl
1) LR bumper reflector.

SIY 7751 U VOLKSWAGEN JETTA

Parts: 5519.15
-10%: (551.92)
4967.24 ✓
Snet: 243.00 ✓
5212.24
labour: 1660.00
6822.24
-20%: (1374.45)
5447.79

4s: 5000.00

Labour

Tanjiu 97495749
WP' 8/5/19C 245p
sure lkkanto.com
lumpsum
Rearry after repair
5-6 days

- | | | |
|-------------|---|--------------------------------------|
| Spare Parts | 1 | Rear boot. |
| | 1 | Rear boot logo. |
| | 1 | Rear boot 'Jetta' emblem. |
| | 1 | Rear boot 'TSI' emblem. |
| | 1 | Rear boot lock. |
| | 1 | Rear boot rubber. |
| | 1 | Rear boot inner garnish. |
| | 1 | Set rear boot inner garnish clips. |
| | 2 | Rear boot reflectors. @\$255.85 |
| | 2 | Rear tail lights. @\$377.85 |
| | 2 | Rear tail light holders. @\$95.65x |
| | 1 | Rear support panel. |
| | 1 | Rear panel inner garnish. |
| | 1 | Set rear panel inner garnish clips. |
| | 1 | Rear bumper. |
| | 1 | Rear bumper reinforcement. |
| | 1 | Rear bumper foamx |
| | 2 | Rear bumper brackets. @\$112.45 |
| | 1 | Set rear bumper clips. |
| | 2 | Rear bumper side retainers. @\$76.95 |
| | 1 | Rear lower bumper |
| | 1 | Rear spare wheel cover. |
| | 1 | Set rear reverse sensors. |
| | 1 | Rear number plate. |

bt ✓	1935.15	Nett
re ✓	114.65	Nett
re ✓	84.05	Nett
re ✓	68.75	Nett
bt ✓	159.35	Nett
cut ✓	332.85	Nett
re ✓	190.65	Nett
re ✓	72.00	Nett
x	511.70	Nett
?	755.70	Nett
?	191.30	Nett
?	2029.85	Nett
?	165.75	Nett
?	36.00	Nett
de ✓	1279.05	Nett
bt ✓	696.45	Nett
?	117.75	Nett
?	224.90	Nett
re ✓	72.00	Nett
?	153.90	Nett
cut ✓	721.85	Nett
x	339.15	Nett
200 re ✓	280.00	Snet
bt ✓	45	Snet

10587.80

1025.28

9562.52

1350.00 800.

1350.00 800

180.00x

180.0060.

150.00 50x.

12772.52

=====

To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear spare wheel base, rear lower member, left rear fender, rt rear fender, left rear fender inner panel, rt rear fender inner panel, renew rear boot, rear support panel, rear lights, rear bumper, rear exhaust and assembly.
To respray damaged parts.
To remove, replace rear windscreen.
To remove rear garnishes, carpets, upholstery, seats to facilitate repairs and assembly.
To reseal joint, reinsulate, anti rust panels and assembly.

Pirelli 205/55R16
WWWZZZ1KZAM140303
162467



樹發汽車修理廠
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK pw SH-que
6th May 2019

Supplementary
TP19- axa

SJY 7751 U VOLKSWAGEN JETTA

Spare Parts 1 Left rear bumper reflector

	SS
	55.00
Less 10%	(5.50)

	49.50

cm ✓