

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965
 TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg
 GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department

Your Ref No: SLB3145T

Claim Type: Third Party

Accident Date: 02/05/2019

TP Veh Reg No: SJP911T

Estimate No: EST1900917

Date: 04 May 2019

Policy No: 5088533256-02

Veh Reg No: SLB3145T

Make/Model: TOYOTA CAMRY 2.0
 AUTO

Chassis No: MR053DK5100105401

Engine No: 6ARP120850

Reg. Date: 01/04/2016

Estimate Repair Cost to Vehicle No : SLB3145T

Description	U/Price	Quantity	Cost S\$	Amount S\$
List Price				
1 FRONT HEADLAMP HID - LH <i>CRA</i>		1 PC	1,897.10	1,897.10
2 FRONT BUMPER <i>Repair x</i>		1 PC	596.80	596.80
3 FRONT FENDER - LH <i>DO</i>		1 PC	597.90	597.90
4 FRONT FENDER INNER SHIELD - LH <i>DEF</i>		1 PC	165.80	165.80
5 FRONT FENDER 'VV ti' EMBLEM - LH <i>hec</i>		1 PC	78.40	78.40
				3,336.00
Special Net				
6 FRONT BUMPER CLIPS <i>hec</i>		1 SET	85.00	30 85.00
7 FRONT FENDER INNER SHIELD CLIPS - LH <i>hec</i>		1 SET	65.00	20 65.00
8 FRONT SPORT RIM - LH <i>mx</i>		1 PC	585.00	585.00
				735.00
To Repair				
9 FRONT BONNET		1 PC	0.00	0.00
				0.00
Labour				
10 LABOUR TO REMOVE NECESSARY DAMAGED PARTS ENABLE TO STRAIGHTEN PANEL, PANEL BEAT & REPAIR AFFECTED PANEL TO THE SAME.		1 JOB	800.00	800.00 500
11 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS		1 JOB	1,000.00	1,000.00 400
12 LABOUR TO APPLY/SPRAY ANTI RUST PROOFING WHERE IS NECESSARY.		1 JOB	100.00	100.00 20
13 LABOUR TO CONDUCT 4XWHEEL ALIGNMENT		1 JOB	90.00	90.00 x
14 WIRING JOB		1 JOB	30.00	30.00 ✓
				2,020.00

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965
TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg
GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01

AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department

Your Ref No: SLB3145T

Claim Type: Third Party

Accident Date: 02/05/2019

TP Veh Reg No: SJP911T

Estimate No: EST1900917

Date: 04 May 2019

Policy No: 5088533256-02

Veh Reg No: SLB3145T

Make/Model: TOYOTA CAMRY 2.0
AUTO

Chassis No: MR053DK5100105401

Engine No: 6ARP120850

Reg. Date: 01/04/2016

Estimate Repair Cost to Vehicle No : SLB3145T

Total	S\$ 6,091.00
Add GST @ 7%	426.37
Total Amount payable	S\$ 6,517.37

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED SEVENTEEN AND CENTS THIRTY SEVEN ONLY

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE



Hwee Jie - LKK
9/5/19
L/s 4days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____