

CC3/TM119008122/K1qd3s2

SHC 74760

22/5/19

Estimate No:

OOITP/MSITP/RES/OD/RES/EVA/INV/MV

To Insured Vehicle No:

at Workshop no/s

of

Insured: **SLQ 3189M**Policy No: **MK000193**Claims No: **M1903323**


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAG Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

**Toyota Pro**CC **1798**

Colour:

**Yellow**A/C: Ins **0** / Std / Nil / NA

Sp. Reading

**228369**T/Radio: Ins **0** / Std / Nil / NA

Eng/No:

C/No:

**J70KB3F4X0356122**Gen. Cond: Good / **0** / Poor / BurntSteering: Inord **0** / Jammed / Leaked / Burnt orBrake: Inord **0** / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD **0** / Rim or

Tyre Size: F:

**195/65R15**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

**Davanti**

Front

Rear

R/Bal.

**7**

mm

R/Bal.

**7**

mm

L/Bal.

**7**

mm

L/Bal.

**7**

mm

D.O.A.

**7/5/19**

D.O.A.

**8/5/19**

Survey held at

**CPAE (Loyang)**

Des. of Damages: Frl / Rear / OIS / NIS / UIC / Rooftop or

**Rear**

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHC 74760 - CS/FCJ/6005303/T1q/h3d1

D/A: 17/3/16 To Kio

SLQ 3189M - A

f11

09/5/19 09.13am Email GIA, police report &amp; estimate to TM

13/5/19 Email P/P \$7234.08 / 3 Bp. (Red \$3706.89, 34%)

RECEIVED 15 MAY 2019

Date/Time, File Pass to?

☐ : Preli. Report11/4/5 **tm34**☐ : Final Report

Date/Time, File Return to?

Days Of Repair: **3**Resurvey No. of Trip: **1**

Survey Fee:

**250**

Transportation:

S+RS: \$

Photos

Charts

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Other (\$

MER-TP

7234.08

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 9 May 2019 9:13 AM  
**To:** Motor Claims  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP -COMFORTDELGRO ENGINEERING PTE LTD, DOA: 07/05/2019, SHC 7476D (TP VEHICLE), SLQ 3189M (OI VEHICLE)  
**Attachments:** SHC7476 PR.pdf, SHC7476 GIA.pdf, SHC7476 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 7476D at M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 08/05/2019.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/05/2019 10:54
Date Of Accident	07/05/2019 11:45
Exact Location Of Accident	UPP CHANGI RD EAST TWDS TPE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC7476D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

### Driver

Name of Driver	LIM LIAN CHYE
NRIC No	S1201460J
Date Of Birth	18/06/1956
Occupation	OUTDOOR
Date Of Driving Pass	17/12/1977
Driving Experience	41 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90618916
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	126 07-82 BEDOK NORTH STREET 2
Postcode	460126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TAMPINES N NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ3189M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

DRIVER

Approximate Age

Injuries Sustain

NOT SURE

Injured person in which vehicle?

SLQ3189M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name

LIM LIAN CHYE

Approximate Age

62

Injuries Sustain

NECK,BACK,HAND

Injured person in which vehicle?

SHC7476D

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

#### DETAILS OF INJURED PERSON 3

Name

PAX

Approximate Age

Injuries Sustain

NECK,BACK

Injured person in which vehicle?

SHC7476D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

#### DETAILS OF INJURED PERSON 4

Name

PAX

Approximate Age

Injuries Sustain

NECK,BACK

Injured person in which vehicle?

SHC7476D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

Attached

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attached police report  
7/20190507 | 2150.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CO. REG. NO. 199502839G

Policyholder's Signature

Date & Time:

Driver's Signature


(If driver is not the policyholder)

Reporting Centre Personnel's Signature

Name:

Loke Wei Yeng

21/11/19





**SINGAPORE  
POLICE FORCE**



T/20190507/2150

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

1 of 3

Report No. T/20190507/2150

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 07/05/2019 17:51	Vide Report No.: G/20190507/0064	Station Diary No.: 22
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: LIM LIAN CHYE		Address: APT BLK 126 BEDOK NORTH STREET 2 #07-82 SINGAPORE 460126	
ID Type / ID No.: NRIC NO / S1201460J		Contact No.: Home/Office: Mobile: 90618916	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 62	Date of Birth: 18/06/1956	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/05/2019 11:45	Type of Location: Straight Road
Location: Along Road 1 UPPER CHANGI ROAD EAST TOWARDS TPE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC7476D	Car	TOYOTA	PIRUS	Yellow		2
SLQ3189M	Car					0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SHC7476D	FIRST CAPITAL INSURANCE LIMITED	D-18088937MFSH	01/01/2018	31/12/2020





**SINGAPORE  
POLICE FORCE**



T/20190507/2150

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

2 of 3

Report No. T/20190507/2150

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM LIAN CHYE	ID No.	S1201460J
Related Vehicle	SHC7476D (Car)	Contact No.	90618916
Hospital/Clinic	OEI FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	07/05/2019	Date Discharge	07/05/2019
No. of Days granted Medical Leave	06	Degree of Injury	NIL

**Brief Details.**

On 07.05.2019 at about 1145hrs, I was driving my vehicle (SHC7476D) along Upper Changi Road East towards the direction of TPE on lane 2 of a 3 lane road with 2 pax on board. While driving the vehicle in front of me applied his brake and I follow suit.

Subsequently out of a sudden, I felt an impact on the rear portion of my vehicle. The rear vehicle SLQ3189M have collided onto the rear portion of my vehicle. I called for Ambulance as my passengers (Malay couple in their early 60's) complaint of pain on their back and neck.

When ambulance arrived at scene, the other driver (male Malay, 20's to early 30's, medium built) was conveyed to CGH condition conscious. My passengers was not conveyed to Hospital and was advised to see a doctor if the pain persist. Traffic Police who was at scene advised me to lodge a RTA Report.

On the same day at about 1540hrs, I went to Oei Family Clinic to seek medical treatment and was given 6 days of out patient leave.

1201460/J



**SINGAPORE  
POLICE FORCE**



T/20190507/2150

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

3 of 3

Report No. T/20190507/2150

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt TAN HOCK CHYE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

07/05/2019 17:51

Officer In Charge Of Case:

TP / GIT /

Insp TAN CHIN YONG

Contact No.: 65476178



Classification Of Case:

Authentication Stamp

NP168

> [Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SHC7476D		
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1 :	Air-Con (Taxi)		
Vehicle Scheme :	Taxi (Company)		
Vehicle Make :	TOYOTA		
Vehicle Model :	PRIUS HYBRID 1.8 CVT		
Chassis No. :	JTDKB3FUX03561027		
Propellant :	Petrol-Electric		
Engine No. :	2ZRS055318		
Motor No. :	1NMS055318		
Engine Capacity :	1798 cc		
Power Rating :	53.0 kW		
Maximum Power Output :	90.0 kW ( 120 bhp)		
Maximum Laden Weight :	1790 kg		
Unladen Weight :	1375 kg		
Year Of Manufacture :	2017		
Original Registration Date :	22 Jun 2017		
Lifespan Expiry Date :	21 Jun 2025		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid :	\$40,500.00		
COE Expiry Date :	21 Jun 2025		
Road Tax Expiry Date :	21 Jun 2019		
PARF Eligibility Expiry Date :	21 Jun 2025		
Inspection Due Date :	21 Dec 2019		
Intended Transfer Date :	16 May 2019		
CO2 Emission :	87.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$27,610.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 21 Jun 2019. You may renew the road tax from 22 Mar 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Jun 2019, late renewal fee(s) will be imposed. Please use <a href="#">Enquire Road Tax Payable</a> to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
<b>Amount Payable (From 22 Jun 2019 to 21 Dec 2019)</b>			
	<b>Amount Before GST (S\$)</b>	<b>GST Amount (S\$)</b>	<b>Amount After GST (S\$)</b>
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
<b>Total Amount Payable :</b>			<b>535.00</b>
<b>Message</b>			
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			
From 18 Feb 2019, the Government has further reduced the annual special tax by \$100 and \$850 for diesel and diesel-hybrid cars and taxis respectively. The Government will also grant road tax rebates for diesel and diesel-hybrid buses and goods vehicles for a 3-year period from 1 Aug 2019. The current enquiry result does not include the revised special tax reduction and road tax rebate commencing 1 Aug 2019. Please refer to the <a href="#">Press Release</a> for more information.			

You may print this page for reference.

OK

Print



CITYCAB TAXI  
59 LOYANG DRIVE  
SINGAPORE 508969

Tyre : *Paranti*  
195/65 R15

*CP/P*

PAGE 1/2

FROM: LIM TIEN SIONG  
TEL : 62148398  
FAX : 65468156

JOB NO : 305293607  
YOUR INSURED:

ATTN:MOTOR CLAIM DEPT

ESTIMATE: THIRD PARTY

VEHICLE : SHC7476D  
MODEL: TOYOTA PRIUS

SURVEYOR: LKK-KALVIN  
INSURANCE CO: TOKIO MARINE  
DATE : 8-May-19

PARTS DESCRIPTION

	P/N #	QTY LIST ITEMS	AMOUNT	AFTER 25%
1	04-01-0302-2282-G	1 REAR BUMPER <i>Rebuilt</i>	\$458.60	\$343.95
2	04-01-0302-2287-G	1 REAR BUMPER LOWER GUARD-BLACK <i>one</i>	\$552.60	\$414.45
3	04-01-0302-2288-G	1 REAR BUMPER REINFORCEMENT <i>Reb</i>	\$318.80	\$239.10
4	04-01-0302-2965-G	1 REAR BUMPER SIDE EXTENSION RH/COVER <i>Reb</i>	\$148.40	\$111.30
5	04-01-0302-2865-G	1 REAR BUMPER SIDE EXTENSION LH/COVER <i>Reb</i>	\$148.40	\$111.30
6	04-01-0302-3937-G	1 REAR BUMPER RETAINER RH <i>X sur</i>	\$112.70	\$84.53
7	04-01-0302-3837-G	1 REAR BUMPER RETAINER LH <i>X sur</i>	\$112.70	\$84.53
8	04-01-0302-2267-G	10 REAR BUMPER CLIP (10PCS) <i>one</i>	\$2.20	\$16.50
9	04-01-0302-2286-G	1 REAR BUMPER TOW COVER <i>one</i>	\$82.70	\$62.03
10	04-01-0302-2347-G	1 REAR UNDER FLOOR COVER <i>one</i>	\$220.50	\$165.38
11	04-01-0302-2256-G	1 BOOTLID <i>Reb</i>	\$922.50	\$691.88
12	04-01-0302-2403-G	1 BOOTLID SPOILER <i>X repair</i>	\$1,357.50	\$1,018.13
13	04-01-0302-2346-G	1 BOOTLID OUTER GARNISH <i>one</i>	\$889.70	\$667.28
14	04-01-0302-2380-G	1 BOOTLID LATCH <i>Reb</i>	\$447.70	\$335.78
15	04-01-0302-2270-G	1 BOOTLID EMBLEM 'HYBRID' <i>one</i>	\$52.40	\$39.30
16	04-01-0302-2271-G	1 BOOTLID EMBLEM 'PRIUS' <i>one</i>	\$60.80	\$45.60
17	04-01-0302-2269-G	1 BOOTLID EMBLEM (Toyota Star) <i>one</i>	\$45.90	\$34.43
18	04-01-0302-0585-G	1 TAILLAMP RH - UPR <i>X sur</i>	\$557.90	\$418.43
19	04-01-0302-0795-G	1 TAILLAMP RH - LWR <i>one</i>	\$548.40	\$411.30
20	04-01-0302-0581-G	1 TAILLAMP LH - UPR <i>X sur</i>	\$557.90	\$418.43
21	04-01-0302-0796-G	1 TAILLAMP LH - LWR <i>X sur</i>	\$548.40	\$411.30
22	04-01-0302-2383-G	1 REAR END PANEL <i>X repair</i>	\$602.10	\$451.58
23	04-01-0302-2258-G	1 TAILGATE UPR WINDSCREEN <i>one</i>	\$1,555.80	\$1,166.85
24	04-01-0302-2257-G	1 TAILGATE LWR WINDSCREEN - BLACK GLASS <i>shld</i>	\$721.30	\$540.98

DISCOUNTED TOTAL

**\$8,284.28**

QTY SPECIAL NETT ITEMS

		QTY SPECIAL NETT ITEMS	AMOUNT	TOTAL
1	09-01-0302-2005-A	1 REVERSE SENSOR <i>shutted</i>	\$135.70	\$135.70
2	04-01-0302-1150-G	1 REAR BUMPER RUBBER MAT <i>one</i>	\$50.00	\$50.00
3	28-01-0302-2016-A	1 BOOTLID 'COMFORTDELGRO' STICKER (CCPL) <i>one</i>	\$30.00	\$30.00
4	28-01-0302-0010-A	1 BOOTLID '65521111' STICKER (CCPL) <i>one</i>	\$30.00	\$30.00
5	28-01-0302-2014-A	1 BOOTLID APPS STICKER (CCPL) <i>one</i>	\$40.00	\$40.00
		<i>Rear Number plate - Reb</i>	<i>\$25</i>	
		<i>Windscreen sealant - one</i>	<i>\$46</i>	
		SPECIAL NETT TOTAL		<b>\$285.70</b>

PAGE 2/2

Before Paint photo

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CCPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/05/2019
Vehicle Reg. No.:	<b>SHC7476D</b>	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Vehicle Reg. Date:	22/06/2017
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	2ZRS055318	Chassis No:	JTDKB3FUX03561027
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	8,640.97
Miscellaneous Items	10.00
Labour	2,290.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>10,940.97</b>
<b>+ GST 7.00% (S\$)</b>	<b>765.87</b>
<b>Nett Amount (S\$)</b>	<b>11,706.84</b>

**This claim is handled by: LIM TIEN SIONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 May 2019)**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC7476D/08/05/2019 17:50**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00 DE	*458.60 FL ✓
2	1		*REAR BUMPER LOWER GUARD-BLACK	25.00	0.00 CRA	*552.60 FL ✓
3	1		*REAR BUMPER REINFORCEMENT	25.00	0.00 BT	*318.80 FL ✓
4	2		*REAR BUMPER EXTENSION COVER RH/LH	25.00	0.00 BT	*296.80 FL ✓
5	2		*REAR BUMPER RETAINER RH/LH	25.00	0.00 XSVC	*225.40 FL ✓
6	10		*REAR BUMPER CLIPS	25.00	0.00 REC	*22.00 FL ✓
7	1		*REAR BUMPER TOW COVER	25.00	0.00 CRA	*82.70 FL ✓
8	1		*REAR UNDER FLOOR COVER	25.00	0.00 CRA	*220.50 FL ✓
9	1		*BOOTLID	25.00	0.00 BT	*922.50 FL ✓
10	1		*BOOTLID SPOILER	25.00	0.00 XR	*1,357.50 FL ✓
11	1		*BOOTLID OUTER GARNISH	25.00	0.00 CRA	*889.70 FL ✓
12	1		*BOOTLID LATCH	25.00	0.00 BT	*447.70 FL ✓
13	1		*BOOTLID EMBLEM-HYBRID	25.00	0.00 REC	*52.40 FL ✓
14	1		*BOOTLID EMBLEM-PRIUS	25.00	0.00 REC	*60.80 FL ✓
15	1		*BOOTLID EMBLEM-TOYOTA STAR	25.00	0.00 REC	*45.90 FL ✓
16	2		*TAILLAMP UPR RH/LH	25.00	0.00 XSVC	*1,115.80 FL ✓
17	2		*TAILLAMP LWR RH/LH	25.00	0.00	*1,096.80 FL ✓
18	1		*REAR END PANEL	25.00	0.00 XR	*602.10 FL ✓
19	1		*BOOTLID UPR WINDSCREEN	25.00	0.00 REC	*1,555.80 FL ✓
20	1		*BOOTLID LWR WINDSCREEN	25.00	0.00	*721.30 FL ✓
21	1		*REVERSE SENSOR	0.00	0.00	*135.70 F ✓
22	1		*REAR BUMPER MAT	0.00	0.00 REC	*50.00 F ✓
23	1		*BOOTLID (COMFORTDELGRO)	0.00	0.00 REC	*30.00 F ✓
24	1		*BOOTLID (65521111)	0.00	0.00 REC	*30.00 F ✓
25	1		*BOOTLID (APPS)	0.00	0.00	*40.00 F ✓
26	1		*REAR NO.PLATE	0.00	0.00 BT	*25.00 F ✓
27	1		*WINDSCREEN SEALANT	0.00	0.00 REC	*46.00 F ✓

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,402.40</b>
<b>- List Item Discount on L Items (\$\$)</b>	<b>2,761.43</b>
<b>Total Parts (\$\$)</b>	<b>8,640.97</b>

ComfortDelGro Engineering Pte Ltd/SHC7476D/08/05/2019 17:50. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	600 840.00
2	SPRAY PAINTING	New	600 800.00
3	WIRING CHECK	New	2.0 50.00
4	TUFF KOTE	New	50 100.00
5	TOWING CHARGE	New	60.00 ✓
6	R/I UPHOLSTERY ETC	New	50 120.00
7	REPLACE REAR WINDSCREENS	New	100 200.00
8	R/I REVERSE SENSOR	New	30 120.00
Gross Labour Cost (S\$)			2,290.00

ComfortDelGro Engineering Pte Ltd/SHC7476D/08/05/2019 17:50. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition		
1. Date: 7/5/19	Time Received: 1345	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)
2. <input type="checkbox"/> New Name of Customer: LIM Contact No.: 90618916 Vehicle No.: SHC 7476D Make / Model / Colour: TOYOTA prius Email:	4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery
7. Location: SAVANNAH CONDO PARK 47 SIMERI RISE	6. Parts Replaced/Remarks:	
9. Preferred Workshop: <input type="checkbox"/> Braddell <input type="checkbox"/> Sin Ming <input type="checkbox"/> Senoko <input type="checkbox"/> Others: <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Pandan <input type="checkbox"/> Ubi <input type="checkbox"/> Cycle & Carriage (PD)	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Overheating <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Starting Problem <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Return Taxi <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Loss Power <input type="checkbox"/> Engine Stalled	
10. Odometer Reading: Fuel Level: F 1/4 1/2 3/4 E	11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	 # : Cracked X : Dented / : Scratched O : Missing Signature of Customer: <i>X</i>
Job Attended		
12. Tow Truck / Recovery Van: <input type="checkbox"/> VRS <input checked="" type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS Name of Driver: SAM Vehicle No.: YN39J6V Time Dispatch: 1345 Time of Arrival: 1405 Time Completed: 1435		
Cash Invoice Details (if applicable)		
13. Cash Invoice No.:		
Customer Acknowledgement		
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.		
7/5/19 Date		1405 Time
		Signature of Customer: <i>X</i>
14. WORKSHOP		
Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305293607

Date : 13/05/19

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive, Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC7476D

Date of Accident : 07-May-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLQ3189M
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$5,714.08
  - (b) Labour Charges \$1,520.00
  - Total for Part-By-Part Repair Cost \$7,234.08**
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature 

Name : KALVIN

Date : 13/5/19

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305293607  
 REGN NO : SHC7476D  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 22.06.2017  
 DATE/TIME IN : 07.05.2019 11:45  
 ACCIDENT DATE : 07.05.2019

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0302-2256-G	BOOTLID	1	922.50	25.00	691.87
0002	04-01-0302-2257-G	BOOTLID LWR WINDSCREEN	1	721.30	25.00	540.97
0003	04-01-0302-2258-G	BOOTLID UPR WINDSCREEN	1	1,555.80	25.00	1,166.85
0004	04-01-0302-2269-G	BOOTLID (TOYOTA STAR)	1	45.90	25.00	34.42
0005	04-01-0302-2270-G	BOOTLID (HYBRID S)	1	52.40	25.00	39.30
0006	04-01-0302-2271-G	BOOTLID (PRIUS)	1	60.80	25.00	45.60
0007	28-01-0302-0010-A	BOOTLID (65521111)	1	30.00		30.00
0008	28-01-0302-2016-A	BOOTLID (COMFORTDELGRO)	1	30.00		30.00
0009	04-01-0302-2282-G	REAR BUMPER	1	458.60	25.00	343.95
0010	04-01-0302-2287-G	R/BUMPER LWR GUARD-Black	1	552.60	25.00	414.45
0011	04-01-0302-2288-G	REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10
0012	04-01-0302-2380-G	BOOTLID LATCH	1	447.70	25.00	335.77
0013	04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305293607  
 REGN NO : SHC7476D  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(C  
 DATE OF REGN : 22.06.2017  
 DATE/TIME IN : 07.05.2019 11:45  
 ACCIDENT DATE : 07.05.2019

JOB / PARTS DESCRIPTION				QTY IND UNIT-PRICE DISC% AMOUNT			
0014 09-01-0302-2005-A	REVERSE SENSOR	1	135.70		135.70		
0015 04-01-0302-2347-G	REAR UNDER FLOOR COVER	1	220.50	25.00	165.37		
0016 04-01-0302-0795-G	TAILLAMP LWR RH	1	548.40	25.00	411.30		
0017 04-01-0302-2346-G	BOOTLID OUTER GARNISH	1	889.70	25.00	667.27		
0018 04-01-0302-2965-G	REAR BUMPER EXTENSION RH	1	148.40	25.00	111.30		
0019 04-01-0302-2286-G	REAR BUMPER TOW COVER	1	82.70	25.00	62.02		
0020 FNPS	NO PLATE(S)	1 L	25.00		25.00		
0021 04-01-0302-2865-G	REAR BUMPER EXTENSION LH	1	148.40	25.00	111.30		
0022 04-01-0302-1150-A	REAR BUMPER MAT	1	50.00		50.00		
0023 05-01-0199-0032-A	WINDSCREEN AHESIVE-310MLC	1	46.00		46.00		
						SUB-TOTAL : 5,714.04	

JOB NATURE

---

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305293607  
REGN NO : SHC7476D  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 22.06.2017  
DATE/TIME IN : 07.05.2019 11:45  
ACCIDENT DATE : 07.05.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING			600.00		
0001 SP	SPRAYPAINT CHARGE			600.00		
0002 17-01	WIRING CHECK			20.00		
0003 20-00	TUFF COAT ON AFFECTED PARTS.			50.00		
0004 23-01	TOWING FEE			60.00		
0005 L	R/I UPHOLSTERY ETC			50.00		
0006 L	REPLACE REAR WINDSCREENS			100.00		
0007 L	R/I REVERSE SENSOR			30.00		
0008 L	TP MERIMEN			10.00		
SUB-TOTAL :						1,520.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.05.2019

REPAIR ESTIMATE

Time: 17:28:11

Page: 4

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305293607  
REGN NO : SHC7476D  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 22.06.2017  
DATE/TIME IN : 07.05.2019 11:45  
ACCIDENT DATE : 07.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT



TOTAL : 7,234.04

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2019 <a href="#">Sendback Est</a>	08 May 2019 17:50 <b>S\$10,940.97</b>	09 May 2019 10:06 <a href="#">Edit Adj Rpt</a>	<b>S\$7,234.07</b> <a href="#">Edit Estimates</a>	<b>S\$7,234.07</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	LCRF PTE. LTD., Co. Reg. No.: 201624597K		
Main Claimant:	CCPL		
Vehicle Reg. No.:	SHC7476D	Date of Loss:	07/05/2019 11:00 - :59 [22 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1903323	Policy/Cover Note No.:	MK000193 (Third Party Only) Coverage: 25/02/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLQ3189M	Policy No. (Claimant):	
		Excess:	S\$1,600.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 21/05/2019]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

SHC7476D (M1903323)  
[SLQ3189M]  
TP  
CCPL  
May 7 2019 11:00AM  
[LCRF PTE. LTD.]  
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

### Assessment Reports

1 per page ▼

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	08/05/19 17:50	<b>Repairer Estimates</b>		Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	14/05/19 09:54	<b>Accident Statement</b> From: SC - Reg. No: SLQ3189M, Claimant: LCRF PTE LTD		Load HTM	

### Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/05/19 08:05	<b>General View</b>		Load JPG	
2	10/05/19 08:05	<b>General View</b>		Load JPG	
3	10/05/19 08:05	<b>General View</b>		Load JPG	
4	10/05/19 08:05	<b>General View</b>		Load JPG	
5	10/05/19 08:05	<b>General View</b>		Load JPG	
6	10/05/19 08:05	<b>General View</b>		Load JPG	
7	10/05/19 08:05	<b>General View</b>		Load JPG	
8	10/05/19 08:05	<b>General View</b>		Load JPG	
9	10/05/19 08:05	<b>General View</b>		Load JPG	
10	10/05/19 08:05	<b>General View</b>		Load JPG	
11	10/05/19 08:05	<b>General View</b>		Load JPG	
12	10/05/19 08:05	<b>General View</b>		Load JPG	
13	10/05/19 08:05	<b>General View</b>		Load JPG	
14	10/05/19 08:05	<b>General View</b>		Load JPG	
15	10/05/19 08:05	<b>General View</b>		Load JPG	
16	10/05/19 08:05	<b>General View</b>		Load JPG	
17	10/05/19 08:05	<b>General View</b>		Load JPG	
18	10/05/19 08:05	<b>General View</b>		Load JPG	
19	10/05/19 08:05	<b>General View</b>		Load JPG	
20	10/05/19 08:05	<b>General View</b>		Load JPG	
21	10/05/19 08:05	<b>General View</b>		Load JPG	
22	10/05/19 08:05	<b>General View</b>		Load JPG	
23	10/05/19 08:05	<b>General View</b>		Load JPG	
24	10/05/19 08:05	<b>General View</b>		Load JPG	
25	10/05/19 08:05	<b>General View</b>		Load JPG	
26	10/05/19 08:05	<b>General View</b>		Load JPG	
27	10/05/19 08:05	<b>General View</b>		Load JPG	
28	10/05/19 08:05	<b>General View</b>		Load JPG	
29	10/05/19 08:05	<b>General View</b>		Load JPG	
30	10/05/19 08:05	<b>General View</b>		Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
31	10/05/19 08:05	General View	 Load JPG	✓
32	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
33	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
34	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
35	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
36	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
37	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
38	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
39	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
40	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
41	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
42	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
43	10/05/19 08:05	Replacement Part Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	15/05/19 16:19	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	 Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	08/05/19 17:50	E-filed GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19008122/K1QD3S2

Date: 16/05/2019

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000193

Claimant Vehicle No: SHC7476D

Insured Vehicle No: SLQ3189M

Date of Loss: 07/05/2019

Nature of Claim: TP

Claim No: M1903323

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHC7476D

Make &amp; Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZRS055318

Reg. Date: 22/06/2017 (Man. Year: 2017)

Chassis No: JTDKB3FUX03561027

Colour: Yellow

Odometer: 228369 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

## CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Davanti 7 mm

Rear Left Side: Davanti 7 mm

Front Right Side: Davanti 7 mm

Rear Right Side: Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,640.97	5,714.07	2,926.90	33.87
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,290.00	1,510.00	780.00	34.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,940.97</b>	<b>7,234.07</b>	<b>3,706.90</b>	<b>33.88</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>765.87</b>	<b>506.38</b>	<b>259.49</b>	<b>33.88</b>
<b>Nett Amount (S\$)</b>	<b>11,706.84</b>	<b>7,740.45</b>	<b>3,966.39</b>	<b>33.88</b>

## INSPECTION

Date of Assignment: 09/05/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 08/05/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2019)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC7476D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER LOWER GUARD-BLACK	Cracked	552.60 FL	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
4	2		*REAR BUMPER EXTENSION COVER RH/LH	Bent	296.80 FL	*296.80 FL
5	2		*REAR BUMPER RETAINER RH/LH	Serviceable	225.40 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER TOW COVER	Cracked	82.70 FL	*82.70 FL
8	1		*REAR UNDER FLOOR COVER	Cracked	220.50 FL	*220.50 FL
9	1		*BOOTLID	Bent	922.50 FL	*922.50 FL
10	1		*BOOTLID SPOILER	Repair	1,357.50 FL	*- FL
11	1		*BOOTLID OUTER GARNISH	Cracked	889.70 FL	*889.70 FL
12	1		*BOOTLID LATCH	Bent	447.70 FL	*447.70 FL
13	1		*BOOTLID EMBLEM-HYBRID	Necessary	52.40 FL	*52.40 FL
14	1		*BOOTLID EMBLEM-PRIUS	Necessary	60.80 FL	*60.80 FL
15	1		*BOOTLID EMBLEM-TOYOTA STAR	Necessary	45.90 FL	*45.90 FL
16	2		*TAILLAMP UPR RH/LH	Serviceable	1,115.80 FL	*- FL
17	1		*TAILLAMP LWR RH/LH	O/s Cracked/N/s Serviceable	1,096.80 FL	*548.40 FL
18	1		*REAR END PANEL	Repair	602.10 FL	*- FL
19	1		*BOOTLID UPR WINDSCREEN	Necessary	1,555.80 FL	*1,555.80 FL
20	1		*BOOTLID LWR WINDSCREEN	Shorted	721.30 FL	*721.30 FL
21	1		*REVERSE SENSOR	Shorted	135.70 F	*135.70 F
22	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
23	1		*BOOTLID (COMFORTDELGRO)	Necessary	30.00 F	*30.00 F
24	1		*BOOTLID (65521111)	Necessary	30.00 F	*30.00 F
25	1		*BOOTLID (APPS)	Not Necessary	40.00 F	*- F
26	1		*REAR NO.PLATE	Bent	25.00 F	*25.00 F
27	1		*WINDSCREEN SEALANT	Necessary	46.00 F	*46.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>11,402.40</b>	<b>7,513.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>2,761.43</b>	<b>1,799.13</b>
<b>Total Parts (S\$)</b>	<b>8,640.97</b>	<b>5,714.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	840.00	600.00
2	SPRAY PAINTING	New	800.00	600.00
3	WIRING CHECK	New	50.00	20.00
4	TUFF KOTE	New	100.00	50.00
5	TOWING CHARGE	New	60.00	60.00
6	R/I UPHOLSTERY ETC	New	120.00	50.00
7	REPLACE REAR WINDSCREENS	New	200.00	100.00
8	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (S\$)			2,290.00	1,510.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;