



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT19002223	Page	1
	100 BEACH ROAD	Date	: 22. May 2019		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: JACK NG		
Registration No	: SFW5385P	Engine No	: L15B5671086		
Chassis No	: JHMRU1830JX201083	Date Time	: 22. May 2019 10:58:45 AM		
Model	: HRV LX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: LIM TAY SONG HAI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 6/5/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:LIM TAY SONG HAI						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:06/05/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:LONPAC						
	TP VEH:GBD 2371 X						
04711-T7A-J00ZZ	FACE,FR.BUMPER ✓ CUT	1	475.60	25	356.70	24.97	381.67
71103-T7A-J00	GRILLE,FR.BUMPER LOWER	1	81.00	25	60.75	4.25	65.00
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE ✓ NLC	1	11.00	25	8.25	0.58	8.83
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE ✓ NLC	1	11.00	25	8.25	0.58	8.83
91505-TM8-003	CLIP,BUMPER ✓ NLC	22	2.30	25	37.95	2.66	40.61
67050-T7A-300ZZ	PANEL COMPL.FR.DOOR X DR R	1	833.80	25	625.35	43.77	669.12
60260-T7A-J00ZZ	PANEL COMPL.FR.FENDER ✓ DO	1	394.90	25	296.17	20.73	316.90
74157-T7A-J01ZQ	PROTECTORL.FR.WHEEL ARCH ✓ CUT	1	147.60	25	110.70	7.75	118.45
42700-T7A-J93	DISK,ALUMINIUM WHEEL ✓ CUT	1	721.60	25	541.20	37.88	579.08
	Sum Item				2045.32	143.17	2,188.49
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	380.00	280	380.00	26.60	406.60
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	450.00	X	450.00	31.50	481.50
BKBU01R	REMOVE & RENEW FR BUMPE. RENEW ALL DAMAGE PARTS ✓ S60	1	3500.00	1680	3500.00	245.00	3745.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) ✓ 450 X 3 + 150	1	2500.00	1500	2500.00	175.00	2675.00
	Sum Labor				6930.00	485.10	7,415.10

Printed on 22/5/2019 11:14:52 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702
Registration No : SFW5385P
Chassis No : JHMRU1830JX201083
Model : HRV LX-SIN CVT YM 2018
Owner's Name : LIM TAY SONG HAI
Ins Policy No. :
Date of Accident : 6/5/2019

Document No. : SQT19002223
Date : 22. May 2019
Customer No. : WZL009
Svc Advisor : JACK NG
Engine No : L15B5671086
Date | Time : 22. May 2019 10:58:45 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By

Steve

Date & Time

22/5/19, 11.00am

Excess

Status

Signature

Total Amount 9,155.32 640.87 9,796.19

Total (Inclusive of GST) 9,796.19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 22/5/2019 11:14:52 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

5069.22
60.75