

19 LE



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SLJ7147U

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

## Vehicle & Document Information

WIP No 34584  
Reg No/Reg Date SLJ7147U / 24/03/2015  
Date In/Mileage / 49735  
Chassis No WDC1569432J063156  
Engine No 27091030514759  
Make/Model MB/GLA 200 B/E OFFROADER (X1  
Colour/Trim 027 787 Mountain Gr/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	02/07/2019/ 08:40	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

### Z REQUEST

Customer Request  
M BPNSUN

POLICY NO/ACC DATE : VPA/P2252151 // 6-05-2019  
DRIVE IN/TP VEH NUMBER : 25-6-2019 // SGF168K - LONPAC  
DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

### A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

### A BPIRES

RESPRAY RH/FRONT DOOR & RH/REAR DOOR

### A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO  
IDENTIFICATION STANDARD. NETT

### A BPILAB

REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT

### M RIGHT FRONT DOOR

repair

1.00 1536.05 00.00

1536.05

### M RH/FRONT DOOR WEATHERSTRIP

repair

1.00 305.97 00.00

305.97

### M RH/FRONT ABSORBING DOOR

repair

1.00 67.32 00.00

67.32

### M RIGHT REAR DOOR

repair

1.00 1805.49 00.00

1805.49

Go Chee Han  
DID : 6771 4336 HP : 9181 7717  
Email : cheehan.go@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

LKK Auto Consultants hence notify  
the Repairer of the following:

### Confirmed & accepted by

To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

7% GST on Nett 7,934.83 555.44

Total Payable 8,490.27

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Finalization

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLJ7147U

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

## Vehicle &amp; Document Information

WIP No 34584  
Reg No/Reg Date SLJ7147U / 24/03/2015  
Date In/Mileage 10/07/2019 / 49735  
Chassis No WDC1569432J063156  
Engine No 27091030514759  
Make/Model MB/GLA 200 B/E OFFROADER (X1  
Colour/Trim 027 787 Mountain Gr/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	20/07/2019/ 10:27	CH	371 / Go Chee Han
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

Z REQUEST

Customer Request

M BRNSUN

POLICY NO/ACC DATE : VPA/P2252151 // 6-05-2019  
DRIVE IN/TP VEH NUMBER : 25-6-2019 // SGF168K - LONPAC  
DATE IN/DATE SURVEY: 5-7-2019 1430 // Rasul - LKK  
BY/AUTHORIZED ON : 10-7-2019 1029 // Jia Le - LKK

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS &amp; REFINISH.

960.00 ✓

A BPIRES

RESpray RH/FRONT DOOR &amp; RH/REAR DOOR

1200.00 ✓

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

0.10

380.00 ✓

A BPILAB

REMOVE &amp; TRANSFER DOOR MECHANICAL &amp; ELECTRICAL INSTALL TO NEW DOOR.NETT

480.00

X RIGHT FRONT DOOR

1.00

1536.05 00.00

1536.05 ✓

X RH/FRONT DOOR WEATHERSTRIP

1.00

305.97 00.00

305.97 ✓

X RH/FRONT ABSORBING DOOR

1.00

67.32 00.00

67.32 ✓

X BLIND RIVET WITH PAN HEAD

11.00

2.51 00.00

27.61 ✓

X GUARD PLATE REAR DOOR

1.00

31.07 00.00

31.07 ✓

X ORNAMENTAL MOLDING CLIP

1.00

5.37 00.00

5.37 ✓

Confirmed &amp; accepted by

Nett 4,993.39  
7% GST on 4993.39 349.54  
Total Payable 5,342.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany





Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLJ7147U

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

### Vehicle & Document Information

WIP No 34584  
Reg No/Reg Date SLJ7147U / 24/03/2015  
Date In/Mileage 10/07/2019 / 49735  
Chassis No WDC1569432J063156  
Engine No 27091030514759  
Make/Model MB/GLA 200 B/E OFFROADER (X1  
Colour/Trim 027 787 Mountain Gr/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator	
WL001605	Credit	20/07/2019/ 10:25	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M. BPNSUN

POLICY NO/ACC DATE : NPA P2252151 / 16-05-2019  
DRIVE IN/TP VER NUMBER : 25-6-2019 // 66F168K LONPAC  
DATE IN/DATE SURVEY: 5-7-2019 1430 // Rasul - LKK  
BY/AUTHORIZED ON : 10-7-2019 1029 // Jia Le - LKK

X BLIND RIVET WITH PAN HEAD  
X GUARD PLATE REAR DOOR  
X ORNAMENTAL MOLDING CLIP

11.00	2.51	00.00	27.61
1.00	31.07	00.00	31.07
1.00	5.37	00.00	5.37

ESTIMATE

Confirmed & accepted by

	Nett	64.05
7% GST on	64.05	4.48
Total Payable		68.53

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany