



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLJ7147U

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **34584**
Reg No/Reg Date **SLJ7147U / 24/03/2015**
Date In/Mileage **/ 49735**
Chassis No **WDC1569432J063156**
Engine No **27091030514759**
Make/Model **MB/GLA 200 B/E OFFROADER (X1**
Colour/Trim **027 787 Mountain Gr/ 043 361 ARTICO Laro**

Account No	Terms	Date/Time Printed	CSE	Operator			
WL001605	Credit	02/07/2019/ 08:40	CH	371 / Go Chee Han			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : VPA/P2252151 // 6-05-2019

DRIVE IN/TP VEH NUMBER : 25-6-2019 // SGF168K - LONPAC

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY RH/FRONT DOOR & RH/REAR DOOR

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT

M RIGHT FRONT DOOR repair

1.00 1536.05 00.00 1536.05

M RH/FRONT DOOR WEATHERSTRIP

1.00 305.97 00.00 305.97

M RH/FRONT ABSORBING DOOR

1.00 67.32 00.00 67.32

M RIGHT REAR DOOR repair

1.00 1805.49 00.00 1805.49

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

Rasul
Hp 90010068
4 days
05/07/19 @ 1430
Reng after repair

Nett 7,934.83
7% GST on 7934.83 555.44
Total Payable 8,490.27

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg