

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0587/2019/DY/TF
Date : 7-May-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Nebil Mahaboob
Address : 18 Marina Boulevard
#25-09
Singapore 018980
Telephone : HP +65 9617 3366
Type of Claim : Own Damage Claims
Policy No. : 1800010879-01
Vehicle No : **SLW 4628 A** ✓
Model Code : Audi A5 Cabriolet 2.0 TFS
Model / Year : Feb-18
Engine No : CVK 043079
Chassis No : WAUZZZF5XJN006247
Mileage : 4306
Date In : 7-May-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-May-19
Place of Accident : Grange Road Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 4628 A

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To remove and transfer lhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓
3	To dismantle and front bumper, lhs front fender, bonnet and lhs front door. To renew lhs front fender, bonnet, lhs wing mirror assy and lhs front door. Re-organize crash management components. Reinstall all parts removed.	\$ 4,400.00 2000.
4	To respray lhs front fender, bonnet, hinges, lhs wing mirror cover and lhs front door. ✓ ✓ ✓	\$ 3,700.00 1800 3 x 550 = 1650 Mirror 2150 1800
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>9,052.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 4628 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - LH <i>Distorted</i>	\$ 968.00	✓
2	FRONT FENDER POP RIVET <i>new</i>	\$ 15.00	✓
3	FRONT FENDER ATTACHMENT PARTS <i>?</i>	\$ 48.00	?
4	FRONT FENDER CLOSING ELEMENT - LH <i>?</i>	\$ 68.00	?
5	FRONT FENDER BRACKET - LH <i>Bent</i>	3 \$ 117.00	✓
6	FRONT FENDER BRACE - LH <i>new</i>	\$ 107.00	?
7	FRONT FENDER DEFORMATION ELEMENT - LH <i>new</i>	\$ 45.00	✓
8	FRONT FENDER COVER - LH <i>Distorted</i>	\$ 16.00	✓
9	FRONT FENDER CLOSING ELEMENT - LH <i>not new</i>	\$ 30.00	✗
10	FRONT WHEEL HOUSING LINER - LH <i>new</i>	\$ 256.00	+
11	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 82.00	+
12	BONNET <i>dented</i>	\$ 2,602.00	✓
13	BONNET ATTACHMENT PARTS <i>?</i>	\$ 150.00	?
14	BONNET HINGE - LH/ RH <i>?</i>	\$ 762.00	?
15	BONNET IMPACT PROTECTION <i>new</i>	3 \$ 75.00	✓
16	FRONT FENDER TOP COVER - LH REAR <i>Distorted</i>	\$ 32.00	✓
17	FRONT HEADLIGHT TOP CORNER COVER - LH <i>new</i>	\$ 14.00	✓
18	FRONT FENDER TOP COVER - LH <i>new</i>	\$ 43.00	✓
19	BONNET BRACKET <i>new</i>	\$ 35.00	+
20	BONNET ACTUATING LEVER <i>new</i>	\$ 45.00	✓
SUB TOTAL SPARE PARTS		\$ 5,510.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 4628 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT DOOR - LH <i>Dented</i>	\$ 2,919.00	✓
22	FRONT DOOR OUTER SEAL - LH <i>new</i>	\$ 201.00	✓
23	BONDING AGENT <i>?</i>	\$ 45.00	?
24	CLEANING SOLUTION <i>?</i>	\$ 65.00	?
25	APPLICATOR <i>?</i>	\$ 7.00	?
26	FRONT DOOR ATTACHMENT PARTS <i>?</i>	\$ 158.00	?
27	FRONT DOOR CATCH - LH <i>new</i>	\$ 96.00	+
28	FRONT FENDER CORNER CHROME TRIM - LH <i>missing</i>	\$ 145.00	✓
29	FRONT DOOR CORNER CHROME TRIM - LH <i>missing</i>	\$ 145.00	✓
30	WIND MIRROR MOUNTING - LH <i>Dented</i>	\$ 999.00	✓
31	WIND MIRROR CAP- LH <i>cracked</i>	\$ 220.00	✓
32	WIND MIRROR GLASS - LH <i>?</i>	\$ 1,132.00	?
33	FRONT DOOR WINDOW SLOT SEAL CHROME <i>new</i>	\$ 416.00	+
34	A PILLER CHROME TRIM - LH <i>new</i>	\$ 1,428.00	+
35	ADHESIVE TAPE <i>new</i>	\$ 54.00	✓
36	SUNDRIES <i>?</i>	\$ 600.00	?
TOTAL SPARE PARTS		\$ 14,140.00	
TOTAL LABOUR CHARGES		\$ 9,052.00	
GRAND TOTAL		\$ 23,192.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *08/05/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 07 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant