

Surveyor:

REF: CS1 / SPFI9008150 / K19d352

Special Instruction:

From (Person): Hafizul Farhan of

ASSIGNMENT (Office)

SPF

Date/Time: 8/5/2019

Part by Part: \$ 1323.77

Estimated Cost:

Bill to:

Third Parties:

Claimant:

Surveyor: Vicom Assessment Centre

Workshop: Comfort Delgro (Braddell)

OD/TP Re-inspection ☒ Evaluation

To Inspect Vehicle No: SHD 3444S

Insured:

QX312Y

at Workshop m/s

Comfort Delgro (Braddell)

Tel:

63838115

of 205 Braddell Road

Policy No:

Claim No:

AEMD/105/009/2018/088

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/5/2018

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time:

Confirmed with

Final Fig

days (Red \$ / %; Original 2 days)

Date/Time:

09/5/19

Submit Final Fig

1158.40

2 days

(Red \$ 165.37 / 12 %; Original 2 days)

Date/Time

Action/Instruction

SHD 3444S - 003 / AIG 17016258 / K19d352

DVA: 19/5/2019

QX312Y - X

Recommend repair days: 2 days

No. Weekend = 0 days

total days: 2 days

range COR = 8100 - 81400

Do Not Finalise

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 09 MAY 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/

Evaluated by:

Fee Charged:

Date:

Basic & Add

Transport

Photos

Others

Total

200

1) Date/Time

09/5/19

File Pass to

MAISA

2) Date/Time

File Return to

3) Date/Time

File Pass to

4) Date/Time

File Return to

5) Date/Time

File Pass to

6) Date/Time

File Return to

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Wednesday, 8 May 2019 2:13 PM
To: Admin-D (LKKAuto); assignments; SUR
Cc: Rosalyn TAN (SPF); Frankie THAY (SPF); Abdul Rahman MOHAMAD SALIM (SPF)
Subject: RE: Outstanding LKK Reports
Attachments: (SHD3444S) 2018-088.pdf

Dear LKK,

Kindly conduct post survey for the below-mentioned vehicle.

S/no	Vehicle No	Accident Date	Case No.	SPF vehicle no.	Remark
1	SHD 3444 S	28 .05. 2018	AEMD/105/009/2018/088	QX 312Y	Post survey

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 8 May 2019 12:40 PM
To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: RE: Outstanding LKK Reports

Dear Farhan,

Please be informed that no record found for SHD 3444S and SHC 8545G.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) [<mailto:denisetay@lkkauto.com>]

Sent: Tuesday, 7 May 2019 2:36 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>

Subject: RE: Outstanding LKK Reports

Dear Farhan,

Sorry, resent the correct report.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Tuesday, 7 May 2019 2:08 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>

Subject: RE: Outstanding LKK Reports

Dear Farhan,

Enclosed report with upper range.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 3 May 2019 3:07 PM
To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: RE: Outstanding LKK Reports

Dear Farhan,

Thank you for the email.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Friday, 3 May 2019 3:01 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>; Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>
Subject: Outstanding LKK Reports

Hi LKK,

Reference to the table below, can I have the survey reports by 8th May 2019.

Thank you.

S/no	Vehicle No	Accident Date	Case No.	SPF vehicle no.	Remark
1	SHA 7270 R	8 .05. 2017	AEMD/105/009/2017/087	QX 326H	Please provide the range cost of re
2	SHD 3444 S	28 .05. 2018	AEMD/105/009/2018/019	QX 312Y	Pending LKK re
3	SHC 8545 G	24 .01. 2019	AEMD/105/009/2019/007	QX 755C	Pending LKK re

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com



VICOM LTD

205 Tanjong Pagar Road Singapore 0625718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg

vicom@vicom.com.sg

TAX INVOICE

COMFORTDELGRO ENGINEERING PTE LTD

#205 Braddell Road

Blk C Ext 1 3rd Level

Singapore 579701

ATTN : MOTOR CLAIMS DEPT.

GST REG No. : M9-0000652-A

CUSTOMER ID : VACC0013

INVOICE No. : LY011209

INVOICE DATE : 09/07/2018

PAYMENT TERM : 30 Days Credit

VEHICLE No. : SHD3444S

ACCIDENT DATE : 28/05/2018

CLAIM No. : 305166205

INSURED VEH.No: QX312Y

DESCRIPTION	QTY	UNIT PRICE (SG\$)	AMOUNT (SG\$)
Photographs	16	1.00	\$ 16.00
Transportation	1	50.00	\$ 50.00
VAC Assessment Fee	1	135.00	\$ 135.00

REMARKS	GROSS AMOUNT	\$	201.00
CTPL	GST @ 7%	\$	14.07
	INVOICE AMOUNT	\$	215.07

This is a computer generated TAX INVOICE

No signature required

Cheque should be made payable to 'VICOM LTD'.

Sin Ming

205 Tanjong Pagar Road Singapore 0625718
Tel: (65) 6458 4555 Fax: (65) 6458 1040

Bukit Batok

511 Bukit Batok Street Singapore 650501
Tel: (65) 6740 1111 Fax: (65) 6740 1112

Kaki Bukit

511 Kaki Bukit Ave 4 Singapore 415001
Tel: (65) 6741 0097 Fax: (65) 6740 1112

COMFORTDELGRO ENGINEERING PTE LTD
 #205 Braddell Road
 Blk C Ext 1 3rd Level
 Singapore 579701



VICOM LTD
 285 Sin Ming Drive Singapore 575718

Mobile (65) 6458 4555
 Facsimile (65) 6458 1040

www.vicom.com.sg
 Company Registration No. 198700018

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No.	: 527174	Claim No.	: 305166205
Accident Date	: 28/05/2018	Claim Type	: THIRD PARTY
Assignment Date	: 24/05/2018	Policy No.	:
Survey Date	: 30/05/2018	Finalised Dt.	:
Survey Report Date	: 09/07/2018		

VEHICLE PARTICULARS

Vehicle No.	: SHD3444S	Chassis No.	: JTDKB3FU703529605
Registration Date	: 14/09/2016	Engine No.	: OBSCURED
Make	: TOYOTA	Engine Cap.	: 1798CC
Model	: PRIUS HYBRID	Transmission	: AUTO
		Colour	: BLUE

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 276074KM		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	195/65R15	WESTLAKE	6
FRONT LH	195/65R15	WESTLAKE	6
REAR RH	195/65R15	WESTLAKE	6
REAR LH	195/65R15	WESTLAKE	6

SURVEY CONDUCTED AT

ComfortDelGro Engineering Pte Ltd,
 59 Loyang Drive Singapore 508969.
 Assignment given by: MVA Larry (C.D.G.E.)

REMARKS

- [1] Workshop Estimate : S\$ 2,179.60
 [2] Our Adjustment : S\$ 1,323.77
 [3] Repair Period : 2 days
 [4] We have not authorised repairs. This survey was carried out on without prejudice basis.

VICOM LTD
SURVEY REPORT

SHD3444S @ 28/05/2018

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Deformed	458.60	458.60
2	1	Rear Bumper Reinforcement	Reuse	318.80	0.00
3	1	Rear Bumper Under Cover	Deformed	552.60	552.60
4	1	Rear Bumper Side Retainer	Reuse	112.70	0.00
5	10	Rear Bumper Clips	Waived	22.00	0.00
6	1	Rear Floor Cover	Snapped	220.50	220.50
Subtotal				1685.20	1231.70
Less 25 %				421.30	307.93
TOTAL				1263.90	923.77

SPECIAL NETT ITEM

1	1	Rear Bumper Reverse Sensor	Reuse	135.70	0.00
2	1	Rear Bumper Rubber Mat	Waived	50.00	0.00
TOTAL				185.70	0.00

TOTAL FOR SPARE PARTS : 1449.60 923.77

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	280.00	200.00
2	Spray painting	280.00	200.00
3	Wiring charges (waived)	50.00	0.00
4	Remove/ refix reverse sensor (waived)	120.00	0.00
TOTAL FOR LABOUR AND SPRAY PAINTING		730.00	400.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	1449.60	923.77
TOTAL FOR LABOUR AND SPRAY PAINTING	730.00	400.00
TOTAL REPAIR COST	2179.60	1323.77

SURVEY REPORT**Annex C: Conclusion****ASSESSOR'S REPORT**

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$2,179.60. We adjusted it to S\$1,323.77 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$1,323.77.

The repairs would require a period of 2 working days.



Kamarudin Abdul Kadir
for VICOM Ltd

p/p \$1158.40 / 2 hrs



Your Ref: AEMD/105/009/2018/088

Date: 14th May 2019

Our Ref: CS1/SPF19008150/K1qd3s2

M/s Automotive Engineering & MGT Division

Accident Claim Section (S'pore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

Attn: Hafizul Farhan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHD 3444S
INSURED VEHICLE: QX 312Y ACCIDENT DATE: 28/05/2018**

We thank you for your instruction on 08/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHD 3444S from M/s Vicom Ltd.
- b) Colour damaged vehicle photographs of SHD 3444S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHD 3444S
Make & Model	: Toyota Prius Hybrid
Year of Registration	: 2016
Chassis Number	: JTDKB3FU703529605
Engine Capacity	: 1798 cc

2. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3444S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	REUSE	318.80	-
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	REUSE	112.70	-
10	REAR BUMPER CLIPS	WAIVED	22.00	-
1	REAR FLOOR COVER	NO DAMAGE	220.50	-
	LESS 25% DISCOUNT		-421.30	-252.80
			1,263.90	758.40
SPECIAL NETT ITEMS				
1	REAR BUMPER REVERSE SENSOR (SN)	REUSE	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	WAIVED	50.00	-
			185.70	-
LABOUR				
	LABOUR CHARGES.		280.00	200.00
	SPRAY PAINTING.		280.00	200.00
	WIRING CHARGES.	WAIVED	50.00	-
	REMOVE / REFIX REVERSE SENSOR.	WAIVED	120.00	-
			730.00	400.00
GRAND TOTAL			2,179.60	1,158.40
RECOMMENDED COST OF REPAIRS				1,158.40

Report Ref No. CS1/SPF19008150/K1qd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,100.00 - \$1,400.00

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.