



# CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit, Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No: 201718369R

GST Reg No: 201718369/05/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TPALG.  
Asker.

Accident date: 05/05/2019

Estimated repair cost for vehicle no: SIX6158U MITSUBISHI LANCER 1.6 M GLX '10

CHASSIS: JMYSNCS3AAU006382

S/n	Qty	Items / Nett	U/price	Amount	
1	1	Rear Boot Lid <i>Repair</i>		\$587.00	+
2	2	Rear Boot Lid Hinge <i>new</i>	\$69.00	\$138.00	+
3	1	Rear Boot Lid Inner Lock <i>new</i>		\$125.00	+
4	1	Rear Boot Lid Inner Rubber <i>new</i>		\$158.00	+
5	1	Rear L/H Tail Lamp <i>cracked</i>		<del>\$436.00</del>	344
6	2	Rear L/H Tail Lamp Clip <i>new</i>	\$8.00	\$16.00	✓
7	1	Rear L/H Tail Lamp Panel <i>Repair</i>		\$121.00	+
8	1	Rear Bumper <i>dent</i>		\$624.00	✓
9	10	Rear Bumper Clip <i>new</i>	\$6.50	<del>\$65.00</del>	30
10	2	Rear Bumper Side Retainer <i>new</i>	\$28.00	\$56.00	✓
11	1	Rear L/H Bumper Mud Shield <i>new</i>		\$83.00	+
12	4	Rear L/H Bumper Mud Shield Clip <i>new</i>	\$6.50	\$26.00	+
13	1	Rear Bumper Centre Beam <i>Best</i>		\$219.00	✓
14	1	Rear End Panel <i>dent</i>		\$398.00	✓
15	1	Rear End Panel Top Garnish <i>dent</i>		\$141.00	✓
16	1	Rear L/H Fender <i>Repair</i>		\$696.00	+
17	1	Rear L/H Fender Inner Trim Board <i>to be</i>		\$212.00	✓
18	8	Rear L/H Fender Inner Trim Board Clip <i>new</i>	\$6.50	<del>\$52.00</del>	30
19	1	Rear Windscreen Top Moulding <i>new</i>		\$108.00	+
20	1	Rear Windscreen Lower Moulding <i>new</i>		\$166.00	+
21	20	Rear Windscreen Side Moulding Clip <i>new</i>	\$3.50	\$70.00	+
22	1	Rear Reverse Sensor (Special Nett) <i>dent</i>		<del>\$350.00</del>	100(SN)
23	1	Body Kit (1 Set) (Special Nett) <i>dent</i>		<del>\$2,500.00</del>	80(SN)

Subtotal :- \$7,347.00

2070 SN: 960  
1863

Labour charges

To remove & refit cushion		<del>\$280.00</del> 60.
To remove & refit reverse sensor		<del>\$100.00</del> 50.
To remove & refit rear camera		\$180.00 X
To remove & refit rear windscreen		\$120.00 X
Gum		\$50.00 X
To check wiring	1820	<del>\$100.00</del> 30
Tuff kote		<del>\$150.00</del> 80
Panel beating		<del>\$1,600.00</del> 800
Spray painting		<del>\$1,600.00</del> 800.

Subtotal :- \$4,180.00

Total :- \$11,527.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total: 4633  
 c/s: 37k.  
 05 Days.  
 (3.7k.)