

INS. CASE OWNER:

CC 6, LPC 1900 8163, A903/12

LKK:  
IDAC:

Surveyor:

LWP

DOI:

ASSIGNMENT

6/5/19

Date / Time:

6/5/19

Registered in Mermen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XB 9052 X

Name of Insured:

De International P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

3/5/2019

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Al zhi bao

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

18/19/19/2008/02755

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLT 3014 T



INSRS:

WSP: My Solution

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SLT 3014 T. X; XB 9052 X. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

45

S\$9,300

( 5 days)

Reduction:

49

%

Email

Call

FINAL SETTLEMENT

Date/Time: 19-07-19

Confirm with: Sy Wong

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

w/69

S\$5,671.00

Loss of Rental (LOR):

S\$

( days)

Loss of Use (LOU):

S\$ 400.00

(\$ 80

x 5 days)

Loss of Income (LOI):

S\$

(\$

x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$ 6,078.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 19-07-19

Confirm with: Sy Wong

Email

Call

Payee 1:

S\$ 6,078.45

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$ 450

COPY SENT  
11/9/19

ASS. REC. BY:

REF:

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLT30147 Yr Regn: 2017 / OctType: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota CHR Hybrid c.c 1797Colour: White A/C: Insured / Std / Nil / NASp. Reading: SS511 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: 27X 102059372Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 215/60R17R: 215/60R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 06/05/19Survey held at MG SolutionDes. of Damages FR Rear / O/S N/S / UIC / Rooftop orO/S Front

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                        |
|-------------|---------------------------------------------|
|             | <u>TP Lon Pac</u>                           |
|             | <u>(LIS \$5,300 / Res \$5,066.50 / 49%)</u> |
|             | <u>MV:</u>                                  |
|             | <u>PV:</u>                                  |
|             | <u>Nett:</u>                                |

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1)

2)

IN

OUT

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

Prel. Report:

Final Report:



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19/VC05/021755  
Our ref: CC6/LPC19008163/Apa3

Date: 23/05/2019

The Motor Claims Department  
M/s Lonpac Insurance Bhd

DearSirs/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLT3014T**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06/05/2019 at the premises of M/s MG SOLUTION PTE LTD, and have the following to report:-

|                               |       |           |
|-------------------------------|-------|-----------|
| Workshop Estimate Amount      | : S\$ | 10,366.50 |
| Revised Estimate Amount       | : S\$ | 5,300.00  |
| "Check" Items Amount          | : S\$ |           |
| Total (Including Check Items) | : S\$ |           |
| Market Value                  | : S\$ | (est)     |
| LTA Reimbursement Value       | : S\$ | (est)     |
| Nett Value                    | : S\$ | (est)     |

**Description of Damage:**

The vehicle sustained damages at the  
Front & O/S Front Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

ADRIAN LING  
Licensed Appraiser

# MG SOLUTION PTE.LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

|                                 |                           |          |              |
|---------------------------------|---------------------------|----------|--------------|
| TO                              | : LONPAC                  | DATE     | : 6-May-19   |
| ATTENTION                       | : MOTOR CLAIMS DEPT       | JOB TYPE | : T/P CLAIM  |
| ESTIMATE REPORT                 | :                         |          |              |
| <u>VEHICLE DETAILS</u>          |                           |          |              |
| VEHICLE NO                      | : SLT3014T                |          |              |
| MODEL                           | : TOYOTA C-HR HYBRID 1.8S |          | 2YX102059372 |
| CHASSIS NO                      | :                         |          | Xiao Tong    |
| <u>ACCIDENT DETAILS</u>         | DATE : 3-May-19           |          |              |
|                                 | TIME : 14:00PM            |          |              |
| THIRD PARTY REQUESTOR / CONTACT | : JACK LI                 |          |              |

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                              | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT BUMPER <i>Rips torn</i>            | 1   | \$ 830.00       | \$ 830.00        |
| 2   | FRONT BUMPER SIDE RETAINER RH <i>new</i> | 1   | \$ 62.30        | \$ 62.30         |
| 3   | HID HEADLAMP RH <i>new curved</i>        | 1   | \$ 1,955.20     | \$ 1,955.20      |
| 4   | FRONT FENDER RH <i>Dented</i>            | 1   | \$ 530.50       | \$ 530.50        |
| 5   | FRONT FENDER INNER COWLING RH <i>new</i> | 1   | \$ 160.20       | \$ 160.20        |
| 6   | FRONT FENDER EMBLEM RH <i>new</i>        | 1   | \$ 90.00        | \$ 90.00         |
| 7   | WHEEL ARCH RH <i>cut</i>                 | 1   | \$ 190.00       | \$ 190.00        |
| 8   | FRONT DOOR RH <i>Dented.</i>             | 1   | \$ 1,455.80     | \$ 1,455.80      |
| 9   | FRONT DOOR HINGE(UPPER) <i>green</i>     | 1   | \$ 92.50        | \$ 92.50         |
| 10  | FRONT DOOR HINGE(LOWER)                  | 1   | \$ 92.50        | \$ 92.50         |
| 11  | FRONT DOOR CHECKER <i>new</i>            | 1   | \$ 160.00       | \$ 160.00        |
| 12  | FRONT DOOR STICKER <i>new</i>            | 1   | \$ 110.00       | \$ 110.00        |
| 13  | FRONT DOOR OUTER PROTECTOR <i>cut</i>    | 1   | \$ 322.50       | \$ 322.50        |
| 14  | SIDE SKIRT RH <i>new</i>                 | 1   | \$ 680.50       | \$ 680.50        |
| 15  | FRONT SIDE MIRROR COVER RH <i>Ry</i>     | 1   | \$ 130.00       | \$ 130.00        |
| 16  | FRONT SIDE MIRROR RH <i>new</i>          | 1   | \$ 920.00       | \$ 920.00        |

6138.20  
4599.90

|                 |             |
|-----------------|-------------|
| TOTAL PRICE     | \$7,782.00  |
| LESS 25%        | \$ 1,945.50 |
| SUB TOTAL PRICE | \$5,836.50  |

| S/N | DESCRIPTION                                      | QTY | UNIT S/NETT | TOTAL S/NETT |      |
|-----|--------------------------------------------------|-----|-------------|--------------|------|
| 1   | FRONT BUMPER CLIPS(SET) <i>new</i>               | 1   | \$ 25.00    | \$ 25.00     | +    |
| 2   | FRONT FENDER INNER COWLING LH (CLIPS) <i>new</i> | 1   | \$ 25.00    | \$ 25.00     | ✓    |
| 3   | FRONT FENDER SEALANT <i>new</i>                  | 1   | \$ 80.00    | \$ 80.00     | ✓    |
| 4   | HEADLAMP CLIPS(SET) <i>new</i>                   | 1   | \$ 20.00    | \$ 20.00     | ✓    |
| 5   | WHEEL ARCH CLIP(SET) <i>new</i>                  | 1   | \$ 20.00    | \$ 20.00     | ✓    |
| 6   | FRONT SIDE SKIRT CLIPS(SET) <i>new</i>           | 1   | \$ 20.00    | \$ 20.00     | +    |
| 7   | WHEEL TYRE <i>new</i>                            | 1   | \$ 380.00   | \$ 380.00    | 180. |
| 8   | WHEEL RIM <i>new</i>                             | 1   | \$ 850.00   | \$ 850.00    | 450  |
|     |                                                  | 650 | TOTAL       | \$1,420.00   |      |

#### CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

| S/N   | JOB DESCRIPTION                                                | PRICE       | ADJUSTED COST | APPROVED |
|-------|----------------------------------------------------------------|-------------|---------------|----------|
| 1     | TO PANEL BEAT, REMOVE AND REPLACE PARTS                        | \$ 1,200.00 | 600.          |          |
| 2     | TO SPRAY PAINT AFFECTED AREA                                   | \$ 1,200.00 | 700           |          |
| 3     | MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC. | \$ 180.00   | +             |          |
| 4     | WIRING CHECK                                                   | \$ 100.00   | 30            |          |
| 5     | TO REFOCUS HEADLAMP BEAM                                       | \$ 250.00   | +             |          |
| 6     | TO REMOVE AND REFIX FRONT DOOR RH                              | \$ 180.00   | 80            |          |
| TOTAL |                                                                | \$3,110.00  |               | 1410     |

#### ESTIMATE REPORT

TOTAL PARTS COST : \$7,256.50  
 TOTAL LABOUR COST : \$3,110.00  
 TOTAL REPAIR COST : \$10,366.50

#### APPROVED DETAILS

EXCESS :  
 NO. OF WORKING DAYS :  
 RE-SURVEY :  
 PART BY PART OR LUMP SUM :  
 DATE & TIME OF SURVEY :  
 SURVEYED BY :  
 CONTACT NUMBER :  
 FAX NUMBER :

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sig

Adrian Lij total: 6655.50  
 H/c 06/05/19. C/s: 531c

05 Days

## Mei Kwan (LKKAUTO)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 9 May, 2019 12:17 PM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Direct Settlement - Accident Involving XB9052X (OI : LPC - TBA) AND SLT3014T (TP : LKK REF - CC6/LPC19008163/Apa3) on 03/05/2019 [External Confidential]  
**Attachments:** 09052019121351.pdf

### Lonpac External - Confidential

Our Ref : 18/19/19/VC05/021755

Dear Mei Kwan,

Attached copy of insured's report for your attention.

The premium for the policy has been settled.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



*Lonpac External - Confidential data is for use by authorised external parties only.*

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Thursday, 9 May, 2019 12:02 PM  
**To:** MT\_Claim\_SG  
**Cc:** ONG LI LI; GERALD POH WEE BIN; Hsiao Tong (LKKAUTO); CS A Team; Admin A  
**Subject:** Direct Settlement - Accident Involving XB9052X (OI : LPC - TBA) AND SLT3014T (TP : LKK REF - CC6/LPC19008163/Apa3) on 03/05/2019

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLT 3014T at M/s MG Solution Pte Ltd - Kaki Bukit on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:  
- TP GIA report





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                                    |      |                              |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|------|------------------------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                                                    |      | Ref : CC6/LPC19008163/Aea3n2 |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                                                    |      | Date : 12-09-2019            |  |
|                                                                                                                                        |                                                                                                                    |      | Code : LPC2                  |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                                    |      |                              |                                                                                     |
| Insured Veh.                                                                                                                           | XB 9052X                                                                                                           |      | Veh. Inspected               | SLT 3014T                                                                           |
| Policy No.                                                                                                                             | Z18VC05000300                                                                                                      |      | Coverage (\$)                | 0.00                                                                                |
| Claim No.                                                                                                                              | 18/19/19/VC05/021755                                                                                               |      | Excess (\$)                  | 0.00                                                                                |
| Assign From                                                                                                                            |                                                                                                                    |      | Assign Date                  | 06/05/2019                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                                    |      |                              |                                                                                     |
| Make & Model                                                                                                                           | TOYOTA C-HR HYBRID                                                                                                 |      | c.c                          | 1797                                                                                |
| Engine No.                                                                                                                             | HIDDEN                                                                                                             |      | Year of Reg.                 | 2017                                                                                |
| Chassis No.                                                                                                                            | ZYX102059372                                                                                                       |      | Colour                       | WHITE                                                                               |
| Odometer                                                                                                                               | 55511                                                                                                              |      | Steering                     | IN ORDER                                                                            |
| Brakes                                                                                                                                 | IN ORDER                                                                                                           |      | Modification                 | SPORTS RIM                                                                          |
| General                                                                                                                                | GOOD                                                                                                               |      |                              |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                                    |      |                              |                                                                                     |
|                                                                                                                                        |                                                                                                                    | Size | Make                         | Balance                                                                             |
| R/H Front Tyre                                                                                                                         | 215/60 R17                                                                                                         |      | BRIDGESTONE                  | 6 mm                                                                                |
| L/H Front Tyre                                                                                                                         | 215/60 R17                                                                                                         |      | BRIDGESTONE                  | 6 mm                                                                                |
| R/H Rear Tyre                                                                                                                          | 215/60 R17                                                                                                         |      | BRIDGESTONE                  | 6 mm                                                                                |
| L/H Rear Tyre                                                                                                                          | 215/60 R17                                                                                                         |      | BRIDGESTONE                  | 6 mm                                                                                |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                                    |      |                              |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                                                                    |      |                              |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                                                    |      |                              |                                                                                     |
| Accident Date                                                                                                                          | 03/05/2019                                                                                                         |      | Inspection Date              | 06/05/2019                                                                          |
| Survey held at                                                                                                                         | MG SOLUTION PTE LTD<br>23 KAKI BUKIT AVE 4<br>(SOUTH WING) #02-03B<br>VICOM INSPECTION CENTRE,<br>SINGAPORE 415933 |      |                              |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                                    |      |                              |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                    |      |                              |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                                    |      |                              |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                                    |      | <b>5 Working Days</b>        |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3014T

| Qty                         | Description of Parts                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                           |                      |                           |                   |
| 1                           | FRONT BUMPER                              | TORN                 | 830.00                    | 830.00            |
| 1                           | FRONT BUMPER SIDE RETAINER RH             | NOT NECESSARY        | 62.30                     | -                 |
| 1                           | HID HEADLAMP RH                           | CRACKED              | 1,955.22                  | 1,955.20          |
| 1                           | FRONT FENDER RH                           | DENTED               | 530.50                    | 530.50            |
| 1                           | FRONT FENDER INNER COWLING RH             | NOT NECESSARY        | 160.20                    | -                 |
| 1                           | FRONT FENDER EMBLEM RH                    | NECESSARY            | 90.00                     | 90.00             |
| 1                           | WHEEL ARCH RH                             | CUT                  | 190.00                    | 190.00            |
| 1                           | FRONT DOOR RH                             | DENTED               | 1,455.80                  | 1,295.00          |
| 1                           | FRONT DOOR HINGE (UPPER)                  | NOT NECESSARY        | 92.50                     | -                 |
| 1                           | FRONT DOOR HINGE (LOWER)                  | NOT NECESSARY        | 92.50                     | -                 |
| 1                           | FRONT DOOR CHECKER                        | NOT NECESSARY        | 160.00                    | -                 |
| 1                           | DFRONT DOOR OUTER PROTECTOR               | CUT                  | 322.50                    | 322.50            |
| 1                           | SIDE SKIRT RH                             | NOT NECESSARY        | 680.50                    | -                 |
| 1                           | FRONT SIDE MIRROR COVER RH                | TO REPAIR SEE LABOUR | 130.00                    | -                 |
| 1                           | FRONT SIDE MIRROR RH                      | DAMAGED              | 920.00                    | 920.00            |
|                             | LESS 25% DISCOUNT                         |                      | -1,918.01                 | -1,533.30         |
|                             |                                           |                      | 5,754.01                  | 4,599.90          |
| 1                           | FRONT DOOR STICKER (SN)                   | NECESSARY            | 110.00                    | 60.00             |
|                             | LESS 25% DISCOUNT                         |                      | -27.50                    | -                 |
|                             |                                           |                      | 82.50                     | 60.00             |
| <b>SPECIAL NETT ITEMS</b>   |                                           |                      |                           |                   |
| 1                           | SET FRONT BUMPER CLIPS (SN)               | NOT NECESSARY        | 25.00                     | -                 |
| 1                           | FRONT FENDER INNER COWLING LH (CLIPS)(SN) | NOT NECESSARY        | 25.00                     | -                 |
| 1                           | FRONT FENDER SEALANT (SN)                 | NOT NECESSARY        | 80.00                     | -                 |
| 1                           | SET HEADLAMP CLIPS (SN)                   | NOT NECESSARY        | 20.00                     | -                 |
| 1                           | SET WHEEL ARCH CLIP (SN)                  | CUT                  | 20.00                     | 20.00             |
| 1                           | SET FRONT SIDE SKIRT CLIPS (SN)           | NOT NECESSARY        | 20.00                     | -                 |
| 1                           | WHEEL TYRE (SN)                           | CUT                  | 380.00                    | 180.00            |

Report Ref No. CC6/LPC19008163/Aea3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                            | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1                                                                           | WHEEL RIM (SN)                                                                                  | CUT           | 850.00                    | 450.00            |
|                                                                             |                                                                                                 |               | 1,420.00                  | 650.00            |
|                                                                             | <b>LABOUR</b>                                                                                   |               |                           |                   |
|                                                                             | TO PANEL BEAT ,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF FRONT SIDE MIRROR COVER RH . |               | 1,200.00                  | 600.00            |
|                                                                             | TO SPRAY PAINT AFFECTED AREA.                                                                   |               | 1,200.00                  | 700.00            |
|                                                                             | MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.                                 | NOT NECESSARY | 180.00                    | -                 |
|                                                                             | WIRING CHECK.                                                                                   |               | 100.00                    | 30.00             |
|                                                                             | TO REFOCUS HEADLAMP BEAM .                                                                      | NOT NECESSARY | 250.00                    | -                 |
|                                                                             | TO REMOVE AND REFIX FRONT DOOR RH .                                                             |               | 180.00                    | 80.00             |
|                                                                             |                                                                                                 |               | 3,110.00                  | 1,410.00          |
|                                                                             | <b>GRAND TOTAL</b>                                                                              |               | <b>10,366.51</b>          | <b>6,719.90</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                 |               |                           | <b>5,300.00</b>   |

Report Ref No. CC6/LPC19008163/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.