

22/03/2002

ASS. REC. BY:

REF: CS3/CT11900 8175/T1cd302

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CT1

Date/Time: 9.5.19 10.30a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 88945

Insured: PC48974

at Workshop m/s Carsmith Private

Tel: 90910000

of 13 Kaki Bukit Road 4 # 01-20

Policy No: DMBISN1F326019022

Claim No: SNM190202053002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 6.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement:

Date/Time: 9.5.19 11.40a.m

Person Contacted: Alex

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SLS 88945 - X
	PC 48974 - X
	Disassemble: 10/5/2019
	After repair: 14/5/2019

Surveillance

Tanp...

REF: C71

PRS

ASSIGNMENT

From: Date: 9.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL58894 S

at Workshop m/s Carsmith

of 13 kaki Bukit Road 4 #01-20

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"WOP"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SL58894S Yr Regn: 2017 OCT

Type: M.Cnr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra c.c 1591

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 19470 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHD841CMJ4 530465

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 9/5/19

Survey held at Carsmith

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

96000 - 97000, 8 days.

18/6/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: PRE.

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		13 May 2019 14:44 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: TAN CHIAN LOONG , ID: S7605877F									
Vehicle Reg. No.: SLS8894S		Date of Loss: 06/05/2019 06:00 - :59							
Claim Type: TP / SNM19D202053C02		Policy/Cover Note No.: DMB1SN17326019022							
Vehicle Reg. No. (Insured): PC4897Y		Policy No. (Claimant): 5104464794							
		Excess: S\$0.00							
Repairer: Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 9 May 2019 10:30 AM
To: Jerdine
Cc: jiamin.mak@alt.sg; vincent@alt.sg; allister@alt.sg; assignments
Subject: RE: PRI - SLS 8894 S / China Vehicle: PC4897Y

Dear LKK,

Pls assist with necessary as per Chin Kiat's email below.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jerdine [mailto:jerdine.wang@alt.sg]
Sent: Thursday, 9 May, 2019 10:20 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: jiamin.mak@alt.sg; vincent@alt.sg; allister@alt.sg
Subject: FW: PRI - SLS 8894 S / China Vehicle: PC4897Y

Dear Boon Sen,

As spoken.

Thank you very much.

Best Regards,

Jerdine

For and on behalf of
Allister Lim

ALLISTER LIM & THRUMURGAN ADVOCATES & SOLICITORS

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6438 3303
DID: 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

From: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Sent: Tuesday, 7 May 2019 5:38 PM
To: jiamin.mak@alt.sg
Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; 'carsmith' <carsmithpl@gmail.com>
Subject: RE: PRI - SLS 8894 S / China Vehicle: PC4897Y

Without Prejudice

Dear Jiamin,

We are not agreeable to your surveyor for SJE.

We shall proceed to appoint our surveyor LKK to proceed with the pre repair inspection.

Kindly let us have your client's workshop contact details

Thank you.

Ong Chin Kiat

Assistant Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6174 | F: (65) 6224 7174 / 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: jiamin.mak@alt.sg [<mailto:jiamin.mak@alt.sg>]
Sent: Tuesday, 7 May, 2019 4:46 PM
To: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; 'carsmith' <carsmithpl@gmail.com>
Subject: RE: PRI - SLS 8894 S / China Vehicle: PC4897Y

Dear Sir,

We refer to your email dated 7 May 2019.

We have our client's instructions to reject your proposal on your Single Joint Expert.

We propose to use the motor surveyor(s) named in the list below to conduct the joint pre-repair survey as a Single Joint Expert:

- WG Appraisal Services

Kindly let us hear from you within 2 working days as per the new NIMA protocol failing which we will proceed with the necessary.

Thank you.

Best Regards,

Jiamin

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

From: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Sent: Tuesday, May 7, 2019 3:18 PM
To: jiamin.mak@alt.sg
Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; 'carsmith' <carsmithpl@gmail.com>
Subject: RE: PRI - SLS 8894 S / China Vehicle: PC4897Y

Without Prejudic

Dear Sirs,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Ong Chin Kiat

Assistant Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6174 | F: (65) 6224 7174 / 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: jiamin.mak@alt.sg [mailto:jiamin.mak@alt.sg]

Sent: Tuesday, 7 May, 2019 12:05 PM

To: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: jerdine.wang@alt.sg; vincent@alt.sg; allister@alt.sg; 'carsmith' <carsmithpl@gmail.com>

Subject: PRI - SLS 8894 S

Your Ref: PC 4897 Y

Our Ref: AL.INS.2019.SLS8894S

7 May 2019

**CHINA TAIPING INSURANCE (SINGAPORE)
COMPANY LTD**

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

BY EMAIL ONLY

Dear Sirs,

ACCIDENT INVOLVING SLS 8894 S & PC 4897 Y ALONG SELETAR WEST LINK TOWARDS CTE (CITY) ON 6 MAY 2019 AT ABOUT 0645 HOURS

We act for the owner of vehicle no. SLS 8894 S.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

CARSMITH PRIVATE LIMITED
13 Kaki Bukit Road 4
#01-20 Bartley Biz Centre

Singapore 417807
Person In-Charge: Alex
Mobile Number: 9091 0000

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at jiamin.mak@alt.sg / jerdine.wang@alt.sg for future correspondences.

Best Regards,

Jiamin

For and on behalf of
Allister Lim

**ALLISTER LIM & THRUMURGAN
ADVOCATES & SOLICITORS**

111 North Bridge Road
#11-04 Peninsula Plaza
Singapore 179098
Telephone : 6422 2187
Facsimile : 6438 1211

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at mail@alt.sg and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5877F
Vehicle Details	
Vehicle No.:	SLS8894S
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	G4FGHU787852
Chassis No.:	KMHD841CMJU550465
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,482.00
Original Registration Date:	10 Oct 2017
First Registration Date:	10 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$12,482.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Oct 2027
PARF Rebate Amount:	\$9,361.00
Intended COE Rebate Details	
COE Expiry Date:	09 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,902.00
COE Rebate Amount:	\$35,629.00
Total Rebate Amount:	\$44,990.00

The information contained herein is correct as at 19 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/05/2019 14:34
Date Of Accident	06/05/2019 06:45
Exact Location Of Accident	SELETAR WEST LINK TWRDS CTE(CITY)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLS8894S
Insured/Policyholder	
Name Of Registered Owner	TAN CHIAN LOONG
NRIC No	S7605877F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97862122
Alternative Phone No	OTHERS-97862122
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104464794
Cover Note Number	
Driver	
Name of Driver	TAN CHIAN LOONG
NRIC No	S7605877F
Date Of Birth	29/02/1976
Occupation	INDOOR
Date Of Driving Pass	17/09/2012
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97862122
Fax Number	
Contact Number	OTHERS-97862122
Email Address	NOEMAIL

Address	BLK 274 #07-148 YISHUN STREET 22
Postcode	760274
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4897Y
Vehicle Make/Model/Colour	TOYOTA HIACE COMMUTER 3.0 GL AT
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

06 MAY 2019

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Reporting Centre Personnel's Signature
Name: Singapore 415933
Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 06/05/2019 at about 0645hrs I was travelling along Seletar West Link toward the direction of CTE (city). The vehicle in front of me slowed down & I proceed to slow down, Out of sudden I felt a strong impact from the rear of my vehicle. I stopped & alighted to found out that Vehicle B had rear ended my vehicle. The rear of my vehicle was badly damage due to the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

06 MAY 2019

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4
Singapore 115933

Reporting Centre Person's Name: *[Signature]*
Tel: 67492305
Fax: 67492305
Email: vackb@singnet.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 May 2019		13 May 2019 14:44 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	TAN CHIAN LOONG , ID: S7605877F								
Vehicle Reg. No.:	SLS8894S	Date of Loss:	06/05/2019 06:00 - :59 [18 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202053C02	Policy/Cover Note No.:	DMB1SN17326019022						
Vehicle Reg. No. (Insured):	PC4897Y	Policy No. (Claimant):	5104464794						
		Excess:	S\$0.00						
Repairer:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/05/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS8894S (SNM19D202053C02)

[PC4897Y]

TP



















































TAN CHIAN LOONG






































May 6 2019 6:00AM

[-]


Carsmith Private Limited











Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)								Thumbnail	Print	
1	06/05/19 14:44	Accident Statement								Load HTM		
Photos/Images									3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)								Thumbnail	Print	
1	06/05/19 14:43	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
2	06/05/19 14:43	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
3	06/05/19 14:43	Driving License [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
4	06/05/19 14:43	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
5	06/05/19 14:43	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
6	06/05/19 14:43	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
7	06/05/19 14:43	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
8	06/05/19 14:43	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
2	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
3	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
4	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
5	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
6	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
7	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
8	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
9	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
10	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
11	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
12	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
13	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
14	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
15	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
16	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
17	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
18	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
19	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
20	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
21	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	
22	19/06/19 18:31	General View								Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
23	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/06/19 18:31	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
73	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	19/06/19 18:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	20/06/19 15:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	20/06/19 15:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	20/06/19 15:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	20/06/19 15:30	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 14:45	PRI CONTACT	 Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/05/19 14:44	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	06/05/19 14:44	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/05/19 14:44	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/05/19 14:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	06/05/19 14:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	06/05/19 14:43	Driving License	 Load JPG	<input checked="" type="checkbox"/>
4	06/05/19 14:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	06/05/19 14:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	06/05/19 14:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	06/05/19 14:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	06/05/19 14:43	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/05/19 14:44	Sketch Plan	 Load TIF	
2	06/05/19 14:44	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19008175/T1CD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN17326019022

Claimant Vehicle
No: SLS8894SInsured Vehicle
No: PC4897Y

Date of Loss: 06/05/2019

Nature of Claim: TP

Claim
No: SNM19D202053C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS8894S

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Reg. Date: 10/10/2017 (Man. Year: 2017)

Colour: White

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: G4FGHU787852

Chassis No: KMHD841CMJU550465

Odometer: 19470 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/05/2019

Date Inspected: 09/05/2019 Inspected At:

Carsmith Private Limited (HQ)
13 KAKI BUKIT ROAD 4 #01-20 BARTLEY
BIZ CENTRE
Singapore 417807

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS8894S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >