

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLJ7462J/1905064

08th May 2019

The Manager
Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street
#04/05 IOB Building
Singapore 049711

Date of Accident : 07th May 2019
Location : Holland Road
Third Party Claim Vehicle No : SGH 1179 L
Repair Cost For Vehicle No : SLJ 7462 J Toyota Harrier

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia	DD/de 1	1,381.50	\$ 1,381.50
2	Rear bumper clips	nee 1set	38.00	\$ 38.00
3	Rear bumper lower lip	DD 1	586.30	\$ 586.30
4	Rear bumper lower lip reflector L&RH	11 2	54.10	\$ 108.20 X
5	Rear bumper sponge	To. 1	137.10	\$ 137.10 2
6	Rear bumper side retainer L&RH	11 2	90.80	\$ 181.60 X
7	Rear boot cover w/strip	11 1	387.30	\$ 387.30 X
8	Rear boot cover emblem (Harrier)	nee 1	72.10	\$ 72.10
				\$ 2,892.10
			Less 25%	\$ 723.02
				\$ 2,169.08
9	Rear bumper reverse sensor (s/nett)	shut 1	380.00	\$ 380.00 2005-2
				\$ 2,549.08

P-2215
25%
1661.25
3031.25

Not Authorized
R/H
Take photo before party.
21/5/19
3 LG.
P/P & 3031.25/

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLJ7462J/1905064

08th May 2019

Balance b/f \$2,549.08

Labour Charges :-

	<u>Amounts</u>	
Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts & re-align body	\$ 880.00	400
Remove & install rear bumper sensor	\$ 80.00	50
Spray painting on damage parts (pearl paint)	\$ 1,280.00	700
Check all lighting after repairs	\$ 35.00	20

Labour Charge \$ 2,930.00

Total Amount \$ 5,479.08

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The survey is on a "Without Prejudice" basis
- No repair work is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: