

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not allowed
like
4/5 \$4100
take the other up
Hdy.
10/5/19
9/5/2019

M/S AXA INSURANCE SINGAPORE PTE LTD JTFU735

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR YM7000P

TO SUPPLY :

List Items

- | | | |
|---|------|-------------------------------------|
| 1 | 1 PC | FRONT BUMPER |
| 2 | 1 PC | RH STEP GARNISH |
| 3 | 1 PC | RH WIPER GARNISH |
| 4 | 1 PC | FRONT RH DOOR |
| 5 | 1 PC | FRONT RH DOOR HINGE |
| 6 | 1 PC | FRONT RH DOOR WING MIRROR |
| 7 | 1 PC | FRONT RH CORNER PANEL |
| 8 | 1 PC | FRONT RH CORNER PANEL BLACK GARNISH |
| 9 | 1 PC | HEADLAMP RH |

LESS 25%

50.2

- | | |
|----|----------------|
| 10 | DOOR ARTWORK |
| | Labour Charge |
| 11 | WIRING |
| 12 | TUFF KOTE |
| 13 | LABOUR CHARGE |
| 14 | SPRAY PAINTING |

Link Auto Consultants hence notify
the insurer of the following:
• To request for a spray painting
• To request for a (part) during resurvey
• To request for a confirmation
• To request for a "Without Prejudice" basis
• To request for a resurvey
• To request for a resurvey and
• To request for a resurvey and
Acknowledged by Remco
Signature
Date

20/24	\$	549.60	—
24	\$	318.30	—
27/10/19	\$	286.40	—
27/12/19	\$	1,742.60	—
7M	\$	189.60	—
310	\$	819.70	—
27	\$	313.70	—
310	\$	117.80	—
310	\$	1,156.70	—
	\$	5,494.40	
	\$	(1,373.60)	
	\$	4,120.80	
200	\$	280.00	200 S
	\$	30.00	20
	\$	80.00	50
	\$	880.00	520
	\$	880.00	600
	\$	6,270.80	

P- 5494.4
502
P- 2747.20
S.W 200.00
1200-1190.00
4137.2