

REF: AIG

ASSIGNMENT

From:

Date:

9/5/19

Estimated Cost:

OD ☒ TP / W5 / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKZ 976S

at Workshop n/s

Optima Werkz

of

9A Serangoon North Ave 5

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKZ 976S

Vr Regn:

01 16

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy A+10

cc

1496

Colour:

M. Black

AC:

Insured / Std / NI / NA

Sp. Reading

65621

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR E161

0011824

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ YOYO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

6/5/19

D.O.I.

9/5/19

Survey field at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooltop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

61 Lm 834000 Carban

(Red \$ 2,322.22/411.1)

5 days + 1 Sunday = 6 days

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + FTL \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$

Date: 08.05.2019

Vehicle No: SKZ976S

Model: TOYOTA COROLLA AXIO 1.5X CVT

Chassis: NRE1610011824 - 2015

Reg.Year: 2016

Third Party Insurer:

AIG

Third Party Veh No:

SLE5115B

Date of Accident:

06.05.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOT LID <i>743.30</i>	1		<i>Ry</i> \$1,161.60 ✓
2	REAR BOOT LID RUBBER	1		<i>De</i> \$159.30 ✓
3	REAR BOOT LID INNER LOCK <i>94.30</i>	1		<i>Di</i> \$197.30 ✓
4	REAR BOOT LID "COROLLA" EMBLEM	1		<i>De</i> \$41.30 ✓
5	REAR BOOT LID "AXIO" EMBLEM	1		<i>De</i> \$46.20 ✓
6	REAR BOOT LID EMBLEM	1		<i>De</i> \$45.60 ✓
7	REAR BUMPER <i>698.10</i>	1		<i>Ry</i> \$1,165.56 ✓
8	REAR BUMPER SIDE BRACKET LH	1		<i>R</i> \$101.26 ✓
9	REAR BUMPER UPPER BRACKET LH (TAILLAMP)	1		<i>Di</i> \$106.26 ✓
10	REAR END PANEL	1		<i>Ry</i> \$609.30 ✓
11	REAR END PANEL UPPER TRIM COVERING	1	<i>218.90</i>	<i>De</i> \$286.40 ✓
12	REAR TAIL LAMP LH <i>548.80</i>	1		<i>My D.1</i> \$618.70 ✓
13	REAR TAIL LAMP INNER PANEL LH	1		REPAIR
14	REAR SPARE TYRE PANEL	1		REPAIR
15	REAR QUARTER PANEL LH	1		REPAIR
SUB TOTAL				\$4,538.78
LESS 25%				-\$1,134.70
PARTS TOTAL				\$3,404.09

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1 SET		<i>De</i> \$50.00 ✓
2	REAR BUMPER REVERSE SENSOR SET	1 SET		<i>CM</i> \$250.00 ✓
3	REAR END PANEL UPPER TRIM COVERING CLIPS	1 SET		<i>De</i> \$20.00 ✓
4	REAR END PANEL JOINT SEALANT	1		<i>De</i> \$80.00 ✓
S/N TOTAL				\$400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Ashish

1/1 May 8?

Repair After Paint

5 day

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 8866 Fax: (+65) 6452 9223



Date:	08.05.2019	Third Party Insurer:	AIG
Vehicle No:	SKZ9765	Third Party Veh No:	SLE5115B
Model:	TOYOTA COROLLA AXIO 1.5X CVT	Date of Accident:	06.05.2019
Chassis:	NRE1610011824 - 2015		
Reg.Year:	2016		

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & TO READJUST REAR ACCIDENT AREAS & ETC. BACK TO ORIGINAL CONDITIONS	\$800.00	600
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC	\$900.00	720
LABOUR CHARGES TO REMOVE & REINSTALL REAR BOOT LID REVERSE CAMERA, REAR BOOT LID MECHANISM INNER WIRING, REAR BUMPER REVERSE SENSOR & ETC	\$100.00	60
TO CHECK WIRING & ELECTRICAL SYSTEMS & DIAGNOSTIC SYSTEM	\$60.00	20
LABOUR TOTAL		\$1,860.00
ONG	TOTAL	\$5,664.09

Head office

6 Kung Cheng Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554506
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6888 Fax: (+65) 6452 9223



Date: 08.05.2019
Vehicle No: SKZ9765
Model: TOYOTA COROLLA AXIO 1.5X CVT
Chassis: NRE1610011824 - 2015
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SLE5115B
Date of Accident: 06.05.2019

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER INNER SIDE SHIELD LH	1		CM \$77.50
SUB TOTAL				\$77.50
LESS 25%				-\$19.38
PARTS TOTAL				\$58.13
ONG			TOTAL	\$58.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct negotiations is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head Office

6 Kung Chong Road Singapore 159142
Tel: (+65) 6472 1213 / Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554580
Tel: (+65) 6462 9919 / Fax: (+65) 6462 1813

Branch

551 Upper Thomson Road Singapore 574419
Tel: (+65) 6462 8888 / Fax: (+65) 6462 9322



[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

2455W

Vehicle Details

Vehicle No.:

SKZ9765

Vehicle to be Exported:

No

Intended Deregistration Date:

07 May 2019

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA AXIO 1.5X CVT

Primary Colour:

Black

Manufacturing Year:

2015

Engine No.:

2NR8533776

Chassis No.:

NRE1610011824

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$14,416.00

Original Registration Date:

08 Jan 2016

First Registration Date:

08 Jan 2016

Transfer Count:

0

Actual ARF Paid:

\$9,416.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

07 Jan 2026

PARF Rebate Amount:

\$7,062.00

Intended COE Rebate Details

COE Expiry Date:

07 Jan 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$45,002.00

COE Rebate Amount:

\$30,001.00

Total Rebate Amount:

\$37,063.00

The information contained herein is correct as at 07 May 2019

OK

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 12 November 2019 9:46 AM
To: sharon@ow.sg
Cc: Admin A; angela.tan@ow.sg; 'Lily Loi OW'; adeline@ow.sg
Subject: RE: LOD - ACCIDENT INVOLVING SKZ976S & SLE5115B ON 06/05/2019 (AIG) *** LKK
REF: CC4/AIG19008186/Kka3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter and your e-mail below.

We are unable to offer on loss of rental as the supporting documents are not in order.

Please provide us the amended supporting documents for the loss of rental claim.

Otherwise, we maintain our offer as follows:

1. Cost of Repair (w/GST)	\$ 3,638.00
2. Loss of Use (6 days x \$60.00)	\$ 360.00
3. LTA Search Fee	\$ 2.00
TOTAL	\$ 4,000.00

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sharon@ow.sg <sharon@ow.sg>
Sent: Thursday, 7 November 2019 12:02 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; angela.tan@ow.sg; 'Lily Loi OW' <Lily.Lo@ow.sg>; adeline@ow.sg
Subject: RE: LOD - ACCIDENT INVOLVING SKZ976S & SLE5115B ON 06/05/2019 (AIG) *** LKK
REF: CC4/AIG19008186/Kka3

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 23 October 2019 1:32 PM
To: 'sharon@ow.sg'
Cc: Admin A; angela.tan@ow.sg; 'Lily Loi OW'
Subject: RE: LOD - ACCIDENT INVOLVING SKZ976S & SLE5115B ON 06/05/2019 (AIG) *** LKK
REF: CC4/AIG19008186/Kka3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter and your e-mail below.

For amicable settlement on a without prejudice basis, we propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 3,638.00
2. Loss of Use (6 days x \$60.00)	\$ 360.00
3. LTA Search Fee	\$ 2.00
TOTAL	\$ 4,000.00

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sharon@ow.sg <sharon@ow.sg>
Sent: Tuesday, 15 October 2019 5:02 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; angela.tan@ow.sg; 'Lily Loi OW' <lily.loi@ow.sg>
Subject: RE: LOD - ACCIDENT INVOLVING SKZ976S & SLE5115B ON 06/05/2019 (AIG) *** LKK
REF: CC4/AIG19008186/Kka3

Without Prejudice

Dear Khanchna,

Khanchna (LKK Auto)

From: sharon@ow.sg
Sent: Tuesday, 15 October 2019 5:02 PM
To: Khanchna (LKK Auto)
Cc: Admin A; angela.tan@ow.sg; 'Lily Loi OW'
Subject: RE: LOD - ACCIDENT INVOLVING SKZ976S & SLE5115B ON 06/05/2019 (AIG) *** LKK
REF: CC4/AIG19008186/Kka3
Attachments: Invoice.pdf

Without Prejudice

Dear Khanchna,

Our car rental department billing wrongly. Please follow benchmark rates to offer us for the rental.

Thank you.

Best Regards,

Sharon Ten (Ms.)

Claims Executive, Motor Claims Department
D: +65 6481 1522 | F: +65 6481 1011



OPTIMA//ERKZ PTE. LTD.

Head Office: 6 Kung Chong Road Singapore 159143
Branch: 9A Serangoon North Ave 5 Singapore 554500
Branch: 452 Tagore Industrial Ave Singapore 787823

Tel: (+65) 6472 1313 Fax: (+65) 6472 2112
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011
Tel: (+65) 6452 8868 Fax: (+65) 6452 9223

www.ow.sg | www.facebook.com/OptimaWerkz

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, you must not copy, distribute or use it for any purpose, nor disclose its contents to any other person.

Please notify the sender if you receive this email in error, and delete the email and its content immediately after which.

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Sent: Tuesday, 15 October 2019 4:52 PM

To: sharon@ow.sg

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: LOD - ACCIDENT INVOLVING SKZ976S & SLE5115B ON 06/05/2019 (AIG) *** LKK REF: CC4/AIG19008186/Kka3

WITHOUT PREJUDICE

Dear Sharon,

Please forward us the tax invoice for Loss of Rental as well.

Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2019 Edit Reg		09 May 2019 00:00 Edit Adj Rpt	\$53,400.00 Edit Estimates	\$53,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAN KELVIN, ID: S7718193H		
Main Claimant:	OPTIMA WERKZ PTE LTD, Co. Reg. No.: 201212455W		
Vehicle Reg. No.:	SKZ976S	Date of Loss:	06/05/2019 17:00 - :59 [39 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3666452657SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 20/06/2018 - 19/06/2019
Vehicle Reg. No. (Insured):	SLE5115B	Policy No. (Claimant):	SD18V07597/VP2/R01
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 6 Kung Chang Road, 159143 Leng Kee - Tel: 64721313		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/05/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ9765 (3666452657SG)
[SLE5115B]
TP
OPTIMA WERKZ PTE LTD
May 6 2019 5:00PM
[TAN KELVIN]
Optima Werkz Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#) |
 [Upload Video](#) |
 [Upload Audio](#)

View View in Browser

1 per page 3 per page

Letters/Correspondences			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit

3 per page

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	28/11/19 16:15	General View		Load JPG
2	28/11/19 16:15	General View		Load JPG
3	28/11/19 16:15	General View		Load JPG
4	28/11/19 16:15	General View		Load JPG
5	28/11/19 16:15	General View		Load JPG
6	28/11/19 16:15	General View		Load JPG
7	28/11/19 16:15	General View		Load JPG
8	28/11/19 16:15	General View		Load JPG
9	28/11/19 16:15	General View		Load JPG
10	28/11/19 16:15	General View		Load JPG
11	28/11/19 16:15	General View		Load JPG
12	28/11/19 16:15	General View		Load JPG
13	28/11/19 16:15	General View		Load JPG
14	28/11/19 16:15	General View		Load JPG
15	28/11/19 16:15	General View		Load JPG
16	28/11/19 16:15	General View		Load JPG
17	28/11/19 16:15	General View		Load JPG
18	28/11/19 16:15	Chasis Number		Load JPG

1 per page

Documentation			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	09/05/19 14:53	TP GIA REPORT		Load PDF
2	14/05/19 13:20	TP ESTIMATE - MARKED		Load PDF
3	16/05/19 11:06	LETTER TO OI		Load PDF
4	03/12/19 10:47	WORKSHOP INVOICE		Load PDF
5	03/12/19 10:47	AUTHORISATION TO ACT FORM		Load PDF
6	03/12/19 10:47	Release Voucher		Load PDF
7	03/12/19 10:47	RENTAL RECEIPT		Load PDF
8	03/12/19 10:47	GIA SEARCH		Load PDF
9	03/12/19 10:47	LOD		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	10/05/19 10:30	OI GIA REPORT		Print

Documents Checklist

Reset Save Print

DOCUMENTS CHECKLIST	
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE5115B (Insd veh)	Model:	TOYOTA COROLLA AXIO
	SKZ976S (TP veh)		1.5 X (A)
Date of Accident:	06/05/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,122.76
Final Repair Cost	:	\$	3,638.00
Loss of Use	:	\$	360.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,000.00

6.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Optima Werkz Pte Ltd	:	\$ 4,000.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

03 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19008186/KKA3Q2

Date: 03/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant SKZ976S **Insured Vehicle No :** SLE5115B
Vehicle No : SKZ976S **Nature of Claim:** TP **Claim No:** 3666452657SG
Date of Loss: 06/05/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ976S**
 Make & Model: TOYOTA COROLLA AXIO, 1.5 X (A) Engine No: 2NR8533776
 Reg. Date: 08/01/2016 (Man. Year: 2015) Chassis No: NRE1610011824
 Colour: Metallic Black Odometer: 65621 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
 Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm
 Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,862.21	2,843.14	1,019.07	26.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,400.00	460.00	24.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,722.21	4,243.14	1,479.07	25.85
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	5,722.21	3,400.00	2,322.21	40.58
+ GST 7.00/7.00% (S\$)	400.55	238.00	162.55	40.58
Nett Amount (S\$)	6,122.76	3,638.00	2,484.76	40.58
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,000.00		

INSPECTION

Date of Assignment: 09/05/2019
 Date Inspected: 09/05/2019 Inspected At: 9A SERANGOON NORTH AVE 5
 SINGAPORE 554500
 Repairer: Optima Werkz Pte Ltd (HQ)
 Estimated Period of Repair: 5.0 days

Adjuster Report

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,161.60 FL	*745.30 FL
2	1		*REAR BOOT LID RUBBER	Dented	159.30 FL	*159.30 FL
3	1		*REAR BOOT LID INNER LOCK	Distorted	197.30 FL	*94.30 FL
4	1		*REAR BOOT LID COROLLA EMBLEM	Necessary	41.30 FL	*41.30 FL
5	1		*REAR BOOT LID AXIO EMBLEM	Necessary	46.20 FL	*46.20 FL
6	1		*REAR BOOT LID EMBLEM	Necessary	45.60 FL	*45.60 FL
7	1		*REAR BUMPER	Bent	1,165.56 FL	*698.10 FL
8	1		*REAR BUMPER SIDE BRACKET LH	Repair	101.26 FL	*- FL
9	1		*REAR BUMPER UPPER BRACKET LH (TAILLAMP)	Distorted	106.26 FL	*106.26 FL
10	1		*REAR END PANEL	Bent	609.30 FL	*609.30 FL
11	1		*REAR END PANEL UPPER TRIM COVERING	Dented	286.40 FL	*218.90 FL
12	1		*REAR TAIL LAMP LH	Mtg Distorted	618.70 FL	*548.80 FL
13	1		*REAR TAIL LAMP INNER PANEL LH (NPA)	Repair	0.00 FL	*- FL
14	1		*REAR SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
15	1		*REAR QUARTER PANEL LH (NPA)	Repair	0.00 FL	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
17	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	250.00 FS	*200.00 FS
18	1		*SET REAR END PANEL UPPER TRIM COVERING CLIPS	Necessary	20.00 FS	*20.00 FS
19	1		*REAR END PANEL JOINT SEALANT	Necessary	80.00 FS	*30.00 FS
20	1		*REAR BUMPER INNER SIDE SHIELD LH	Cracked	77.50 FL	*77.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 5,016.28 3,690.86

- List Item Discount on L Items 25.00/25.00% (S\$) 1,154.07 847.72

Total Parts (S\$) 3,862.21 2,843.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR & TO READJUST REAR ACCIDENT AREAS & ETC .BACK TO ORIGINAL CONDITIONS	New	800.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC	New	900.00	720.00
3	LABOUR CHARGES TO REMOVE & REINSTALL REAR BOOT LID REVERSE CAMERA ,REAR BOOT LID MECHANISM INNER WIRING ,REAR BUMPER REVERSE SENSOR & ETC	New	100.00	60.00
4	TO CHECK WIRING & ELECTRICAL SYSTEMS & DIAGNOSTIC SYSTEM	New	60.00	20.00
Gross Labour Cost (\$\$)			1,860.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >