

INS. CASE OWNER:

CC 3, CT1 1900 8189, Khas

LKK:
IDAC:

Surveyor:

Amk

DOI:

ASSIGNMENT

8/11/19

Date / Time:

8/11/19

Registered in Merimen:

Pre-assign / CCU / FTE

Sum 2m6 X



Insured Vehicle No.:

Claim No.:

Sum 90202047 / 0016

Name of Insured:

Kan Tat Leng

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

7/15/19

Place of Accident:

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHC 6086 C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SHC 6086 C - NA / IM 1013306 / r, D.O.A: 7/15/19
Sum 2m6 X - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

19/06/19 - vic

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

23-5-19

RECEIVED VIDEO FROM TP.
OI CUT LANE CAUSING
CHAIN COLLISION. - MIL.

PRELIMINARY ADVICE Date/Time:

14/05/19

Sent By:

as

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

49

SS 2,600.00 (A days) Reduction: 70 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

9-7-19

Confirm with:

SHAFAWATI

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

GST

SS 2,382.00 x 6 days 99.51 VIDEO

TP VIDEO IN

Loss of Rental (LOR):

SS

597.06

x

days

Loss of Use (LOU):

SS

-

x

days

Loss of Income (LOI):

SS

-

x

days

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

SS

2. x x

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3,381.06

Global Sum SS:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

3,381.06

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

x

Name 2:

x

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: ☒ Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Barreter: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 6086C Yr Regn: 24, 2014

Type: M. Car / M. Cycle / Bus / Van / Lorry / T/G / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 400528 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH M 414 ME 54 6820

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or Other

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 7/5/19 D.O.I. 8/5/19

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	
15/5/19	Insured 4/5 \$2600/4.07p.	7 INT CT2
	CRAB: \$6,369.60 (70%)	8 DOIW
		9 2
		10 F 3
		11 7 4
		12 5
		13 OUT

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / Bill of

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS \$ _____

Photos _____

Others _____

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19008189/K1ja3

Date: 14/05/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 6086C

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 08/05/2019 at the premises of M/s Premier Automotive Services Pte Ltd - Changi and have the following to report:-

Workshop Estimate Amount	: S\$	8,939.60
Revised Estimate Amount	: S\$	2,600.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,600.00

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6086 C

1 pc	Front o/s head lamp	X sue	\$	1,028.00
1 pc	Front bumper	/ cr	\$	531.00 ✓
1 pc	Front bumper emblem	/ m	\$	44.00 ✓
1 pc	Front o/s fender	/ head/chl	\$	384.00 ✓
1 pc	Front o/s fender inner shield	/ tan	\$	120.00 ✓
1 pc	o/s rocker panel garnish	X rep.m	\$	286.00
1 pc	Front o/s lower arm	X sue	\$	439.00
1 pc	Front o/s shock absorber	X sue	\$	330.00
1 pc	Front o/s ball joint	X sue	\$	59.00
1 pc	Front o/s driveshaft	X sue	\$	971.00
1 pc	Front insulator strut	X sue	\$	105.00
1 pc	Front strut bearing	X sue	\$	34.00
1 pc	Front o/s stabilizer link	X sue	\$	86.00
1 pc	Steering rack and pinion	X sue	\$	866.00
1 pc	Front o/s rim	/ Best	\$	246.00 ✓
1 pc	Wheel cover	/ cr	\$	116.00 ✓
1 pc	Front bumper o/s side retainer	/ cr	\$	16.00 ✓
1 pc	Front bumper o/s upper bracket	/ cr	\$	16.00 ✓
1 pc	Front bumper o/s support bracket	/ cr	\$	16.00 ✓
1 pc	Front o/s door	X rep.m	\$	791.00
			\$	6,484.00
			Less 10%	\$ 648.40
				\$ 5,835.60

S/NETT

1 pc	Front bumper clips	/ nec	\$	48.00 ✓
1 pc	Front o/s fender sticker	X m	\$	30.00
1 set	Front o/s fender inner shield clips	/ nec	\$	28.00 ✓
1 set	o/s rocker panel garnish clips	X m	\$	38.00
1 set	o/s door stickers	/ nec	\$	100.00 ✓
1 pc	Front o/s tyre (Tyre brand achilles)	/ partake 50% 100 Maxxis	\$	200.00 ✓

8-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6086 C

Sundry *rec*

To check front o/s wheel alignment

To dismantle / refit front o/s wheel undercarriage

Towing Fee

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s wheel housing

To putty and spray painting on front bumper, front o/s fender, front o/s wheel house, front o/s door, o/s rocker panel garnish

To apply rustproofing on the repaired and replaced panels.

\$	50.00 ²⁰
\$	60.00 ✓ 60
\$	250.00 100 X 2
\$	50.00
\$	900.00 ⁶⁰⁰
\$	1,200.00 ⁹⁰⁰
\$	150.00 50
\$	<u>8,939.60</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalua 10/05/19
✓ 8/5/19 1615h
4 Pz,
4/5
Allen Regan plh

15/5/19
what 4/5 \$2600/4 Pz
✓



Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	30 Jul 2014 / 10:14:34	Receipt No.:	AACCK001-AX239-140730-000015
Asset Type:	Vehicle	Transaction Amount:	\$65,817.00
Asset ID:	SHC6086C	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140730101434179668		

Vehicle No.:	SHC6086C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	30 Jul 2014
Original Registration Date:	30 Jul 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5464250
Engine No.:	D4FDDH307916
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,908.00
Minimum PARF Benefit:	\$7,444.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	30 Jul 2014 10:14:34
COE No.:	2014073001001367K
COE Expiry Date:	29 Jul 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$53,269.00
Lifespan Expiry Date:	29 Jul 2022
Owner ID Type:	Company

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	30 Jul 2014 / 10:14:34	Receipt No.:	AACCK001-AX239-140730-000015
Asset Type:	Vehicle	Transaction Amount:	\$65,817.00
Asset ID:	SHC6086C	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140730101434179668		

Vehicle No.:	SHC6086C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	30 Jul 2014
Original Registration Date:	30 Jul 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5464250
Engine No.:	D4FDDH307916
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,908.00
Minimum PARF Benefit:	\$7,444.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	30 Jul 2014 10:14:34
COE No.:	2014073001001367K
COE Expiry Date:	29 Jul 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$53,269.00
Lifespan Expiry Date:	29 Jul 2022
Owner ID Type:	Company

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5107202885-000567

Cover : Third Party

- | | |
|---|---------------------------|
| 1. Index mark and Registration Number of Vehicle | : SHC6086C |
| Chassis Number | : KNAGM414ME5464250 |
| 2. Name of Policyholder | : PREMIER TAXIS PTE. LTD. |
| 3. Effective Date of Insurance | : 01 Feb 2019 |
| 4. Expiry Date of Insurance | : 31 Jan 2020 |
| 5. Persons or Classes of Persons entitled to drive* | |
| (a) The Policyholder. | |
| (b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use* | |
| (a) Use as a Taxi. | |
| (b) Use for social domestic and pleasure purposes. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 01 Feb 2019 09:37 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

CASH SALE/WORK ORDER

No: AE 8658



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717
TEL: 6743 1987 (3 LINES) FAX: 6743 0013
Reg No: 200415052W

Date: 7/5/19

貨號

Messrs:

車號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time:

premier

SAC 6086 C

車型

Model No:

Kia

Rangoon Road

Chng;

omega

18:43:19:15:19:47

AMOUNT:

\$

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人
Authorised by:

M 5672

收貨人

Received by:

1 key for Pandiyan
S 94160401

Mei Kwan (LKKAUTO)

From: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Sent: Wednesday, 15 May, 2019 4:29 PM
To: Mei Kwan (LKKAUTO)
Cc: CS A Team; Admin A; Joy Irene (LKKAUTO)
Subject: RE: OUR REF: SNM19D202097/C02/6-SLM2216X - Direct Settlement - Accident Involving SLM2216X (OI : CTI - TBA) and SHC6086C (TP : LKK REF - CC3/CTI19008189/K1ja3) on 07/05/2019
Attachments: INSD SLM2216X GIA REPORT.PDF

Dear Mei Kwan,

Please find attached our insured's GIA report.

Thank you.

Ong Chin Kiat
Assistant Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6174 | F: (65) 6224 7174 / 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 15 May, 2019 1:16 PM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Elaine Cheong; Ong Chin Kiat; CS A Team; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving SLM2216X (OI : CTI - TBA) and SHC6086C (TP : LKK REF - CC3/CTI19008189/K1ja3) on 07/05/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/ Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 6086C at M/s Premier Automotive Services Pte Ltd – Changi on a WP basis and TP repairer purposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Towing

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD Ref : CC3/CTI19008189/K1ha3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-07-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 2216X	Veh. Inspected	SHC 6086C
Policy No.	DMPCSN3026891902	Coverage (\$)	0.00
Claim No.	SNM19D202097/C02/6	Excess (\$)	0.00
Assign From		Assign Date	08/05/2019

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5464250	Colour	SILVER
Odometer	400528	Steering	AFFECTED
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2019	Inspection Date	08/05/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6086C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT O/S HEAD LAMP	SERVICEABLE	1,028.00	-
1	FRONT BUMPER	CRACKED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT O/S FENDER	BUCKLED	384.00	384.00
1	FRONT O/S FENDER INNER SHIELD	TORN	120.00	120.00
1	O/S ROCKER PANEL GARNISH	TO REPAIR SEE LABOUR	286.00	-
1	FRONT O/S LOWER ARM	SERVICEABLE	439.00	-
1	FRONT O/S SHOCK ABSORBER	SERVICEABLE	330.00	-
1	FRONT O/S BALL JOINT	SERVICEABLE	59.00	-
1	FRONT O/S DRIVESHAFT	SERVICEABLE	971.00	-
1	FRONT INSULATOR STRUT	SERVICEABLE	105.00	-
1	FRONT STRUT BEARING	SERVICEABLE	34.00	-
1	FRONT O/S STABILIZER LINK	SERVICEABLE	86.00	-
1	STEERING RACK & PINION	SERVICEABLE	866.00	-
1	FRONT O/S RIM	BENT	246.00	246.00
1	WHEEL COVER	CRACKED	116.00	116.00
1	FRONT BUMPER O/S SIDE RETAINER	CRACKED	16.00	16.00
1	FRONT BUMPER O/S UPPER BRACKET	CRACKED	16.00	16.00
1	FRONT BUMPER O/S SUPPORT BRACKET	CRACKED	16.00	16.00
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	791.00	-
	LESS 10% DISCOUNT		-648.40	-148.90
			5,835.60	1,340.10
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET O/S ROCKER PANEL GARNISH CLIPS (SN)	NOT NECESSARY	38.00	-
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	FRONT O/S TYRE (TYRE BRAND MAXXIS)(50%)(SN)	PUNCTURE	200.00	100.00

Report Ref No. CC3/CTI19008189/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Reg. No: 199607198R GST Reg. No: 19-9607198R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRY (SN) LABOUR TO CHECK FRONT O/S WHEEL ALIGNMENT. TO DISMANTLE/REFIT FRONT O/S WHEEL UNDERCARRIAGE. TOWING FEE. TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE FRONT O/S WHEEL HOUSING.INCLUSIVE OF THE REPAIR OF O/S ROCKER PANEL GARNISH AND FRONT O/S DOOR. TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,FRONT O/S FENDER,FRONT O/S WHEEL HOUSE,FRONT O/S DOOR,O/S ROCKER PANEL GARNISH. TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NECESSARY	50.00	20.00
			494.00	296.00
		NOT NECESSARY	60.00	60.00
			250.00	-
			50.00	50.00
			900.00	600.00
			1,200.00	900.00
			150.00	50.00
			2,610.00	1,660.00
			8,939.60	3,296.10
GRAND TOTAL				
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00	

Report Ref No. CC3/CT19008189/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.