

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6086 C

1 pc	Front o/s head lamp	X sue	\$	1,028.00
1 pc	Front bumper	— cr	\$	531.00
1 pc	Front bumper emblem	— m	\$	44.00
1 pc	Front o/s fender	— break/chl	\$	384.00
1 pc	Front o/s fender inner shield	— br	\$	120.00
1 pc	o/s rocker panel garnish	X repn	\$	286.00
1 pc	Front o/s lower arm	X sue	\$	439.00
1 pc	Front o/s shock absorber	X sue	\$	330.00
1 pc	Front o/s ball joint	X sue	\$	59.00
1 pc	Front o/s driveshaft	X sue	\$	971.00
1 pc	Front insulator strut	X sue	\$	105.00
1 pc	Front strut bearing	X sue	\$	34.00
1 pc	Front o/s stabilizer link	X sue	\$	86.00
1 pc	Steering rack and pinion	X sue	\$	866.00
1 pc	Front o/s rim	— Bent	\$	246.00
1 pc	Wheel cover	— cr	\$	116.00
1 pc	Front bumper o/s side retainer	— cr	\$	16.00
1 pc	Front bumper o/s upper bracket	— cr	\$	16.00
1 pc	Front bumper o/s support bracket	— cr	\$	16.00
1 pc	Front o/s door	X repn	\$	791.00
			\$	6,484.00
		Less 10%	\$	648.40
			\$	5,835.60

S/NETT

1 pc	Front bumper clips	— nec	\$	48.00
1 pc	Front o/s fender sticker	X m	\$	30.00
1 set	Front o/s fender inner shield clips	X nec	\$	28.00
1 set	o/s rocker panel garnish clips	X m	\$	38.00
1 set	o/s door stickers	— nec	\$	100.00
1 pc	Front o/s tyre (Tyre brand achilles)	— putrid 50% Maxxis	\$	200.00

8-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6086 C

Sundry	\$ 50.00 ²⁰
To check front o/s wheel alignment	\$ 60.00 ✓ 60
To dismantle / refit front o/s wheel undercarriage	\$ 250.00 ¹⁰⁰⁰
Towing Fee	\$ 50.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s wheel housing	\$ 900.00 ⁶⁰⁰
To putty and spray painting on front bumper, front o/s fender, front o/s wheel house, front o/s door, o/s rocker panel garnish	\$ 1,200.00 ⁹⁰⁰
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 ⁵⁰
	<u>\$ 8,939.60</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 10/05/19
8/5/19 1615h
4/5
At the Repair place

15/5/19
what 4/5 \$2600/4/5
H

