



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19008197/Upa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-09-2020



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBP 312S	Veh. Inspected	FBG 3380Y
Policy No.	AN3171870	Coverage (\$)	0.00
Claim No.	S9M01MUA	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	09/05/2019

2. Vehicle Particulars & Condition

Make & Model	SYM MAXSYM	c.c	400
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	RFGLXA902BS000401	Colour	BLACK
Odometer	10082	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 R15	BRIDGESTONE	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R15	BRIDGESTONE	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/04/2019	Inspection Date	09/05/2019
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------