



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

MOTOR CLAIMS DEPT

VEHICLE NO. : FBG3380Y

MAKE/MODEL : SYM / MAXSYM 400I CVT

NO. : 34089

DATE : 07/05/2019

CLAIM NO. : 11329

POLICY NO. :

FROM : RAYMOND

*not filled
near
n/s
4 day
9/5/19
Take 2nd Atterday*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX FR-INNER P/N: 55078	REPLACE	1.00	\$66.00	66.00 ✓
2	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$202.00	202.00 ✓
3	COVER GARNISH FRONT RH P/N: 55474	REPLACE	1.00	\$9.00	9.00 ✓
4	COVER L-BODY ASSY	REPLACE	1.00	\$198.00	198.00 ✗
5	COVER OUTER ASSY .BK-001U P/N: 55354	REPLACE	1.00	\$119.00	119.00 ✓
6	COVER REAR CENTER	REPLACE	1.00	\$77.00	77.00 ?
7	COVER TAIL REAR RH P/N: 56665	REPLACE	1.00	\$9.00	9.00 ?
8	DAMPER BOX INNER LID P/N: 56666	REPLACE	1.00	\$12.00	12.00 ?
9	DAMPER COVER TAIL RH P/N: 56673	REPLACE	1.00	\$5.00	5.00 ✓
10	FRONT UNDER SPOILER P/N: 57449	REPLACE	1.00	\$262.00	262.00 ✓
11	GUARD HANDLE (ACERBIS) X-TARMAC P/N: 62535	REPLACE	1.00	\$382.00	382.00 ✓
12	R SIDE COVER ASSY WH-300P P/N: 61511	REPLACE	1.00	\$135.00	135.00 ✓
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		12.00	\$35.00	420.00 300



CERT NO.: 2002-1-0383
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER BRAKE RH P/N: 55472	REPLACE	1.00	\$80.00	502 80.00
15	L-FR COVER GARNISH BK P/N: 55050	REPLACE	1.00	\$17.00	9 17.00
16	LID INNER BOX	REPLACE	1.00	\$54.00	? 54.00
17	LIGHT L-TAIL ASSY P/N: 55105	REPLACE	1.00	\$273.00	cm 273.00
18	METER PANEL BK-001U P/N: 55090	REPLACE	1.00	\$32.00	11 32.00 X
19	MIRROR RH P/N: 55470	REPLACE	1.00	\$140.00	502 140.00
20	PANEL RH- FLOOR P/N: 55065	REPLACE	1.00	\$42.00	cm 42.00
21	PROTECTOR EXHAUST P/N: 55471	REPLACE	1.00	\$117.00	cm 117.00
22	R SIDE COVER ASSY BK-231P P/N: 57440	REPLACE	1.00	\$109.00	2 109.00 X
23	RR FENDER BK 001U P/N: 55057	REPLACE	1.00	\$48.00	cm 48.00
24	SEAT HANDLE LH	REPLACE	1.00	\$93.00	2 93.00 X
25	SEAT HANDLE RH	REPLACE	1.00	\$93.00	2 93.00 X
26	SPRAY PAINT LH LOWER SIDE COVER		1.00	\$85.00	60 85.00
27	SPRAY PAINT LH REAR HANDLE		1.00	\$30.00	30.00
28	SPRAY PAINT LH SIDE TAIL COVER		1.00	\$120.00	60 120.00
29	SPRAY PAINT RH LOWER SIDE COVER		1.00	\$85.00	60 85.00
30	SPRAY PAINT RH REAR HANDLE		1.00	\$30.00	30.00
31	WIND SCREEN ASSY P/N: 57424	REPLACE	1.00	\$230.00	cm 230.00

SUB TOTAL

\$3,574.00

GST @ 7 %

\$250.18

GRAND TOTAL

\$3,824.18

50% deposit required before ordering of parts.

Validity: 30 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey & on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CERT NO.: 2002-1-0383
ISO 9001 : 2015

S/N DescriptionActionQtyUnit PriceAmount

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

