



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

MOTOR CLAIMS DEPT

VEHICLE NO. : FBG3380Y
MAKE/MODEL : SYM / MAXSYM 400I CVT

NO. : 34089

DATE : 07/05/2019

CLAIM NO. : 11329

POLICY NO. :

FROM : RAYMOND

*not Afford
near
n/s #2300/
4 day.
9/5/19
Take 2nd Atter up 2 -*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX FR-INNER P/N: 55078	REPLACE	1.00	\$66.00	66.00
2	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$202.00	202.00
3	COVER GARNISH FRONT RH P/N: 55474	REPLACE	1.00	\$9.00	9.00
4	COVER L-BODY ASSY	REPLACE	1.00	\$198.00	198.00
5	COVER OUTER ASSY .BK-001U P/N: 55354	REPLACE	1.00	\$119.00	119.00
6	COVER REAR CENTER	REPLACE	1.00	\$77.00	77.00
7	COVER TAIL REAR RH P/N: 56665	REPLACE	1.00	\$9.00	9.00
8	DAMPER BOX INNER LID P/N: 56666	REPLACE	1.00	\$12.00	12.00
9	DAMPER COVER TAIL RH P/N: 56673	REPLACE	1.00	\$5.00	5.00
10	FRONT UNDER SPOILER P/N: 57449	REPLACE	1.00	\$262.00	262.00
11	GUARD HANDLE (ACERBIS) X-TARMAC P/N: 62535	REPLACE	1.00	\$382.00	382.00
12	RIGHT SIDE COVER ASSY WH-300P P/N: 61511	REPLACE	1.00	\$135.00	135.00
13	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		12.00	\$35.00	420.00



S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER BRAKE RH P/N: 55472	REPLACE	1.00	\$80.00	5cr 80.00
15	L-FR COVER GARNISH BK P/N: 55050	REPLACE	1.00	\$17.00	cr 17.00
16	LID INNER BOX	REPLACE	1.00	\$54.00	cr 54.00
17	LIGHT L-TAIL ASSY P/N: 55105	REPLACE	1.00	\$273.00	cr 273.00
18	METER PANEL BK-001U P/N: 55090	REPLACE	1.00	\$32.00	cr 32.00
19	MIRROR RH P/N: 55470	REPLACE	1.00	\$140.00	5cr 140.00
20	PANEL RH- FLOOR P/N: 55065	REPLACE	1.00	\$42.00	cr 42.00
21	PROTECTOR EXHAUST P/N: 55471	REPLACE	1.00	\$117.00	cr 117.00
22	R SIDE COVER ASSY BK-231P P/N: 57440	REPLACE	1.00	\$109.00	cr 109.00
23	RR FENDER BK 001U P/N: 55057	REPLACE	1.00	\$48.00	cr 48.00
24	SEAT HANDLE LH	REPLACE	1.00	\$93.00	cr 93.00 X
25	SEAT HANDLE RH	REPLACE	1.00	\$93.00	cr 93.00 X
26	SPRAY PAINT LH LOWER SIDE COVER	✓	1.00	\$85.00	60 85.00
27	SPRAY PAINT LH REAR HANDLE	✓	1.00	\$30.00	30.00
28	SPRAY PAINT LH SIDE TAIL COVER	✓	1.00	\$120.00	80 120.00
29	SPRAY PAINT RH LOWER SIDE COVER	✓	1.00	\$85.00	60 85.00
30	SPRAY PAINT RH REAR HANDLE	✓	1.00	\$30.00	30.00
31	WIND SCREEN ASSY P/N: 57424	REPLACE	1.00	\$230.00	cr 230.00

SUB TOTAL

\$3,574.00

GST @ 7 %

\$250.18

GRAND TOTAL

\$3,824.18

50% deposit required before ordering of parts.

Validity: 30 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CERT NO.: 2002-1-0383
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	For & on Behalf of				
	BAN HOCK HIN CO PTE LTD			Acknowledge & Accepted By	



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

