

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0601/2019/DY/KN
Date : 9-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : SJX 8935 E

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Vjayvarmman s/o Gnasnasekaran
Address : Blk 337 Choa Chu Kang Ave 4
#01-14
Singapore 689872
Telephone : (HP)+65 90028510
Type of Claim : Third Party Claim
Policy No. : 2019-V0106934-VDP-E001
Vehicle No : **SKH 8554 T**
Model Code : A6 2.0 TFSI S TRONIC
Model / Year : Jan-13
Engine No : CDN 301692
Chassis No : WAUZZZ4G8DN059683
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-May-19
Place of Accident : BKE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKH 8554 T

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid and rear lid kick sensor.	S/N \$ 360.00 ✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail light.	\$ 280.00 X
3	To dismantle and renew rear bumper and rear lid. To inspect end panelling for further damages. Re-organise rear crash management components. Reinstall all parts removed	\$ 2,400.00 800
4	To respray rear bumper and rear lid	S/N \$ 2,200.00 1600 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>5,432.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 8554 T

S/N	Parts Description		Damaged Parts & Prices S/Nett
1	REAR BUMPER <i>red</i>	\$	2,343.00 ✓
2	REAR BUMPER STICKY PAD <i>3 pc</i>	4 \$	21.00 ✗
3	REAR BUMPER FIXING PARTS	\$	249.00 ✗
4	REAR BUMPER SPOILER <i>lt</i>	\$	316.00 ✓
5	REAR BUMPER SECURING STRIP <i>pc</i>	\$	157.00 ✗
6	REAR BUMPER CARRIER <i>pc</i>	\$	887.00 ✗
7	REAR BUMPER SEAL <i>pc</i>	2 \$	26.00 ✗
8	REAR BUMPER GUIDE SECTION <i>pc</i>	2 \$	60.00 ✗
9	GUIDE SECTION CONNECTING PIECE	2 \$	22.00 ✗
10	GUIDE SECTION PROFILE	2 \$	106.00 ✗
11	CENTER GUIDE SECTION PROFILE	\$	96.00 ✗
12	LOWER GUIDE SECTION PROFILE	\$	48.00 ✗
13	REAR BUMPER CARRIER COVER - RH	\$	105.00 ✗
14	REAR SENSOR <i>pc</i>	2 \$	462.00 ✗
15	BOOT LID <i>pc</i>	\$	2,600.00 ✗
16	BOOT LID ATTACHMENT PARTS	\$	74.00 ✗
17	BOOT LID HINGE - LH/RH	2 \$	416.00 ✗
18	BOOT LID LOCK ACTUATOR	\$	167.00 ✗
19	GASKET FLAP	\$	190.00 ✗
20	BOOT LID LOCK	\$	178.00 ✗
SUB SPARE PARTS CHARGES		:	\$ 8,523.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKH 8554 T

S/N	Parts Description		Damaged Parts & Prices S/Nett
21	PROTECTIVE CAP	2	\$ 13.00 X
22	AUDI EMBLEM - SEDAN	2	\$ 113.00 ✓
23	INSCRIPTION CHROME - 2.0 T	2	\$ 87.00 ✓
24	INSCRIPTION CHROME - A6	2	\$ 316.00 ✓
25	PACKING ADHESIVE	2	\$ 30.00 ✓
26	INNER LED TAIL LIGHT - LH	2	\$ 1,149.00 X
27	INNER LED TAIL LIGHT - RH	2	\$ 1,149.00 +
28	INNER TRIM TAIL LIGHT - LH	2	\$ 27.00 X
29	INNER TRIM TAIL LIGHT - RH	2	\$ 27.00 +
30	LED LICENCE PLATE LIGHT	2	\$ 105.00 X
31	CONTROL UNIT OPENING BOOT LID	2	\$ 387.00 +
32	REAR TRIM CROSS PANEL	2	\$ 122.00 +
33	REAR NO PLATE	1	\$ 40.00 ✓
34	SUNDRIES	?	\$ 700.00 ?
TOTAL SPARE PARTS CHARGES			\$ 12,779.00
TOTAL LABOUR CHARGES			\$ 5,432.00
GRAND TOTAL			\$ 18,211.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Lj
Surveyed Date : 09/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 0 days.

Please Note : This estimate is based on visual inspection of the affected
Should we require further labour charges and spare parts
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant