

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KMH TC61DVDU113381

MOHAMAD SOFIAN BIN MOHAMAD YONI

Date :16.05.2019

BLK 274D PUNGGOL PLACE

TP FWD

Vehicle No :SKG 8714D

#10-848

Vivian

Make/Model :HYUNDAI VELOSTER

S 824274

Accident date :08.05.2019

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear bumper <i>behind</i>	1	\$ 852.30 <i>678</i>
2	Rear bumper reinforcement <i>cauled</i>	1	\$ 952.90 <i>612</i>
3	Rear bumper side holder@42.40 <i>new</i>	2	\$ 84.80
4	Rear bumper lower lip <i>behind</i>	1	\$ 334.40
5	Rear bumper side reflector@63.80 <i>new</i>	2	\$ 116.60 <i>+</i>
6	Rear bumper reverse sensor <i>new</i>	1	\$ 418.00 <i>282</i>
7	Rear bumper clips <i>new</i>	1	\$ 55.00 <i>30</i>
8	Rear exhaust pipe chrome <i>lit</i>	1	\$ 192.50
9	Rear end panel <i>Rep 5</i>	1	\$ 549.50 <i>+</i>
10	Rear end panel inner top garnish <i>new</i>	1	\$ 80.30 <i>+</i>
11	Rear number plate lamp@41.80 <i>new</i>	2	\$ 83.60 <i>x</i>
			\$ 3719.90
Less 20% Disc			\$ 744.00
Total			\$ 2975.90

Special Nett Items

1	Rear number plate <i>cauled</i>	1	\$ 55.00 <i>30</i>
2	Rear number plate holder <i>behind</i>	1	\$ 55.00 <i>30</i>
Total			\$ 110.00

Labour Cost

1	To supply rear end panel inner sealant	\$ 200.00 <i>+</i>
2	Remove & reinstall rear exhaust pipe	\$ 150.00 <i>+</i>
3	Remove & reinstall reverse sensor	\$ 150.00 <i>50</i>
4	Remove ,replace & repair consistent to the accident	\$ 1200.00 <i>300</i>
5	Respray painting	\$ 900.00 <i>400</i>
6	Tuff kote	\$ 100.00 <i>x</i>
Total		\$ 2700.00

Grand Total \$ 5785.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2352.96
1/5. 2K
08 Days